

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 6 October 2020 11:19 AM
To: 'Carrine Leong'
Cc: 'Chang Chee Sing'; SUR; 'Boo seng yak'; jiayee.yap@premiumauto.com.sg
Subject: RE: FINAL REVISION - SME2867Y - OD AIG - SURVEYED 12 AUG 2020 RE-SURVEYED 17 AUG

Dear Carrine,

WITHOUT PREJUDICE

Confirm final fig \$23,393.36 before excess \$1,600.00 & GST and 9 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>
Sent: Monday, 5 October 2020 1:39 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: 'Chang Chee Sing' <claims@premiumauto.com.sg>; 'Boo seng yak' <boojohnny@gmail.com>; jiayee.yap@premiumauto.com.sg
Subject: RE: FINAL REVISION - SME2867Y - OD AIG - SURVEYED 12 AUG 2020 RE-SURVEYED 17 AUG

Hi Rasul,

For the FRONT BUMPER BRACKET – LH only. 1pc is \$225 please find attachment file for your reference, sorry for typing error on the estimate.

Please find the attachment diagnostic report for the power module and control unit for the headlight for your attention as per your request.

Thanks & Best Regard
Carrine Leong
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183
e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Rasul (LKKAuto) [<mailto:Rasul@lkkauto.com>]
Sent: Monday, 5 October, 2020 10:12 AM
To: Carrine Leong <carrine.leong@premiumauto.com.sg>
Subject: RE: FINAL REVISION - SME2867Y - OD AIG - SURVEYED 12 AUG 2020 RE-SURVEYED 17 AUG

Hi Carrine,

FRONT BUMPER BRACKET – LH / RH to be given 1pc only. Kindly check.
Kindly provide the diagnostic report for the power module and control unit for the headlight

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Carrine Leong [<mailto:carrine.leong@premiumauto.com.sg>]
Sent: Friday, 2 October, 2020 6:16 PM
To: Rasul (LKKAuto); SUR
Cc: 'Boo seng yak'; jiayee.yap@premiumauto.com.sg; 'Chang Chee Sing'
Subject: FINAL REVISION - SME2867Y - OD AIG - SURVEYED 12 AUG 2020 RE-SURVEYED 17 AUG

Hi Rasul ,

Revised estimate and photographs is attached.

Please confirm repair cost of \$23,393.36 @ 9 days exclude 1 Sun.

Your early closure is well appreciated.

Thanks & Best Regard
Carrine Leong
Claims Administrator


Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 **d.** +65 6768 9925 **f.** +65 6841 1183

e. carrine.leong@premiumauto.com.sg **w.** www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 **p.** +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you