

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 44820

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0553/2020/NS
Date : 11-Aug-20

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Rasul,
9days ok - 02/10/2020 - Carrine

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Dumir Neeraj
Address : 150 Prince Charles Crescent
#14-04
Singapore 159012
Telephone : HP + 65 91720001
Type of Claim : Own Damage Claims
Policy No. : 1800114782
Vehicle No : **SME 2867 Y**
Model Code : Audi A4 Sedan 2.0 TFSI 8W
Model / Year : Sep-18
Engine No : CVK 069008
Chassis No : WAUZZZF49JA232987
Mileage : 9760km
Date In : 11-Aug-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 8-Aug-20
Place of Accident : Holland Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SME 2867 Y

<u>S/N</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's commendations</u>
1	To remove and transfer/reinstall front bumper wire harness for front parking aid system.	S/N \$	280.00	\$ 280.00
2	To remove and transfer lhs headlight control unit and power module.	S/N \$	350.00	\$ 250.00
3	To dismantle lhs front door panel trim. To remove and reinstall lhs wing mirror assy.	S/N \$	350.00	\$ 350.00
4	To remove and renew aircon condenser, charged air coolers and radiator. Check electrical fans and control unit. Pressurise cooling system. To carv out	S/N \$	1,200.00	\$ 1,200.00
5	To dismantle and renew front bumper, lhs front fender, bonnet and lhs headlight. To renew front lock carrier and align to position. Re-organise crash manadement components. Reinstall all parts	\$	4,900.00	\$ 2,750.00
6	To respray front bumper, bonnet, lhs front fender, hinges and lhs front door.	\$	4,200.00	\$ 2,200.00
7	To carry out pre and post diagnostic check.	S/N \$	384.00	\$ 384.00
SUB TOTAL LABOUR CHARGES			\$ 11,664.00	\$ 7,414.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2867 Y

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 2,171.00	\$ 1,736.80
2	FRONT BUMPER FIXING PARTS	\$ 282.00	
3	FRONT BUMPER SECURING STRIP	2 \$ 70.00	
4	FRONT BUMPER GRILLE - CENTRE	\$ 194.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 208.00	
6	FRONT BUMPER AIR GUIDE - LH	\$ 62.00	
7	RADIATOR GRILLE	\$ 1,317.00	\$ 1,053.60
8	FRONT BUMPER AIR GUIDE GRILLE - LH	\$ 134.00	
9	FRONT BUMPER CARRIER	\$ 795.00	\$ 635.60
10	FRONT BUMPER FOAM FILLER PIECE	\$ 123.00	\$ 98.40
11	FRONT BUMPER FOAM FILLER PIECE COVER	\$ 126.00	
12	FRONT BUMPER GUIDE SECTION - LH	\$ 36.00	\$ 28.48
13	FRONT BUMPER BRACKET - LH / RH	\$ 225.00	\$ 180.00
14	CAUTION SIGN STICKER	NEC \$ 14.00	\$ 10.80
15	LOCK CARRIER BRACKET	\$ 136.00	\$ 108.40
16	FRONT BUMPER SUPPORT - LH / RH	2 \$ 56.00	\$ 44.48
17	FRONT PARKING AID SENSOR - INNER / OUTER	2 TBC	\$ 193.20
18	FRONT BUMPER WIRING SET	\$ 505.00	
19	HORN - LH HIGH TONE	\$ 124.00	
20	SPRING SHACKLE - LH	\$ 29.00	
SUB TOTAL SPARE PARTS CHARGES		: \$ 6,607.00	\$ 4,089.76

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Rean No. SME 2867 Y

S/N	Parts Description		Damage Parts & Prices	
			S/Nett	Remarks
		<i>c/f</i>		\$ 4,089.76
21	FRONT FENDER - LH / RH		\$ 758.00	\$ 606.00
22	FRONT FENDER ATTACHMENT PARTS		\$ 200.00	
23	FRONT FENDER CLOSING ELEMENT - LH		\$ 49.00	\$ 39.20
24	FRONT FENDER BRACKET - LH		\$ 35.00	\$ 27.60
25	DEFORMATION ELEMENT BRACKET - LH		\$ 49.00	
26	FRONT FENDER BRACKET		\$ 31.00	
27	FRONT FENDER BRACE - LH		\$ 117.00	\$ 93.60
28	TOP FENDER LEDGE COVER - LH UPPER		\$ 31.00	\$ 24.40
29	TOP FENDER LEDGE COVER - LH LOWER		\$ 23.00	\$ 17.68
30	WHEEL HOUSING LINER - LH		\$ 237.00	
31	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 90.00	
32	WHEEL SPOILER		\$ 73.00	
33	WHEEL SPOILER TRIM - LH		\$ 35.00	
34	STONE CHIP GUARD - LH		\$ 50.00	\$ 39.92
35	BONNET		\$ 2,763.00	\$ 2,210.40
36	BONNET ATTACHMENT PARTS		\$ 121.00	
37	BONNET LID HINGE - LH / RH	2	\$ 602.00	
38	BONNET IMPACT PROTECTION - CENTRE		\$ 27.00	\$ 21.52
39	BONNET IMPACT PROTECTION - RH		\$ 27.00	\$ 21.52
40	BONNET IMPACT PROTECTIN - LH		\$ 28.00	\$ 21.84
SUB TOTAL SPARE PARTS CHARGES			\$ 5,346.00	\$ 7,213.44

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2867 Y

S/N	Parts Description	c/f	<u>Damage Parts & Prices</u>		Remarks
			S/Nett		
					\$ 7,213.44
41	BONNET STRIKER - LH / RH	2	\$	100.00	
42	BONNET LID LOCK	2	\$	423.00	\$ 169.20
43	BONNET BOWDEN CABLE - CENTRE		\$	57.00	
44	BONNET BOWDEN CABLE		\$	57.00	
45	BONNET RELEASE LEVER		\$	13.00	
46	BONNET SOUND ABSORBER		\$	339.00	
47	LED HEADLIGHT - LH		\$	7,693.00	\$ 6,154.40
48	MAIL LIGHT ELECTRONICS POWER MODULE		\$	739.00	\$ 591.20
49	LIGHT CONTROL SYSTEM CONTROL UNIT		\$	742.00	\$ 593.60
50	HEADLIGHT HOSE - LH / RH		\$	36.00	
51	HEADLAMP REPAIR KIT - LH		\$	130.00	
52	HEADLIGHT COMPENSATING PIECE		\$	40.00	
53	HEADLIGHT COMPENSATING PIECE		\$	40.00	
54	HEADLIGHT COMPENSATING PIECE		\$	40.00	
55	LIFT CYLINDER - LH		\$	208.00	\$ 166.00
56	LIFT CYLINDER CORRUGATED PIPE		\$	92.00	
57	LOCK CARRIER		\$	1,004.00	\$ 803.20
58	LOCK CARRIER SUPPORT		\$	38.00	
59	AIRCON CONDENSER		\$	615.00	
60	REFRIGERANT LINE		\$	165.00	
SUB TOTAL SPARE PARTS CHARGES :			\$	12,571.00	\$ 15,691.04

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2867 Y

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/Nett	Remarks
			\$ 15,691.04
61	REFRIGERANT LINE	\$ 336.00	
62	TEMPERATURE SENSOR BRACKET	\$ 18.00	\$ 14.40
63	PRESSURE PIPE	\$ 422.00	
64	RADIATOR	\$ 837.00	
65	READY MIX COOLANT	\$ 91.00	\$ 72.32
66	RADIATOR FAN RING	\$ 242.00	
67	RADIAOTR FAN	\$ 1,896.00	
68	RADIATOR AIR GUIDE - LH	\$ 28.00	
69	RADIATOR AIR GUIDE - LH	\$ 12.00	\$ 9.36
70	RADIATOR AIR GUIDE - UPPER	\$ 16.00	
71	FRONT NO PLATE	S/N \$ 60.00	\$ 60.00
72	SUNDRIES	\$ 300.00	\$ 132.24
TOTAL SPARE PARTS CHARGES		\$ 28,782.00	\$ 15,979.36
TOTAL LABOUR CHARGES		\$ 11,664.00	\$ 7,414.00
GRAND TOTAL		\$ 40,446.00	\$ 23,393.36