

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 44820

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0553/2020/NS
Date : 11-Aug-20

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Dumir Neeraj
Address : 150 Prince Charles Crescent
#14-04
Singapore 159012
Telephone : HP +65 91720001
Type of Claim : Own Damage Claims
Policy No. : 1800114782
Vehicle No : **SME 2867 Y**
Model Code : Audi A4 Sedan 2.0 TFSI 8W
Model / Year : Sep-18
Engine No : CVK 069008
Chassis No : WAUZZZF49JA232987
Mileage : 9760km
Date In : 11-Aug-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 8-Aug-20
Place of Accident : Holland Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2867 Y

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>turn</i>	\$ 2,171.00	1736.80
2	FRONT BUMPER FIXING PARTS ? <i>XSVL</i>	\$ 282.00	
3	FRONT BUMPER SECURING STRIP ? <i>XSVL</i>	2 \$ 70.00	
4	FRONT BUMPER GRILLE - CENTRE <i>XSVL</i>	\$ 194.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE ? <i>XSVL</i>	\$ 208.00	
6	FRONT BUMPER AIR GUIDE - LH <i>XSVL</i>	\$ 62.00	
7	RADIATOR GRILLE <i>cm</i>	\$ 1,317.00	1053.60
8	FRONT BUMPER AIR GUIDE GRILLE - LH <i>XSVL</i>	\$ 134.00	
9	FRONT BUMPER CARRIER <i>bt</i>	\$ 795.00	635.60
10	FRONT BUMPER FOAM FILLER PIECE <i>cm</i>	\$ 123.00	98.40
11	FRONT BUMPER FOAM FILLER PIECE COVER ? <i>XSVL</i>	\$ 126.00	
12	FRONT BUMPER GUIDE SECTION - LH ? <i>cm</i>	\$ 36.00	28.48
13	FRONT BUMPER BRACKET - LH / RH <i>LH - ? / RH - X @ 225</i>	\$ (1pc) 225.00	180.00
14	CAUTION SIGN STICKER <i>nee</i>	NEC \$ 14.00	10.80
15	LOCK CARRIER BRACKET ? <i>cm</i>	\$ 136.00	108.40
16	FRONT BUMPER SUPPORT - LH / RH <i>LH - ? / RH - X</i>	2 \$ 56.00	44.48
17	FRONT PARKING AID SENSOR - INNER / OUTER <i>nee</i>	<i>X</i> 1 TBC	193.20
18	FRONT BUMPER WIRING SET ? <i>Xnn</i>	\$ 505.00	
19	HORN - LH HIGH TONE ? <i>Xnn</i>	\$ 124.00	
20	SPRING SHACKLE - LH ? <i>Xnn</i>	\$ 29.00	

SUB TOTAL SPARE PARTS CHARGES

: \$ 6,607.00

AIR - CON STICKER - nee

FRONT bumper cover upper + cent

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SME 2867 Y

S/N	Nature of Jobs		Estimated Charges	Survevor's Recommendation
1	To remove and transfer/reinstall front bumper wire harness for front parking aid system.	S/N \$	280.00	/ /
2	To remove and transfer lhs headliht control unit and power module.	S/N \$	350.00 250	/
3	To dismantle lhs front door panel trim. To remove and reinstall lhs wing mirror assy.	S/N \$	350.00	/ /
4	To remove and renew aircon condenser, charged air coolers and radiator. Check electrical fans and control unit. Pressurise cooling system. To cary out vacuum and regas.	S/N \$	1,200.00	/ /
5	To dismantle and renew front bumper, lhs front fender, bonnet and lhs headlight. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$	4,900.00 2750	/
6	To respray front bumper, bonnet, lhs front fender, hinges and lhs front door.	\$	4,200.00 2200	/
7	To carry out pre and post diagnostic check.	S/N \$	384.00	/ /
SUB TOTAL LABOUR CHARGES			: \$ 11,664.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Rean No. SME 2867 Y

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	FRONT FENDER - LH / RH LH-bt / RH-X sm nn	\$ 758.00	606.00
22	FRONT FENDER ATTACHMENT PARTS ? X sm	\$ 200.00	
23	FRONT FENDER CLOSING ELEMENT - LH ? sm	\$ 49.00	39.20
24	FRONT FENDER BRACKET - LH ? bt	\$ 35.00	27.60
25	DEFORMATION ELEMENT BRACKET - LH ? X sm	\$ 49.00	
26	FRONT FENDER BRACKET ? X sm	\$ 31.00	
27	FRONT FENDER BRACE - LH ? bt	\$ 117.00	93.60
28	TOP FENDER LEDGE COVER - LH UPPER nee	\$ 31.00	24.40
29	TOP FENDER LEDGE COVER - LH LOWER nee	\$ 23.00	17.68
30	WHEEL HOUSING LINER - LH X sm	\$ 237.00	
31	WHEEL HOUSING LINER ATTACHMENT PARTS X sm	\$ 90.00	
32	WHEEL SPOILER X sm	\$ 73.00	
33	WHEEL SPOILER TRIM - LH X sm	\$ 35.00	
34	STONE CHIP GUARD - LH nee	\$ 50.00	39.92
35	BONNET bt	\$ 2,763.00	2210.40
36	BONNET ATTACHMENT PARTS ? X sm	\$ 121.00	
37	BONNET LID HINGE - LH / RH ? X sm	2 \$ 602.00	
38	BONNET IMPACT PROTECTION - CENTRE nee	\$ 27.00	21.52
39	BONNET IMPACT PROTECTION - RH nee	\$ 27.00	21.52
40	BONNET IMPACT PROTECTIN - LH nee	\$ 28.00	21.84
SUB TOTAL SPARE PARTS CHARGES		: \$ 5,346.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2867 Y

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
41	BONNET STRIKER - LH / RH - LH- ^{XSV} ? / RH-X ^{SVL}	21\$	100.00
42	BONNET LID LOCK - LH- ^{bt} ? / RH-XSV	21\$	423.00 169.20
43	BONNET BOWDEN CABLE - CENTRE XSVL	\$	57.00
44	BONNET BOWDEN CABLE XSVL	\$	57.00
45	BONNET RELEASE LEVER XSVL	\$	13.00
46	BONNET SOUND ABSORBER XSVL	\$	339.00
47	LED HEADLIGHT - LH bro ✓	\$	7,693.00 6154.40
48	MAIL LIGHT ELECTRONICS POWER MODULE ? } Diagnose report	\$	739.00 591.20
49	LIGHT CONTROL SYSTEM CONTROL UNIT ?	\$	742.00 593.60
50	HEADLIGHT HOSE (LH) / RH ? XSVL	\$	36.00
51	HEADLAMP REPAIR KIT - LH ? XSVL	\$	130.00
52	HEADLIGHT COMPENSATING PIECE ? XSVL	\$	40.00
53	HEADLIGHT COMPENSATING PIECE ? XSVL	\$	40.00
54	HEADLIGHT COMPENSATING PIECE ? XSVL	\$	40.00
55	LIFT CYLINDER - LH ? com ✓	\$	208.00 166.00
56	LIFT CYLINDER CORRUGATED PIPE ? XSVL	\$	92.00
57	LOCK CARRIER bt ✓	\$	1,004.00 803.20
58	LOCK CARRIER SUPPORT ? XSVL	\$	38.00
59	AIRCON CONDENSER ? XSVL	\$	615.00
60	REFRIGERANT LINE XSVL	\$	165.00

SUB TOTAL SPARE PARTS CHARGES : \$ 12,571.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2867 Y

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
61	REFRIGERANT LINE <i>X su</i>	\$	336.00
62	TEMPERATURE SENSOR BRACKET <i>? ne</i>	\$	18.00 <i>14.40</i>
63	PRESSURE PIPE <i>? su</i>	\$	422.00
64	RADIATOR <i>X an</i>	\$	837.00
65	READY MIX COOLANT <i>? ne</i>	\$	91.00 <i>72.32</i>
66	RADIATOR FAN RING <i>X an</i>	\$	242.00
67	RADIAOTR FAN <i>X an</i>	\$	1,896.00
68	RADIATOR AIR GUIDE - LH <i>? su</i>	\$	28.00
69	RADIATOR AIR GUIDE - LH <i>? ne</i>	\$	12.00 <i>9.36</i>
70	RADIATOR AIR GUIDE - UPPER <i>? su</i>	\$	16.00
71	FRONT NO PLATE <i>ne</i>	S/N \$	60.00 <i>/</i>
72	SUNDRIES <i>? ne</i>	\$	300.00 <i>132.24</i>

TOTAL SPARE PARTS CHARGES : \$ 28,782.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

: RASUL - HP 90010068

Surveyed Date

: 12/08/2020 @ 1430

Authorised Date

:

Excess Cost

:

9 days

Liability

:

EXCESS: THA

Remarks

:

REPAIR

Resurvey before paint

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant