

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/ CT12 0008241/44f3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJS8122 K

at Workshop m/s Tan Kim Guan

of _____

Insured: SLB6460M

Policy No. DMPCSNW00029612004

Claims No. SNM20D202791C02

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: B69

IDAS Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: 2 Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS LTA 33886

Date: _____ Person Contacted: Rep 7h.

Vehicle: IN / OUT

Veh No: SJS8122K Yr Regn: 11/19

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make: Kia Cerato LX c.c. 1591

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 30370 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAF1416MK5051815

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or KumHo

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 8/8/20 D.O.I. 12/8/20

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Ree

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21/8/20 1/5 @ 1800 confirmed with MR Tan (Red \$3502.70, 66%)

Date/Time, File Pass to?

☐ : Preli. Report

1) 21/08 Typist

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____) S + RS \$I

☐ : Interview (\$ _____) Photos

☐ : Tech. Invs (\$ _____) Others

☐ : Weekend (\$ _____)

Report Format : MER-TP

Lump Sum ~~H.B.H.~~ (\$) 1800)

Survey Fee:

Transportation:

TOTAL



陳林摩哆私人有限公司

TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

CTP Insured's Veh No : SLB6460M

Date of Accident : 08 August 2020

not Authorized

12/8/20

Take photo before painting
3 days.

Date : 12 August 2020

Messrs VFM Pte Ltd

Estimate To Repair SJS8122K - KIA CERATO 1.6(A) LX

Chassis No : KNAF1416MK5051815

L/S \$1800

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	rear bumper	\$ 652.00
02	12/8/20	rear bumper clip	\$ 60.00
03	1 pc	rear bumper lower pad with mash	\$ 218.00
04	1 pc	n/s rear bumper fog lamp	\$ 163.00
05	1 pc	n/s rear bumper fog lamp trim	\$ 17.00
06	1 pc	rear bumper beam	\$ 287.00
07	1 pc	rear end panel	\$ 292.00
08	1 pc	bootlid	\$ 1,298.00
09	1 pc	bootlid weatherstrip	\$ 90.00
10	1 pc	bootlid lock	\$ 101.00
11	1 pc	bootlid cerato emblem	\$ 25.00
Less 10 %			\$ 3,203.00
			\$ 320.30
			\$ 2,882.70
<u>SPECIAL NETT ITEMS</u>			
12	1 set	rear bumper parking sensor	\$ 400.00
13	1 pc	bootlid C&C emblem	\$ 25.00
14	1 pc	bootlid cerato club sticker	\$ 25.00
			\$ 450.00
<u>LABOUR & MISC. CHARGES</u>			
01		To rust-proofing of the affected areas.	\$ 250.00
02		To reinstall of rear bumper parking sensor.	\$ 80.00
03		To transfer of bootlid fittings, attachments and perform water seepage test.	\$ 80.00
04		To check electrical lighting concerned.	\$ 60.00
05		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 750.00
06		Putty and spray painting of the affected portion.	\$ 750.00
			\$ 1,970.00
Total			\$ 5,302.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: