

MBM WHEELPOWER PTE. LTD.

YOUR REF.: SLM1080B

OUR REF.: SLB4348T

TO: Allied World Assurance Company, Ltd

CC: MOTOR CLAIMS DEPARTMENT

FAX:

ESTIMATE FOR VEHICLE NO.: SLM1080B

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	TAIL GATE 1100.00		1	\$ 1,700.00 ✓
2	TAIL GATE GLASS MOULDING		1	\$ 120.00 ✓
3	WEATHERSTRIP, TAILGATE		1	\$ 150.00 X
4	TAIL GATE HINGE		2	\$ 60.00 X
5	TAILGATE SPOILER		1	\$ 250.00 X
6	TAIL GATE INNER TRIM		1	\$ 480.00 X
7	TAIL GATE UPPER LINING		1	\$ 120.00 X
8	TAIL GATE SIDE INNER LINING LH		1	\$ 50.00 X
9	TAIL GATE SIDE INNER LINING RH		1	\$ 50.00 X
10	TAIL GATE EMBLEM "VEZEL"		1	\$ 50.00 X
11	TAIL GATE EMBLEM "HONDA" LOGO		1	\$ 20.00 X
12	TAIL GATE LAMP LH		1	\$ 500.00 X
13	TAIL GATE LAMP RH		1	\$ 500.00 X
14	REAR BUMPER 761.60		1	\$ 1,000.00 ✓
15	REAR BUMPER REFLECTOR LH		1	\$ 150.00 X
16	REAR BUMPER REFLECTOR RH		1	\$ 150.00 X
17	REAR BUMPER CORNER PANEL RH		1	\$ 380.00 X
18	REAR BUMPER CORNER PANEL LH		1	\$ 380.00 X
19	REAR BUMPER CORNER PANEL INNER LINING RH		1	\$ 250.00 X
20	REAR BUMPER CORNER PANEL INNER LINING LH		1	\$ 250.00 X
21	REAR BUMPER CORNER COVER BRACKET RH		1	\$ 75.00 X
22	REAR BUMPER CORNER COVER BRACKET LH		1	\$ 75.00 X
23	REAR BUMPER CROSS MEMBER		1	\$ 200.00 X
24	REAR BUMPER CLIP		10	\$ 90.00 ✓
25	REAR BUMPER UNDERCOVER		1	\$ 200.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



DATE: 8/8/2020
FROM: Lee Shirley
FAX: 6452 5333
CONTACT: 8686 5188
MAKE & MODEL: HONDA VEZEL 1.5X CVT
CHASSIS NO.: RU11209461
ENGINE NO.: L15B4409461
YEAR MADE: 2016
ACCIDENT DATE: 1 August 2020

MBM WHEELPOWER PTE. LTD.
160 SIN MING DRIVE, #06-02
SIN MING AUTOCITY
t 6262 8888 f 6452 5333
COMPANY REG. NO.: 200204110W

26	FENDER INNER LINER RH	1	\$	Sn	100.00	X
27	FENDER INNER LINER LH	1	\$	Sn	100.00	X
28	WHEEL ARCH PROTECTOR RH	1	\$	Sn	150.00	X
29	WHEEL ARCH PROTECTOR LH	1	\$	Sn	150.00	X
30	TAIL LAMP RH	1	\$	Sn	500.00	X
31	TAIL LAMP LH	1	\$	Sn	500.00	X
32	REAR END PANEL	1	\$	R	650.00	X
33	REAR END PANEL TOP GARNISH	1	\$	Sn	85.00	X
TOTAL:					\$ 9,485.00	
LESS 20%:					\$ (1,897.00)	
PARTS TOTAL:					\$ 7,588.00	

SPECIAL NETT

REAR NUMBER PLATE & HOLDER	1	\$	Sn	50.00	X
BODY SEALANT	1	\$	nn	50.00	X
TAIL GATE SEALANT	1	\$	30sn	80.00	
REAR BUMPER SENSOR	1	\$	Sn	250.00	X
REAR BUMPER STEP FOOT PLATE	1	\$	Nol	200.00	✓
REAR BUMPER LOWER DIFFUSER	1	\$	Sn	360.00	X
REAR BUMPER EXHAUST PIPE	1	\$	Nol Sn	200.00	X
			120sn		✓

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS	\$	500l	1,600.00	
TO REMOVE & INSTALL REAR UPHOLSTERY TO FACILITATE REPAIR	\$	60l	150.00	
TO REMOVE & INSTALL TAILGATE GLASS	\$	120l	180.00	
TO REALIGN EXHAUST PIPE	\$	nn	80.00	X
TO APPLY ANTI RUST COATING	\$	✓ 30l	80.00	?
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	20l	100.00	
TO REMOVE & INSTALL REVERSE SENSOR	\$	50l	80.00	
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	400l	1,000.00	
TOTAL:			\$ 12,048.00	
7% GST:			\$ 843.36	
GRAND TOTAL:			\$ 12,891.36	