

Certification for Bus Repairs

CBR REF NO. : SL20205473Depot : SLReport No.: W29072020BUS VEHICLE NO. : SBS3198UDriver's Co no. & Name : 17927 Wong Way ShenAccident Date : 28/07/2020Date in : 28/07/2020Date Out : 10/09/2020

Yr Of Reg	Make / Model	Chassis No.
2012	Volvo B9TL Eu5, DD, AC, 3 Axle	YV3S4P92XCA157268

Stock Code	Description	Quantity	Total Material cost(\$)
		0	\$0.00
30541727	LED STOP/TAIL LIGHT 24V;30541713 1 LED	1	\$66.00
30750003	SEALED LEVER LATCH;OS/NS;RR SIDE DR	2	\$68.00
30750383	ALLOY CAPPING FOR LOWER DECK SIDE PLANK	1	\$74.00
30541726	LED INDICATOR LIGHT 24V;30541714 1 LED	1	\$65.00
30750059	O/S LOWER ENG ACCESS DOOR;SHEETMETAL	1	\$1,620.00
30750012	EXTERIOR RR O/S CORNER;F/GLASS	1	\$732.00
30541715	REAR REVERSE LAMP;B9TL EU5	1	\$81.00
30122256	RIVET.MBP-R8-M6.SIDE FRAME	100	\$32.00
30730009	BOSTICK SEALANT 7008	7	\$108.00
30750126	M8X15 HEXALOBULAR TORX CAP HEAD BOLT	20	\$22.00
30750055	PANEL ATTACHMENT BRKT;SHEETMETAL	2	\$59.00
30750060	SIDE SHEETMETAL PANEL	1	\$853.00
30750041	SIDE SHEETMETAL PANEL	1	\$190.00
30750042	SIDE SHEETMETAL PANEL	1	\$769.00
30750032	PANEL ATTACHMENT BRKT;SHEETMETAL	2	\$27.00
30750649	SIDE PLANK	1	\$5,047.00
30750030	GLASS.SIDE.4MM.GLAZING.O/N/S	1	\$654.00
30750007	GLASS.SIDE.4MM.GLAZING.O/N/S	2	\$500.00
30122240	SIMSON PRIMER G EXTRA M - 1000/250ML	1	\$48.00
30730009	BOSTICK SEALANT 7008	9	\$139.00
30117229	GLASS.SIDE.4MM.GLAZING	1	\$153.00
30750118	SIKA 552 WHITE 600ML SAUSAGE	3	\$42.00
30122256	RIVET.MBP-R8-M6.SIDE FRAME	100	\$32.00
30730009	BOSTICK SEALANT 7008	-9	(\$139.00)
30122240	SIMSON PRIMER G EXTRA M - 1000/250ML	-1	(\$48.00)
30750030	GLASS.SIDE.4MM.GLAZING.O/N/S	-1	(\$654.00)
30750055	PANEL ATTACHMENT BRKT;SHEETMETAL	-2	(\$59.00)
30750032	PANEL ATTACHMENT BRKT;SHEETMETAL	-2	(\$27.00)
30750126	M8X15 HEXALOBULAR TORX CAP HEAD BOLT	-20	(\$22.00)
30122256	RIVET.MBP-R8-M6.SIDE FRAME	-100	(\$32.00)
30750012	EXTERIOR RR O/S CORNER;F/GLASS	-1	(\$732.00)
30541715	REAR REVERSE LAMP;B9TL EU5	-1	(\$81.00)
30541726	LED INDICATOR LIGHT 24V;30541714 1 LED	-1	(\$65.00)
30541727	LED STOP/TAIL LIGHT 24V;30541713 1 LED	-1	(\$66.00)
30122256	RIVET.MBP-R8-M6.SIDE FRAME	-100	(\$32.00)

TOTAL FOR PARTS S\$ 9424.00

S/N	Labour / Spray Painting / Contractor Cost	Amount
1	(2) Workshop Labour	S\$ 192.00
2	Contractor's repair charges	S\$ 4300.00

TOTAL LABOUR / SPRAY PAINTING / CONTRACTOR COST S\$ 4492.00

Repair cost of Advertisement / Livery S\$ -

TOTAL DAMAGE S\$ 13916.00

Certification for Bus Repairs

CBR REF NO. : SL20205473Depot : SLReport No.: W29072020BUS VEHICLE NO. : SBS3198UDriver's Co no. & Name : 17927 Wong Way ShenAccident Date : 28/07/2020Date in : 28/07/2020Date Out : 10/09/2020

Yr Of Reg	Make / Model	Chassis No.
2012	Volvo B9TL Eu5, DD, AC, 3 Axle	YV3S4P92XCA157268
TOTAL DAMAGE		S\$ 13916.00
Overheads		S\$ 4174.80
Towing Charges		S\$ -
Repair Period : 8 day(s)	Loss of Use	S\$ 3421.12
TOTAL LOSS		S\$ 21511.92

Prepared By : Goh Jit MinDate : 31/12/2020

Approved By

Workshop Mgr : Tay Inn MengDate : 31/12/2020

	Survey Fee	refer to Group Claims
TOTAL DUE		S\$ 21511.92

Acknowledged By

Depot Safety : Rosy YeowDate : 04/01/2021

* This is computer generated document and does not require signature

