

Date: 11.08.2020
Vehicle No: SMR4220G
Model: HONDA SHUTTLE 1.5 AUTO
Chassis: GP72001933 - 2018
Reg.Year: 2020

Third Party Insurer: QBE
Third Party Veh No: SJZ8229A
Date of Accident: 10.08.2020

*Not Authorised
Resurvey By paint
4 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>By</i> \$986.90
2	REAR TAILGATE "SHUTTLE" EMBLEM	1		<i>re</i> \$46.60
3	REAR TAILGATE "HYBRID" EMBLEM	1		<i>re</i> \$56.20
4	REAR TAILGATE INNER TRIM CLIPS	8	\$5.50	\$44.00
5	REAR WINDSCREEN MOULDING	1		<i>re</i> \$68.70
6	REAR BUMPER	1		<i>re</i> \$783.70
7	REAR BUMPER CLIPS	8	\$5.80	<i>re</i> \$46.40
8	REAR TAILLAMP RH	1	<i>N.C (CM)</i>	\$580.20
9	REAR END PANEL	1		REPAIR
<i>I KK Auto Consultants hence notify the Repairer of the following:</i> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company				
SUB TOTAL				\$2,612.70
LESS 20%				-\$522.54
PARTS TOTAL				\$2,090.16

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>re</i> \$60.00
2	REAR WINDSCREEN STOPPER	2	\$15.00	<i>re</i> \$30.00
3	REAR BUMPER REVERSE SENSOR	1		<i>re</i> \$350.00
S/N TOTAL				\$440.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REFIX, REPLACE, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

\$600.00 *400*

LABOUR CHARGES TO REMOVE, REFIX & REPLACE REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT, REAR WINDSCREEN MOULDING & ETC. TO EFFECT REPLACE OF REAR TAILGATE & ETC.

\$150.00 *120*

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$80.00 *50*

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR TAILGATE & ETC.

\$120.00 *60*

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

452 Tagore Industrial Avenue Singapore 787823
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date: 11.08.2020
Vehicle No: SMR4220G
Model: HONDA SHUTTLE 1.5 AUTO
Chassis: GP72001933 - 2018
Reg.Year: 2020

Third Party Insurer: QBE
Third Party Veh No: SJZ8229A
Date of Accident: 10.08.2020

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT
REAR TAILGATE, REAR BUMPER, REAR END PANEL & ETC.

\$700.00 4001

TO CHECK WIRING & ELECTRICAL WIRING SYSTEM.

\$80.00 201

LABOUR TOTAL \$1,730.00

ONG TOTAL \$4,260.16

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

452 Tagore Industrial Avenue Singapore 787823
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

