

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

TEO BOON LIANG
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

TPChin
Jale.

11th August 2020

TMAH3513VLJ115153

Accident date: 03th AUGUST 2020

Estimated repair cost for vehicle no: SMP7748S HYUNDAI I30 1.4 '2019

S/n	Qty	Items	U/price	Amount
1	1	Front bonnet <i>new</i>		\$1,150.00 X
2	1	front bonnet inner lock <i>gate new</i>		\$185.20 X
3	1	front bonnet inner rubber		\$125.00 X
4	1	Front grille <i>cut</i>		\$415.00 ✓
5	1	Front grille logo <i>new</i>		\$80.00 ✓
6	1	Front Bumper <i>behind</i>		\$950.00 837
7	1	Front Bumper inner sponge <i>new new</i>		\$155.00 X
8	2	Front Bumper Side Bracket <i>new</i>	\$133.00	\$266.00 X
9	8	Front bumper clips <i>new</i>	\$5.00	\$40.00 ✓
10	2	Front Head Lamp <i>LT cracked</i>	\$ 3202.00	\$ 6404.00 3202
11	1	front support panel <i>new</i>		\$688.00 X
12	2	Fog lamp <i>LT Damp</i>	\$255.00	\$510.00 255
13	2	Front bumper fog lamp cover <i>cracked LT</i>	\$88.10	\$176.20 88.10
14	1	front bumper center lower garnish <i>new</i>		\$211.00 X
15	1	Front bumper lower grille	5489.10	\$188.00 X
16	1	Front bumper number plate	4391.28	\$50.00 X
17	1	Front bumper reinforcement <i>new</i>		\$385.00 X
18	1	Front bumper lower cover		\$280.80 X

Front bumper day running light.

572

Subtotal :- \$7,565.20

Labour charges

Tuff kote

\$120.00 X

To Check Wiring System

\$80.00 30

Panel beating

\$600.00 300

Spray painting

\$700.00 250

Subtotal :- \$1,500.00

Total :- \$9,065.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 4971.28 (P/P)

03 Days.