

Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

LTK

GST REG. NO : M2 - 0020081 - X

11 AUG 2020

E S T I M A T E

Estimate No. : b1 55735 Page No. : 1 of 5
Date Estimated : 11/08/2020
Prepared By : Joseph Yaguel

ESTIMATE REPAIR FOR -
Kwon Na Young
Elizabeth Drive
01-13
Singapore 669743

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
KR5300B	WBA2A32000VZ50802	13/02/2015	218iA AT	0

DESCRIPTION	VALUE
To replace rear bumper panel and attachment, bootlid, rework tail panel	1700 3,400.00
Spray rear bumper, bootlid and tail panel	1730 2,666.00
To supply rear emboss number plate.	nm X 83.00
To remove and install boot compartment carpet and garnish to facilitate repairs.	nm 230? 271.00
To replace rear windscreen glass.	676.00
To conduct water leak tests.	75.00
To supply and install rear windscreen solar film.	nm ? 625.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 171.00
To carry out body cavity preservation. (Per panel).	100 118.00
Sundries	80? 150.00

Total Labour 1: **8,241.00**

DESCRIPTION	QTY	PRIC	VALUE
TRUNK LID <i>sf</i>	1	1,210.35	1,210.35
REAR BUMPER PANEL PRIMED (PDC) <i>de</i>	1	1,045.45	1,045.45
RR BUMPER LH SIDE GUIDE <i>X sue</i>	1	61.35	61.35
RR BUMPER RH SIDE GUIDE <i>? X sue</i>	1	61.35	61.35
REAR BUMPER CARRIER <i>? X sue</i>	1	460.40	460.40
SUPPORT <i>? X sue</i>	1	45.55	45.55
RR BUMPER LH INNER SIDE GUIDE <i>X sue</i>	1	61.35	61.35
RR BUMPER RH INNER SIDE GUIDE <i>? X sue</i>	1	61.35	61.35

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Page No. : 2 of 5

Estimate No. : b1 55735
Date Estimated : 11/08/2020
Prepared By : Joseph Yaguel

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKR5300B	WBA2A32000VZ50802	13/02/2015	218iA AT	0

DESCRIPTION	QTY	PRIC	VALUE
GROMMET <i>na</i>	2	0.80	1.60
PLAQUE 74MM <i>na</i>	1	71.60	71.60
BUMP STOP ? <i>na</i>	10/6	3.75	2250 37.50
REAR FLAP TOWING EYE PRIMED <i>cut xsvl</i>	1	43.05	43.05
REAR WINDOW ESG ? <i>na</i>	1	657.60	657.60
DECOUPING RING PDC TORQUE CONVERTER <i>na x na</i>	4	5.10	20.40
(DG) CLEANER R1 (100ML) ? <i>na</i>	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) ? <i>na</i>	2	131.55	263.10
(DG/SL)ADHESIVE PRIMER VP 206 (30ML) ? <i>na</i>	1	27.85	27.85
Total Parts :			4,156.00

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 31/08/2020 @ 1450 Excess S\$ _____

Surveyor's Name P. Han Sign _____

Surveyor's Tel _____ Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Labour 1	:	8,241.00
Parts	:	4,156.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	867.00
Grand Total	:	13,264.00



** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 55735**
Date Estimated : **11/08/2020**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -
Kwon Na Young
1 Elizabeth Drive
#01-13

Singapore 669743

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKR5300B	WBA2A32000VZ50802	13/02/2015	218iA AT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6 nec	2.70	3.00		8.10
# EXPANDING NUT nec	1.00	2.00		2.00
# LETTERING 218I nec	64.45	1.00		64.45

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	74.55
Total Labour & Parts :	74.55