

Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



LTKK

GST REG. NO : M2 - 0020081 - X

11 AUG 2020

E S T I M A T E

Estimate No. : **b1 55735** Page No. : 1 of 5
Date Estimated : **11/08/2020**
Prepared By : **Joseph Yaguel**

<p>- ESTIMATE REPAIR FOR - Kwon Na Young 1 Elizabeth Drive #01-13 Singapore 669743</p>	<p>- ACCOUNT - 121 AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Chartis Building Singapore 079120</p>
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKR5300B	WBA2A32000VZ50802	13/02/2015	218iA AT	0

DESCRIPTION	VALUE
To replace rear bumper panel and attachment, bootlid, rework tail panel	1700 3,400.00
Spray rear bumper, bootlid and tail panel	1730 2,666.00
To supply rear emboss number plate.	X 83.00
To remove and install boot compartment carpet and garnish to facilitate repairs.	230? 271.00
To replace rear windscreen glass.	676.00
To conduct water leak tests.	75.00
To supply and install rear windscreen solar film.	? 625.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
To carry out body cavity preservation. (Per panel).	100 118.00
Sundries	? 150.00
Total Labour 1:	8,241.00

DESCRIPTION	QTY	PRIC	VALUE
TRUNK LID sf	1	1,210.35	1,210.35
REAR BUMPER PANEL PRIMED (PDC) da	1	1,045.45	1,045.45
RR BUMPER LH SIDE GUIDE X	1	61.35	61.35
RR BUMPER RH SIDE GUIDE ?	1	61.35	61.35
REAR BUMPER CARRIER ?	1	460.40	460.40
SUPPORT ?	1	45.55	45.55
RR BUMPER LH INNER SIDE GUIDE X	1	61.35	61.35
RR BUMPER RH INNER SIDE GUIDE ?	1	61.35	61.35

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 55735	Page No. : 2 of 5
Date Estimated : 11/08/2020	
Prepared By : Joseph Yaguel	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKR5300B	WBA2A32000VZ50802	13/02/2015	218ia AT	0

DESCRIPTION	QTY	PRIC	VALUE
GROMMET <i>na</i>	2	0.80	1.60
PLAQUE 74MM <i>na</i>	1	71.60	71.60
BUMP STOP ?	10	3.75	37.50
REAR FLAP TOWING EYE PRIMED <i>at</i>	1	43.05	43.05
REAR WINDOW ESG ?	1	657.60	657.60
DECOUPING RING PDC TORQUE CONVERTER <i>na</i>	4	5.10	20.40
(DG) CLEANER R1 (100ML) ?	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) ?	2	131.55	263.10
(DG/SL)ADHESIVE PRIMER VP 206 (30ML) ?	1	27.85	27.85
Total Parts :			4,156.00

Claims OD / <u>3rd Party</u> / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time <u>31/08/2020 @ 1450</u>	Excess S\$ _____
Surveyor's Name <u>PRM</u>	Sign _____
Surveyor's Tel _____	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____	
Surveyor's E-mail _____	
No. of Working Days Recommend <u>5 days</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



Labour 1	:	8,241.00
Parts	:	4,156.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	867.79
Grand Total	:	13,264.79

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY****
**** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE ****