

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:2010011581 RCB NO:2010011581

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

Estimate No: ES2090610/WS

Date: 18 Aug 2020

Policy No: 5116013047

Veh Reg No: SKR8659Y

Make/Model: TOYOTA TOYOTA

ESTIMA AERAS

PREMIUM 2.4 A

WS Ref: TP/INDIA

Claim Type: Third Party

Accident Date: 06/08/2020

TP Veh Reg No: SHD3473H

Chassis No: ACR507125643

Engine No: 2AZJ130990

Reg. Date: 13/03/2015

Estimate Repair Cost to Vehicle No :SKR8659Y

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	622.10	1 PC	622.10	✓
2 REAR BUMPER CLIPS	4.50	5 PC	22.50	✓
3 TAILGATE LOGO	72.20	1 PC	72.20	✓
4 TAILGATE EMBLEM "ESTIMA"	49.10	1 PC	49.10	✓
5 TAILGATE EMBLEM "AERAS"	57.20	1 PC	57.20	✓
6 REAR END PANEL	755.40	1 PC	755.40	✓
7 REAR END PANEL INNER TOP GARNISH	308.20	1 PC	308.20	✓
			1,886.70	
		Less 25%	471.68	1,415.03
Special Net				
8 ISET REVERSE SENSOR	280.00	4 PC	280.00	✓
9 REAR END PANEL SEALANT	40.00	1 PC	40.00	✓
			320.00	320.00
Labour				
10 REMOVE AND REFIT REAR BUMPER, TAILLAMP, CUT, WELD REAR END PANEL AND REALIGN THE SAME.	600.00	1 PC	600.00	5401
11 PUTTY AND RESPRAY REAR BUMPER, PARKING SENSORS, TAILGATE, REAR END PANEL AND ALL AFFECTED AREAS.	600.00	1 PC	600.00	✓
12 REMOVE AND REFIX REAR FENDER GARNISH TO FACILITATE REPAIR.	150.00	1 PC	150.00	601
13 RUSTPROOFING	30.00	1 PC	30.00	✓
			1,380.00	1,380.00
Total				S\$ 3,115.03
Add GST @ 7%				218.05
Total Amount Payable				<u>S\$ 3,333.08</u>

For Cheng Hoe Motor Pte Ltd



AUTHORISED SIGNATURE