

S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 12 August 2020

To : LKK

By Fax: 6256-4315

Attn : Bryan

Tel: 97237799

VEHICLE NO : JSL 6612

Yamaha LC 135

ACCIDENT DATE: 6 August 2020

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Pillar Grip HH	1	95.00 X
2 Rear Mudguard Broken	1	235.00 ✓
3 Exhaust Pipe HH	1	650.00 X
4 Exhaust Guard - Nozzle HH	1	280.00 X
5 Exhaust Centre Guard HH	1	250.00 X
6 Rear LH Signal Broken	1	90.00 ✓
7 Clutch Lever HH	1	85.00 X
8 Handle Bar HH	1	155.00 X
9 Rear Rim HH distorted HH	1	320.00 X hand X
10 Rear LH Side Panel Cnt	1	185.00 ✓
11 Balancer Cnt	1 set	160.00 ✓
12 Front Rim distorted	1	380.00 ✓
13 Front LH Side Panel Cnt	1	168.00 ✓

Sub-Total 3,053.00

Less 10% 305.30

Sub-Total 2,747.70

1218.00

1070 1096.20



VEHICLE NO : JSL 6612

Yamaha LC 135

Nett Items

1	Rear number plate <i>st</i>	15.00	✓
2	Number plate holder <i>NN</i>	85.00	X
3	One set body decal sticker <i>NK</i>	120.00	→ 80/-
4	Towing fee <i>NN</i>	40.00	X
5	Remove & replace necessary parts, align & etc	250.00	150/-
6	Remove & replace rim & check fork assy	200.00	80/-

Sub-Total

710.00

Nett Total

3,457.70

NB: This estimate was made from a visual inspection only. any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion.

Thank you

S9 MOTOR TRADING PTE LTD

:LG

12/08/2020 @ 1700hr

Not Androm

Lpnn 3 days

Ryan

LKK And

1421.20

4/5 1100/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer