

**ACCIDENT REPAIR ESTIMATES**

Our Ref: TP / SMH7086K

Type of Claim : TPVehicle No. : SMH7086KMake & Model : BLUECAR / BLUECARBLUYear of Manufacture : 2018Chassis No. : VL4BCEB4RJT003458Ins Company : AIG ASIA PACIFIC  
INSURANCE PTE LTDEngine No. : 922403B18W282820021Excess : 0

Policy No. : \_\_\_\_\_

Date of Accident : 06 08 2020Time of Accident : 1400Suggested Days of Repair : 5Case Owner : BLUECAR EAST ASIA PTE LTDTP Vehicle No. : GBG1067R**Repair Estimates**Parts (a) Cost / List Price Items \$ 6,223.00Plus/Less <sup>15</sup>~~20.0%~~ \$ 1,244.60Total of Cost / List \$ 7,467.60(b) Nett Price Items \$ -Less \$ -Total of Nett Item \$ -(c) Special Nett Items \$ 40.00Total Parts Cost (Appendix A) \$ 7,507.60Labour (Appendix B) \$ 2,450.00Total Repair Cost \$ 9,957.60**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged parts during repair
- Parts prices are subject to confirmation
- Third party survey on "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Guo Qiang - 8288 0282Company : LKKSurvey conducted on : 12/8/2020 at \_\_\_\_\_**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 6 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : h Date: \_\_\_\_\_before/After  
paint photos.

P/P

\$8055.85

## ESTIMATED REPAIR COST DETAILS

|                           |                                |                           |                                  |
|---------------------------|--------------------------------|---------------------------|----------------------------------|
| <b>Vehicle No</b> :       | <u>SMH7086K</u>                | <b>Case Owner</b> :       | <u>BLUECAR EAST ASIA PTE LTD</u> |
| <b>Make &amp; Model</b> : | <u>BLUECAR / BLUECARBLUECA</u> | <b>Year Manufacture</b> : | <u>2018</u>                      |
| <b>Chassis No</b> :       | <u>VL4BCEB4RJ003458</u>        | <b>Engine No</b> :        | <u>922403B18W2828200 21</u>      |
| <b>Date &amp; Time</b> :  | <u></u>                        | <b>Supplier</b> :         | <u></u>                          |
| <b>Order By</b> :         | <u></u>                        | <b>Type of Claim</b> :    | <u>TP</u>                        |

| S/No | Part Description                        | QTY | Cost Price  |             | List Price | Nett Price | S/N      |
|------|-----------------------------------------|-----|-------------|-------------|------------|------------|----------|
|      |                                         |     | Unit        | Sub-Total   |            |            |          |
| 1    | REAR BUMPER ASSY ✓ CPA                  | 1   | \$ 1,364.00 | \$ 1,364.00 |            |            |          |
| 2    | REAR BUMPER SCREW ✓ MCL                 | 10  | \$ 2.00     | \$ 20.00    |            |            |          |
| 3    | REAR BUMPER REFLECTOR LH X SVC          | 1   | \$ 122.00   | \$ 122.00   |            |            |          |
| 4    | REAR BUMPER REINFORCEMENT X SVC         | 1   | \$ 80.00    | \$ 80.00    |            |            |          |
| 5    | REAR BUMPER REINFORCEMENT BRACKET LH X  | 1   | \$ 42.00    | \$ 42.00    | SVC        |            |          |
| 6    | LH TAILLAMP ASSY ✓ CPA                  | 1   | \$ 147.00   | \$ 147.00   |            |            |          |
| 7    | TAILLAMP COVER LH ✓ CPA                 | 1   | \$ 282.00   | \$ 282.00   |            |            |          |
| 8    | REAR LH FENDER COVER ✓ LT               | 1   | \$ 189.00   | \$ 189.00   |            |            |          |
| 9    | REAR LH FENDER COVER NUTS ✓ MCL         | 4   | \$ 1.00     | \$ 4.00     |            |            |          |
| 10   | REAR LH FENDER INNER SHIELD ✓ RL        | 1   | \$ 150.00   | \$ 150.00   |            |            |          |
| 11   | REAR LH FENDER INNER SHIELD CLIPS ✓ MCL | 8   | \$ 2.00     | \$ 16.00    |            |            |          |
| 12   | REAR FENDER PANEL LH ✓ DIS              | 1   | \$ 3,807.00 | \$ 3,807.00 |            |            |          |
| 13   | REAR FENDER STICKER LH/RH ✓ MCL         | 1   | \$ -        | \$ -        |            |            | \$ 40.00 |
| 14   |                                         |     | \$ -        | \$ -        |            |            |          |
| 15   |                                         |     | \$ -        | \$ -        |            |            |          |
| 16   |                                         |     | \$ -        | \$ -        |            |            |          |
| 17   |                                         |     | \$ -        | \$ -        |            |            |          |
| 18   |                                         |     | \$ -        | \$ -        |            |            |          |
| 19   |                                         |     | \$ -        | \$ -        |            |            |          |
| 20   |                                         |     | \$ -        | \$ -        |            |            |          |
| 21   |                                         |     | \$ -        | \$ -        |            |            |          |
| 22   |                                         |     | \$ -        | \$ -        |            |            |          |
| 23   |                                         |     | \$ -        | \$ -        |            |            |          |
| 24   |                                         |     | \$ -        | \$ -        |            |            |          |
| 25   |                                         |     | \$ -        | \$ -        |            |            |          |
| 26   |                                         |     | \$ -        | \$ -        |            |            |          |
| 27   |                                         |     | \$ -        | \$ -        |            |            |          |
| 28   |                                         |     | \$ -        | \$ -        |            |            |          |
| 29   |                                         |     | \$ -        | \$ -        |            |            |          |
| 30   |                                         |     | \$ -        | \$ -        |            |            |          |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

|                |                                   |                     |
|----------------|-----------------------------------|---------------------|
| Vehicle No. :  | <u>SMH7086K</u>                   | Case Owner          |
| Make & Model : | <u>/ BLUECARBLUECAR /</u> BLUECAR | Year of Manufacture |

**BLUECAR  
EAST ASIA  
PTE LTD**  
**2018**

| S/No | Labour Description                                                                                                                                                  | Esimated Price | Adjusted Price |
|------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------|----------------|
| 1    | TO REPAIR,REPLACE REAR BUMPER, REINFORCEMENT, BRACKET,<br>REAR LEFT FENDER, COVER, INNER SHIELD, LH TAILLAMP ASSY &<br>COVER, REFLECTOR , STICKER AND AFFECTED AREA | \$1,500.00     | 800            |
| 2    | TO PUTTY AND RESPRAY ON REAR BUMPER, REAR LEFT FENDER<br>AND AFFECTED AREA                                                                                          | \$700.00       | 250            |
| 3    | TO APPLY TUFF KOTE                                                                                                                                                  | \$150.00       | 60             |
| 4    | TO CHECK WIRING                                                                                                                                                     | \$100.00       | 30             |
|      |                                                                                                                                                                     |                |                |
|      |                                                                                                                                                                     |                |                |
|      |                                                                                                                                                                     |                |                |
|      |                                                                                                                                                                     |                |                |
|      |                                                                                                                                                                     |                |                |
|      |                                                                                                                                                                     |                |                |
|      |                                                                                                                                                                     |                |                |
|      |                                                                                                                                                                     |                |                |
|      |                                                                                                                                                                     |                |                |
|      |                                                                                                                                                                     |                |                |
|      |                                                                                                                                                                     |                |                |
|      |                                                                                                                                                                     |                |                |
|      |                                                                                                                                                                     |                |                |
|      |                                                                                                                                                                     |                |                |
|      |                                                                                                                                                                     |                |                |
|      |                                                                                                                                                                     |                |                |
|      |                                                                                                                                                                     |                |                |
|      |                                                                                                                                                                     |                |                |
|      |                                                                                                                                                                     |                |                |
|      |                                                                                                                                                                     |                |                |
|      | TOTAL                                                                                                                                                               | \$2,450.00     |                |

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*