

TTS EUROCARS PTE LTD

383 Sin Ming drive Singapore 575717

Date : 07.08.2020

RE: VEHICLE REPAIR QUOTATION

Insurance Company	:	India International Insurance
Vehicle Reg No	:	SLT1156E
Name of Insured	:	
Policy Number	:	
Date of Accident	:	07.08.2020
Tyre of Claim	:	Third Party Claim
Model	:	BMW 530I
Chassis No	:	WBAJA52090G885833

We are please to submit our estimate of repairs to the above mention vehicle.

		Parts	Labour
1	FRONT RH FENDER	\$ 1,161.42	
2	FRONT RH FENDER GRILLE	\$ 99.54	
3	FRONT RH SIDE MIRROR	\$ 1,623.34	
4	FRONT RH DOOR	\$ 2,186.96	
5	DOOR HINGE TOP	\$ 90.51	
6	DOOR HINGE BOTTOM	\$ 90.51	
7	DOOR WINDO REGULATOR	\$ 528.58	
8	DOOR WINDOW MOTOR	\$ 419.10	
9	DOOR WEATHER STRIP	\$ 289.58	
10	WEATHER STRIP COLUMN B	\$ 106.44	
11	WEATHERSTRIP EXTERNAL LINE	\$ 182.02	
12	WEATHERSTRIP WINDOW FRAME	\$ 264.84	
13	REAR DOOR RH	\$ 2,386.98	
14	DOOR HINGE TOP	\$ 90.51	
15	DOOR HINGE BOTTOM	\$ 90.51	
16	SIDE SKIRT RH	\$ 660.32	
17	SUPPORT LEDGE BACK	\$ 43.57	
18	SUPPORT LEDGE MID	\$ 43.57	
19	SUPPORT LEDGE EDGE	\$ 43.57	
20	REAR DOOR CARRIER		
21	REAR DOOR WINDOW LIFTER	\$ 628.58	
22	REAR DOOW WEATHERSTRIP	\$ 289.58	
23	REAR DOOR GAP SEAL	\$ 76.39	
24	DOOR WEATHER STRIP COLUMN B	\$ 137.90	
25	DOOR WEATHER STRIP EXTERNAL LINE	\$ 132.86	
26	DOOR WEATHERSTRIP EXTERNAL LINE	\$ 132.86	
27	REAR RH FENDER	\$ 2,458.67	

Sub Total Parts	\$14,258.71
Less 5%	\$ 712.94
Total Parts	<u>\$13,545.77</u>

1	Sundries	\$	150.00
2	Wiring connection and check.	\$	150.00
3	Tuff kote and spray anti rust proofing	\$	350.00

4	Sealant for front rh door, rear RH door	\$	250.00
5	To remove and replace front RH door, dismantle door components, scuff plates trim boards,	\$	350.00
6	To remove and repalce rear RH door, dismantle door components, scuff plates trim boards	\$	350.00
7	To conduct door frequency test, calibrate door "keyless entry" programme, install and conduct acutuation,	\$	350.00
8	To remove and refic/ replace front rh side mirror	\$	150.00
9	Labour charges to dismantle & refix front bumper front rh fender, front rh door, rear rh door rear rh fender, rh side skirt, rh rocker panel rh side mirror, rh "B" pillar and all other affected areas To repair and adjust affected portion to specific dimension.	\$	2,000.00
10	To putty, sand, spray paint, polish and wax front bumper, front rh fender, front rh door rear rh door, rear rh fender, RH side skirt RH rocker panel, RH "B" pillar and all other affected areas	\$	2,000.00
11	To conduct and programme 360 degree sensor calibrate, actuate distance setting. Integration and adaptation	\$	550.00
12	Remove and refix\ front bumper sensor	\$	150.00
13	To conduct ECU programming, check and clear fault codes, restore programme modules	\$	550.00
Total (Labour)		\$	<u>7,350.00</u>
Sub Total :		\$	20,895.77
GST 7%		\$	1,462.70
Grand Total :		\$	<u>22,358.48</u>

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.