



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2108552

INV Date 13/12/2021

Reference CC4/LPC20008295/R1ea3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. XE 2971Z
Insured Veh. XE 3588R
Claim No. 20/20/20/VC06/023475
Policy No. Z/20/VC06/106259
Accident Date 16/07/2020
Inspection Date 12/08/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC20008295/R1ea3q2 Date: 13/12/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 3588R	Veh. Inspected	XE 2971Z	
Policy No.	Z/20/VC06/106259	Coverage (\$)	0.00	
Claim No.	20/20/20/VC06/023475	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	12/08/2020	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI FUSO FV51	c.c	11967	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	FV51SJA10152	Colour	MULTI	
Odometer	408821 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	BRIDGESTONE	8 mm	
L/H Front Tyre	295/80 R22.5	BRIDGESTONE	8 mm	
R/H Rear Tyre	295/80 R22.5 (D)	BRIDGESTONE	8/8 mm	
L/H Rear Tyre	295/80 R22.5 (D)	BRIDGESTONE	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/07/2020	Inspection Date	12/08/2020	
Survey held at	ASM AUTOMOTIVE SERVICES PTE LTD 13 PIONEER SECTOR 1 SINGAPORE 628424			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 2971Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	MIRROR STAY ,LH	TO REPAIR SEE LABOUR	809.27	-
1	ROUND MIRROR ,LH	SERVICEABLE	116.48	-
2	SIDE MIRROR ,LH @\$188.78	SCRATCHED	377.56	377.56
1	MIRROR STAY LOWER BRACKET ,LH	TO REPAIR SEE LABOUR	128.85	-
1	CORNER PANEL ,LH	CRACKED	1,164.13	1,164.13
1	FRONT SIGNAL LAMP ,LH	SERVICEABLE	234.41	-
1	FRONT BUMPER TOP COVER ,LH	DEFORMED	193.04	193.04
1	FRONT BUMPER TOP COVER REINFORCEMENT ,LH	BENT	226.06	226.06
1	FRONT BUMPER	BENT	1,694.48	1,694.48
1	FRONT BUMPER STEP PROTECTOR	CRACKED	162.95	162.95
1	HEADLAMP ALUMINIUM BRACKET ,LH	CRACKED	947.63	947.63
1	HEADLAMP ASSY ,LH	CRACKED	1,286.44	1,286.44
1	HEADLAMP BEZEL ,LH	CRACKED	210.48	210.48
1	FOGLAMP ,LH	CRACKED	293.25	293.25
1	FOGLAMP BEZEL ,LH	CRACKED	186.05	186.05
1	SIDE BUMPER ,LH	CRACKED	140.29	140.29
1	BUMPER AIR GUIDE DUCT, LH	DEFORMED	96.70	96.70
1	UREA SENSOR ,LH	CUT	127.42	127.42
1	DOOR PANEL ,LH	BENT	3,092.64	3,092.64
1	DOOR SIGNAL LAMP ,LH	BROKEN	81.53	81.53
1	STEP LOWER FENDER ,LH	CRACKED	744.59	744.59
1	STEP PLATE ,LH -CENTER	SCRATCHED	220.74	220.74
1	STEP UPPER WALL ,LH	BROKEN	324.55	324.55
1	STEP PLATE ,LH -LOWER	BROKEN	331.55	331.55
1	STEP UNDER COVER ,LH	BROKEN	237.97	237.97
1	STEP BRACKET ,LH-1ST	BENT	471.94	471.94
1	STEP BRACKET ,LH-2ND	TO REPAIR SEE LABOUR	679.95	-
	LESS 25% DISCOUNT		-3,645.24	-3,153.00
			10,935.71	9,458.99

Report Ref No. CC4/LPC20008295/R1ea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<u>SPECIAL NETT ITEMS</u>	BENT		
	FRONT NUMBER PLATE (SN)		15.00	15.00
			15.00	15.00
	<u>LABOUR</u>			
	TO REMOVE AND REPLACE DAMAGED PARTS AS ABOVE ,JACK AND REALIGN LEFT SIDE PILLAR .INCLUSIVE OF THE REPAIR OF MIRROR STAY ,LH ,MIRROR STAY LOWER BRACKET ,LH AND STEP BRACKET ,LH-2ND.		2,450.00	1,750.00
	SPRAY PAINTING (2 COLOURS) .		1,000.00	750.00
	LOGO WRITING.		150.00	120.00
			3,600.00	2,620.00
GRAND TOTAL			14,550.71	12,093.99
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,650.00

Report Ref No. CC4/LPC20008295/R1ea3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XE 2971Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XE 2971Z

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

