



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424
Main Line: 6265 0980 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Co. / GST Reg. No.: 201203813C

bizSAFE₃

FROM : Jaclyn Lai
TEL. NO. : 6265-0026 / 9236-8218
EMAIL : jaclynlai@asmauto.com.sg

TO : Lonpac Insurance Bhd
ATTN : Motor Claim Department
TEL. NO. : 6250-7388
EMAIL : mt_claim@lonpac.com

CC : T B C Transportation & Trading P/L

DATE : 05.08.2020

VEHICLE NO. : XE 2971 Z
MODEL NO. : MIT FUSO FV51SJR5VDEA
CHASSIS NO. : FV51SJA10152
ENGINE NO. : OM457284022
LTA REG DATE : 19/8/2014

CLAIM TYPE : Third Party - XE 3588 R
D.O.A : 16.07.2020
CLAIM REF NO. : asm/AC20059/JL

Quotation for Accident Repair

S/N	SPARE PARTS	QUANTITY	UNIT PRICE	AMOUNT
1	Mirror stay, LH <i>repair</i>	1	\$ 809.27	\$ 809.27
2	Round mirror, LH <i>X</i>	1	\$ 116.48	\$ 116.48
3	Side mirror, LH <i>scr</i>	2	\$ 188.78	\$ 377.56
4	Mirror stay lower bracket, LH <i>repair</i>	1	\$ 128.85	\$ 128.85
5	Corner panel, LH <i>con</i>	1	\$ 1,164.13	\$ 1,164.13
6	Front signal lamp, LH <i>X</i>	1	\$ 234.41	\$ 234.41
7	Front bumper top cover, LH <i>de</i>	1	\$ 193.04	\$ 193.04
8	Front bumper top cover reinforcement, LH <i>st</i>	1	\$ 226.06	\$ 226.06
9	Front bumper <i>bi</i>	1	\$ 1,694.48	\$ 1,694.48
10	Front bumper step protector <i>con</i>	1	\$ 162.95	\$ 162.95
11	Headlamp aluminium bracket, LH ?	1	\$ 947.63	\$ 947.63
12	Headlamp assy, LH <i>con</i>	1	\$ 1,286.44	\$ 1,286.44
13	Headlamp bezel, LH <i>con</i>	1	\$ 210.48	\$ 210.48
14	Foglamp, LH <i>con</i>	1	\$ 293.25	\$ 293.25
15	Foglamp bezel, LH <i>con</i>	1	\$ 186.05	\$ 186.05
16	Side bumper, LH <i>con</i>	1	\$ 140.29	\$ 140.29
17	Bumper air guide duct, LH ?	1	\$ 96.70	\$ 96.70
18	UREA sensor, LH ?	1	\$ 127.42	\$ 127.42
19	Door panel, LH <i>bi</i>	1	\$ 3,092.64	\$ 3,092.64
20	Door signal lamp, LH <i>bro</i>	1	\$ 81.53	\$ 81.53
21	Step lower fender, LH <i>con</i>	1	\$ 744.59	\$ 744.59
22	Step plate, LH - center <i>scr</i>	1	\$ 220.74	\$ 220.74
23	Step upper wall, LH <i>bro</i>	1	\$ 324.55	\$ 324.55
24	Step plate, LH - lower <i>bro</i>	1	\$ 331.55	\$ 331.55
25	Step under cover, LH <i>bro</i>	1	\$ 237.97	\$ 237.97
26	Step bracket, LH - 1st <i>st</i>	1	\$ 471.94	\$ 471.94
27	Step bracket, LH - 2nd <i>repair</i>	1	\$ 679.95	\$ 679.95
SUB-TOTAL :				\$ 14,580.95
LESS 25% :				\$ 3,645.24
BALANCE :				\$ 18,226.19

S/N	SPARE PARTS (SPECIAL NETT ITEMS)	QUANTITY	UNIT PRICE	AMOUNT
1	Front number plate <i>st</i>	1	\$ 15.00	\$ 15.00
S/N ITEMS TOTAL :				\$ 15.00



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424
Main Line: 6265 0980 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Co. / GST Reg. No.: 201203813C

biSAFE₃

TOTAL PARTS :

\$ 18,241.19

LABOUR CHARGES

- 1 To remove and replace damaged parts as above, jack and realign left side pillar.
(\$350 x 7 days)
- 2 Spray painting (2 colours)
- 3 Logo writing

\$ ~~2,450.00~~ 1750

\$ ~~1,000.00~~ 750

\$ ~~150.00~~ 120

TOTAL LABOUR :

\$ 3,600.00

GRAND TOTAL :

\$ 21,841.19

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
7 days
L/S
12/08/2020 @ 1550
Resurvey after repair