



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424
Main Line: 6265 0980 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Co. / GST Reg. No.: 201203813C

bizSAFE₃

FROM : Jaclyn Lai
TEL. NO. : 6265-0026 / 9236-8218
EMAIL : jaclynlai@asmauto.com.sg

TO : Lonpac Insurance Bhd
ATTN : Motor Claim Department
TEL. NO. : 6250-7388
EMAIL : mt_claim@lonpac.com

CC : T B C Transportation & Trading P/L

DATE : 05.08.2020

VEHICLE NO. : XE 2971 Z
MODEL NO. : MIT FUSO FV51SJR5VDEA
CHASSIS NO. : FV51SJA10152
ENGINE NO. : OM457284022
LTA REG DATE : 19/8/2014

CLAIM TYPE : Third Party - XE 3588 R
D.O.A : 16.07.2020
CLAIM REF NO. : asm/AC20059/JL

Quotation for Accident Repair

S/N	SPARE PARTS	QUANTITY	UNIT PRICE	AMOUNT	
1	Mirror stay, LH <i>repair</i>	1	\$ 809.27	\$ 809.27	Rx
2	Round mirror, LH <i>Xsrc</i>	1	\$ 116.48	\$ 116.48	X
3	Side mirror, LH <i>src</i>	2	\$ 188.78	\$ 377.56	
4	Mirror stay lower bracket, LH <i>repair</i>	1	\$ 128.85	\$ 128.85	Rx
5	Corner panel, LH <i>cm</i>	1	\$ 1,164.13	\$ 1,164.13	
6	Front signal lamp, LH <i>Xsrc</i>	1	\$ 234.41	\$ 234.41	X
7	Front bumper top cover, LH <i>de</i>	1	\$ 193.04	\$ 193.04	
8	Front bumper top cover reinforcement, LH <i>bt</i>	1	\$ 226.06	\$ 226.06	
9	Front bumper <i>bt</i>	1	\$ 1,694.48	\$ 1,694.48	
10	Front bumper step protector <i>cm</i>	1	\$ 162.95	\$ 162.95	
11	Headlamp aluminium bracket, LH <i>? cm</i>	1	\$ 947.63	\$ 947.63	
12	Headlamp assy, LH <i>cm</i>	1	\$ 1,286.44	\$ 1,286.44	
13	Headlamp bezel, LH <i>cm</i>	1	\$ 210.48	\$ 210.48	
14	Foglamp, LH <i>cm</i>	1	\$ 293.25	\$ 293.25	
15	Foglamp bezel, LH <i>cm</i>	1	\$ 186.05	\$ 186.05	
16	Side bumper, LH <i>cm</i>	1	\$ 140.29	\$ 140.29	
17	Bumper air guide duct, LH <i>? de</i>	1	\$ 96.70	\$ 96.70	
18	UREA sensor, LH <i>? cut</i>	1	\$ 127.42	\$ 127.42	
19	Door panel, LH <i>bt</i>	1	\$ 3,092.64	\$ 3,092.64	
20	Door signal lamp, LH <i>br</i>	1	\$ 81.53	\$ 81.53	
21	Step lower fender, LH <i>cm</i>	1	\$ 744.59	\$ 744.59	
22	Step plate, LH - center <i>src</i>	1	\$ 220.74	\$ 220.74	
23	Step upper wall, LH <i>br</i>	1	\$ 324.55	\$ 324.55	
24	Step plate, LH - lower <i>br</i>	1	\$ 331.55	\$ 331.55	
25	Step under cover, LH <i>br</i>	1	\$ 237.97	\$ 237.97	
26	Step bracket, LH - 1st <i>bt</i>	1	\$ 471.94	\$ 471.94	
27	Step bracket, LH - 2nd <i>repair</i>	1	\$ 679.95	\$ 679.95	Rx

SUB-TOTAL : 12611.99
LESS 25% : 25%
BALANCE : 9458.99

\$ 14,580.95
\$ 3,645.24
\$ 18,226.19

S/N	SPARE PARTS (SPECIAL NETT ITEMS)	QUANTITY	UNIT PRICE	AMOUNT
1	Front number plate <i>bt</i>	1	\$ 15.00	\$ 15.00
S/N ITEMS TOTAL :				\$ 15.00



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424
 Main Line: 6265 0980 Fax: 6265 6068
 Email: enquiry@asmauto.com.sg
 Co. / GST Reg. No.: 201203813C



TOTAL PARTS : \$ 18,241.19

LABOUR CHARGES

- | | |
|--|-----------------------------|
| 1 To remove and replace damaged parts as above, jack and realign left side pillar.
(\$350 x 7 days) | \$ 2,450.00 1750 |
| 2 Spray painting (2 colours) | \$ 1,000.00 750 |
| 3 Logo writing | \$ 150.00 120 |

TOTAL LABOUR : \$ 3,600.00

GRAND TOTAL : \$ 21,841.19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Resur
Hp 90010068
7 days
4/8
12/08/2020 @ 1550
Resur after repair

9458.99

15.00

2620.00

12093.99

20%

9675.19

4/8 - 9,650

7 days