



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC20007332/Gqf3e2-1

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 18-08-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLZ 3461D	Veh. Inspected	GZ 5557H
Policy No.		Coverage (\$)	0.00
Claim No.	19/20/20/VP05/023468	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	12/08/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA 150D	c.c	2986
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	JTFUF34Y103011953	Colour	BLUE
Odometer	180431	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185 R14	BRIDGESTONE	5 mm
L/H Front Tyre	185 R14	BRIDGESTONE	5 mm
R/H Rear Tyre	185 R14	BRIDGESTONE	5 mm
L/H Rear Tyre	185 R14	BRIDGESTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/07/2020	Inspection Date	16/07/2020
Survey held at	RUI CHUAN CAR REPAIRING BLK 3006 UBI ROAD 1 #01-340 SINGAPORE 407800		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------