



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

MARIAM BEE D/O SHAIK IBRAHIM
BLK 363 WOODLANDS AVE 5 #05-442
SINGAPORE 730363

Contact : 94563242, 90250941

TP Chinn.
Denise.

ESTIMATE

Repair Code : CLM16363

Date in : 07/08/2020

Vehicle Num. : SGZ214E

Model : HYUNDAI ELANTRA AD 1.6 GLS AT

Chassis/Eng# : KMHD841CMHU133342/G4FGGU150293

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID <i>Defect</i>	1	1782.00	✓ 1,782.00
REAR BOOTLID 'ELANTRA' EMBLEM <i>2</i>	1	56.00	✓ 56.00
REAR BOOTLID 'GLS' EMBLEM <i>new</i>	1	40.00	✓ 40.00
REAR BOOTLID 'LOGO' EMBLEM	1	32.00	✓ 32.00
REAR BOOTLID HINGES L/R <i>LH Bent</i>	2	179.00	179 358.00
REAR BOOTLID INNER RUBBER SIDE GUIDE STOPPER L/R <i>new</i>	2	8.00	✓ 16.00
REAR BOOTLID INNER TRIM <i>for</i>	1	279.00	✓ 279.00
REAR BOOTLID LOCK STRIKER <i>new</i>	1	38.00	✓ 38.00
REAR BOOTLID MECHANISM LOCK <i>new</i>	1	155.00	✓ 155.00
REAR BOOTLID REFLECTOR INNER BLACK GASKET L/R <i>LH new</i>	2	22.00	22 44.00
REAR BOOTLID REFLECTOR L/R <i>LH cut</i>	2	368.00	368 736.00
REAR BOOTLID WEATHER STRIP <i>lt</i>	1	92.50	✓ 92.50
REAR BUMPER <i>Dislod</i>	1	520.40	✓ 520.40
REAR BUMPER LH REFLECTOR <i>cut + Missing</i>	1	40.80	✓ 40.80
REAR BUMPER LOWER LID <i>Defect</i>	1	260.00	✓ 260.00
REAR BUMPER REINFORCEMENT <i>Bent</i>	1	303.00	✓ 303.00
REAR BUMPER REINFORCEMENT TOP BRACKET L/R <i>LH Bent</i>	2	18.00	18 36.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	45.00	✓ 90.00

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

MARIAM BEE D/O SHAIK IBRAHIM
 BLK 363 WOODLANDS AVE 5 #05-442
 SINGAPORE 730363

Contact : 94563242, 90250941

ESTIMATE

Repair Code : CLM16363

Date in : 07/08/2020

Vehicle Num. : SGZ214E

Model : HYUNDAI ELANTRA AD 1.6 GLS AT

Chassis/Eng# : KMHD841CMHU133342/G4FGGU150293

REAR BUMPER UNDER COVER LH <i>Rehd</i>	1	78.00	✓	78.00
REAR END PANEL <i>Dented</i>	1	581.00	✓	581.00
REAR END PANEL INNER TOP GARNISH <i>Rehd</i>	1	69.80	✓	69.80
REAR LH FENDER <i>Dishd</i>	1	1768.30	✓	1,768.30
REAR LH FENDER AIR VENT <i>Rehd</i>	1	38.90	✓	38.90
REAR LH FENDER INNER PANEL <i>Repair</i>	1	1406.20	✗	1,406.20
REAR LH FENDER INNER SHIELD <i>torn</i>	1	194.00	✓	194.00
REAR LH FENDER INNER TRIM BOARD <i>Cracked</i>	1	291.00	✓	291.00
REAR SPARE TYRE PANEL <i>Repair</i>	1	878.00	✗	878.00
REAR SPARE TYRE PANEL TOP BOARD COVER <i>Rehd</i>	1	339.00	✓	339.00
REAR TAILLAMP L/R <i>LH cancelled</i>	2	378.00	✓	756.00
<i>Rear Spare Tyre Side Panel LH. 328 ✓</i>				
Subtotal before discount				11,278.90
<i>Dishd</i> Percentage discount 20%				2,255.78
Sub-total 1				9,023.12
REAR BOOTLID INNER TRIM CLIPS - SET <i>new</i>	1	50.00		50.00 <i>30</i>
REAR BOOTLID NUMBER PLATE <i>new</i>	1	25.00		25.00 <i>+</i>
REAR BOOTLID NUMBER PLATE HOLDER <i>new</i>	1	50.00		50.00 <i>+</i>
REAR BUMPER CLIPS - SET <i>new</i>	1	80.00		80.00 <i>30</i>

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

MARIAM BEE D/O SHAIK IBRAHIM
BLK 363 WOODLANDS AVE 5 #05-442
SINGAPORE 730363

Contact : 94563242, 90250941

ESTIMATE

Repair Code : CLM16363

Date in : 07/08/2020

Vehicle Num. : SGZ214E

Model : HYUNDAI ELANTRA AD 1.6 GLS AT

Chassis/Eng# : KMHD841CMHU133342/G4FGGU150293

REAR BUMPER REVERSE SENSOR <i>2and</i>	1	250.00	<i>200</i>	250.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>nu</i>	1	20.00	<i>✓</i>	20.00
REAR LH FENDER INNER SHIELD CLIPS - SET <i>nu</i>	1	30.00	<i>20</i>	30.00
REAR LH FENDER INNER TRIM BOARD CLIPS - SET <i>nu</i>	1	50.00	<i>30</i>	50.00
REAR SPARE TYRE PANEL INSULATOR MAT <i>nu</i>	1	250.00	<i>+</i>	250.00
REAR TAILLAMP CLIPS L/R - SET <i>nu</i>	2	20.00	<i>10</i>	40.00
Subtotal before discount				845.00
Percentage discount 0%				0.00
Sub-total 2				845.00
Parts-total				9,868.12

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	<i>✓</i>	60.00
To remove and refit rear windscreen(to FR)	<i>120</i>	150.00
To remove, reinstall rear suspension and undercarriage part. (to FR)	<i>X</i>	200.00
To road test driving, check and resetting wheel alignments system.	<i>X</i>	120.00
To remove, reinstall petrol tank. (to FR)	<i>80</i>	100.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	<i>80</i>	150.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	<i>1400</i>	1600.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	<i>1800</i>	2500.00

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

MARIAM BEE D/O SHAIK IBRAHIM
BLK 363 WOODLANDS AVE 5 #05-442
SINGAPORE 730363

Contact : 94563242, 90250941

ESTIMATE

Repair Code : CLM16363

Date in : 07/08/2020

Vehicle Num. : SGZ214E

Model : HYUNDAI ELANTRA AD 1.6 GLS AT

Chassis/Eng# : KMHD841CMHU133342/G4FGGU150293

To mount vehicle on to Car 'O' Liner.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall rear camera.

100
50.

Labour Total

Parts & Labour Total

3490

X 300.00

100 120.00

5,300.00

15,168.12

*** This is a computer-generated document which requires no signature.***

page 4

Adrian L
1/2 12/08/20.

10 Days.

Supplementary : 16672

total: 10639.68

W/S: 8.5K.

8.5K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921

Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

MARIAM BEE D/O SHAIK IBRAHIM

BLK 363 WOODLANDS AVE 5

#05-442

SINGAPORE 730363

Repair Code: CLM16363

Date in: 07/08/2020

Vehicle No.: SGZ214E

Model: HYUNDAI ELANTRA AD 1.6 GLS AT

Chassis/Eng#: KMHD841CMHU133342/G4FGGU150293

SUPPLEMENTARY ITEMS

No	Description Of Parts		Qty	Unit Price	Amount
1	REAR LH MUDFLAP <i>10m</i>	L	1	\$ 49.20	\$ 49.20
2	REAR WINDSCREEN GLASS MOULDING <i>new</i>	L	1	\$ 84.20	\$ 84.20
Sub total 1: before discount:					\$ 133.40
Percentage discount 20%:					\$ 26.68
Sub-total 2: after discount:					\$ 106.72
3	REAR WINDSCREEN SEALANT <i>new</i>	S	1	\$ 60.00	\$ 60.00
Sub-total 3 :					\$ 60.00
Parts Total:					\$ 166.72

Supplementary : 166.72