TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit Autohub

2 Kaki Bukit Ave 2, #01-17

Singapore 417921

Tel No.: +65 6744 0510 / 6842 0051 Fax No.: +65 6741 0510

Company Reg. No.: 200714616M GST Registration No.: 200714616M

Our Ref:

SLQ 5017 M

Your ref:

SHB 3063 T

07 August 2020

MS FIRST CAPITAL INSURANCE LIMITED

BY EMAIL MotorClaims@msfirstcapital.com.sg ONLY

6 RAFFLES QUAY #21-00 SINGAPORE 048580

Attn: Motor Claims Department

Dear Sir/Madam,

DATE OF ACCIDENT: 06 Aug 2020

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

PURSUANT TO PARAGRAPH 2.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

We are instructed by TAN KUAN KIAT, KELVIN to notify you of a road traffic accident on 06 Aug 2020 at about 19:30 HRS along TAMPINES AVE 8 / TAMPINES AVE 3 involving our client's vehicle SLQ 5017 M & SHB 3063 T driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be inform that we don't excess to Merimen System and kindly reply to us by Email / Fax.

Yours faithfully,

