

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-50 Singapore 680113
 HP: 8386 8989 EMAIL: atautoconsultant@gmail.com
 Email: atautoconsultant@gmail.com
 Co. Reg. No. : 53368526E

Not Authorized
Clay B7
Resurvey After Paint
5-7 days

Date of Estimate: 10.08.2020
 Vehicle No: SJD5226T
 Owner: VITE MOTORS SINGAPORE LLP
 Date of Accident: 05.08.2020
 Make & Model: Honda Odyssey
 Chassis No : JHMRB18508C203371

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

01/08/20

\$442.00

ESTIMATE FOR ACCIDENT VEHICLE NO SJD5226T

PARTS

- | | | |
|----|---|---|
| 1 | 1 | Taigate |
| 2 | 1 | Tailgate logo |
| 3 | 1 | Tailgate reflector centre |
| 4 | 2 | Tailgate reflector RH/LH |
| 5 | 1 | Tailgate lock |
| 6 | 1 | Tailgate lock striker |
| 7 | 1 | Tailgate inner trim lower garnish |
| 8 | 1 | Tailgate weatherstrip |
| 9 | 1 | Rear bumper |
| 10 | 1 | Rear bumper reflector RH |
| 11 | 2 | Rear bumper retainer RH |
| 12 | 1 | Rear bumper tow cover |
| 13 | 1 | Rear end panel |
| 14 | 1 | Rear end panel top garnish |
| 15 | 1 | Rear end panel top garnish lock striker cover |
| 16 | 1 | Rear end panel top garnish inner cover |
| 17 | 1 | Taillamp RH |
| 18 | 1 | Rear fender RH |
| 19 | 1 | Rear fender inner trim RH |
| 20 | 1 | Exhaust muffler |
| 21 | 1 | Exhaust heat shield |
| 22 | 1 | Rear wheel inner garnish RH |

SUB TOTAL

LESS 20%

DISCOUNTED SUB TOTAL

~~\$183.00~~ ?

n \$1,370.00 *X*
n \$78.00 *✓*
in CNA \$263.00 *X*
n \$884.00 *LT*
n \$216.00 *X*
n \$38.00 *X*
Adlkn \$369.00 *✓*
in \$138.00 *X*
Bur \$1,198.00 *✓*
in \$76.00 *X*
D11 \$113.00 *✓*
in \$45.00 *X*
in \$685.00 *?*
in \$168.00 *X*
in \$33.00 *X*
in \$78.00 *X*
Bur \$899.00 *✓*
in \$1,123.00 *?*
in \$866.00 *X*
in \$1,280.00 *?*
n \$118.00 *X*

\$10,038.00

\$2,356.00

\$7,682.00

S. NETT ITEM

- | | | |
|---|------|-----------------------------------|
| 1 | 1set | Rear bumper clips |
| 2 | 1set | Rear end panel top garnish clips |
| 3 | 1set | 4 pcs Reverse sensor |
| 4 | 1 | Tailgate windscreen sealant |
| 5 | 1 | Rear fender quarter glass sealant |

SUB TOTAL

LESS 0 %

DISCOUNTED SUB TOTAL

n 50.00 *✓*
n 20.00 *X*
Adl 380.00 *320.00*
n 120.00 *40.00*
in 120.00 *?*

\$690.00

\$0.00

\$690.00

LABOUR

- | | |
|---|---|
| 1 | Panel beating for replace and repair affected parts |
| 2 | Spray painting on accident areas |
| 3 | Wiring charges |
| 4 | Remove/refix reverse sensor |
| 5 | Transfer tailgate component |
| 6 | Remove/refix tailgate windscreen glass |
| 7 | Remove/refix rear fender quarter glass |
| 8 | Apply undercoating to above affected areas |

\$1,000.00 *700*
 \$1,200.00 *800*
 \$50.00 *20*
 \$120.00 *60*
 \$250.00 *120*
 \$180.00 *?*
 \$180.00 *?*

\$3,160.00

SUB TOTAL (LABOUR)

Page 1 of 2