

## Shiau Chan (LKKAuto)

---

**From:** Wai Yin Ng <waiyin.ng@transcab.com.sg>  
**Sent:** Wednesday, 16 September 2020 10:25 AM  
**To:** Shiau Chan (LKKAuto)  
**Cc:** Claims  
**Subject:** FW: TP VEHICLE SHD 9596Y / DOA: 06/08/2020 -- AAD2008-036  
**Attachments:** SHD9596Y EST.pdf; IMG\_2186.JPG; IMG\_2189.JPG; IMG\_2187.JPG

[Without prejudice](#)

Dear Shiau Chan

Amount confirmed \$5,099.80 (before GST).

Thank You  
Best Regards,  
**Ng Wai Yin**  
Finance Department  
TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**

TRANS-CAB SERVICES PTE LTD  
No. 2 Ang Mo Kio Street 63  
Singapore 569111  
Tel: 6287 6666 Fax: 6287 7764

---

**From:** Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]  
**Sent:** Wednesday, 16 September, 2020 10:02 AM  
**To:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Subject:** TP VEHICLE SHD 9596Y / DOA: 06/08/2020

Dear Wai Yin,

WITHOUT PREJUDICE

Based on our surveyor's marking estimate, the calculation of repair cost will be at final fig \$5,099.80 before GST and 2 repair days.

Kindly check.

Best Regards,  
**Shiau Chan (Ms)** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)