

DMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA1943Y 07.08.20

Date: 11.08.20

Make : HYUNDAI

Insurance: NTUC

Model : IONIQ(G2)

MVA: LKE

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR LICENCE PLATE LAMP LH			\$60.40
1	REAR LICENCE PLATE LAMP RH			\$60.40
1	REAR BUMPER LOWER CTR MOULDING			\$155.00
1	BOOTLID EMBLEM 'IONIQ'			\$31.30
1	BOOTLID EMBLEM 'HYBRID'			\$24.30
<div> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>				
			988.25	
SUB TOTAL				\$1,264.05
LESS 20%			790.60	\$252.81
DISCOUNTED TOTAL				\$1,011.24
<div> <p>REAR BUMPER RUBBER MAT</p> <p>1 BOOTLID COMFORTDLEGRO LOGO</p> <p>1 BOOTLID TEL. NO STICKER</p> <p>1 REAR BUMPER REVERSE SENSOR</p> <p>Rear number plate \$25 ava ✓</p> <p>Labour Charge</p> <p>PANEL BEATING</p> <p>SPRAY PAINTING CHARGE</p> <p>WIRING CHARGE</p> <p>REMOVE/REFIX REVERSE SENSOR</p> <p>Tariff 57445749</p> <p>wh' 11/8/20 @ 3pm</p> <p>unpsum</p> <p>Resurvey after repair</p> <p>tariff & labour with 2-3 days</p> </div>				
			SN	\$50.00
				\$20.00
			235	\$10.00
			10% - 211.50	\$180.00
			SN-50	\$260.00
			261.50	\$500.00
				\$450.00
			940	\$50.00
				\$120.00
TOTAL LABOUR			1942.10	\$1,120.00
ESTIMATE TOTAL			4581.600	\$2,391.24
			3 days.	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

[illegible]