

Bifrost Auto Pte Ltd

NO.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: 65 64524457 / Fax: +65 64524584

CO. Reg. No.: 201929175W

Model : Honda Civic
Registraion No : SLF 1883 M
Chassis No: JHMFD26408S200138
Year of Manufacturing: 2007

S/No	Qty	Items	Unit Price	Amount
1	1	Rear Bumper / <i>RL</i> RH X NN	\$ 954.20	654
2	2	LHS & RHS Rear Bumper Retainer <i>LL</i> / DE	\$ 35.90	17.95
3	2	LHS & RHS Rear Bumper Bracket X NN	\$ -	-
4	1	End Panel / <i>Buc</i>	\$ 389.40	✓
5	1	End Panel Top Garnish / <i>RL</i>	\$ 59.30	✓
6	1	Boot / <i>ND</i>	\$ 797.20	645.2
7	1	Boot Weather Strip / <i>mis</i>	\$ 101.20	✓
8	2	Boot Hinge X NN	\$ 98.30	X
9	1	Boot Lock / BT	\$ 725.50	194.9
10	1	Boot Lock Catch X NN	\$ 32.30	X
11	1	Boot Insulator X NN	\$ 85.20	X
12	1	Boot Logo	\$ 79.30	36.7
13	1	Boot Emblem "CIVIC" / <i>ABC</i>	\$ 69.70	32.7
14	1	Boot emblem "SI" / <i>ABC</i>	\$ 45.30	31.5
15	1	RHS Boot Reflector / <i>SCR</i>	\$ 489.50	199.8
16	1	LHS Boot Reflector / <i>SCR</i>	\$ 489.50	199.8
17	1	RHS Tail Lamp ✓ CRA	\$ 656.40	299.6
18	1	RHS Tail Lamp Panel X NN	\$ 110.20	X
19	1	LHS Tail Lamp ✓ CRA	\$ 656.40	299.6
20	1	LHS Tail Lamp Panel X NN	\$ 110.20	X
21	1	Spare Tyre Compartment X NN	\$ 992.30	X
22	1	Spare Tyre Compartment Board X NN	\$ 316.50	X
23	1	RHS Rear Fender X NN	\$ 1212.50	X
24	1	RHS Rear Fender Inner Trim Board X NN	\$ 362.80	X
25	1	RHS Rear Fender Shield X NN	\$ 153.20	X
26	1	LHS Rear Fender X NN	\$ 1212.50	X
27	1	LHS Rear Fender Inner Trim Board ✓ <i>TN</i>	\$ 362.80	X
28	1	LHS Rear Fender Shield X NN	\$ 153.20	249.9
				X
				\$ -
				-20% \$ -
				3411.55
				Total for spare parts \$ -
				2729.24

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Special Nett

1	10	Rear Bumper Clip	✓ NEC	\$	5.00	\$	50.00	30
2	10	End Panel Top Garnish Clip	✗ NN	\$	5.00	\$	50.00	✗
3	10	RHS Rear Fender Inner Trim Board Clip	✗ NN	\$	5.00	\$	50.00	✗
4	10	LHS Rear Fender Inner Trim Board Clip	✓ NEC	\$	5.00	\$	50.00	30
5	1	Rear Bumper Diffuser	✓ BR	\$	850.00	\$	850.00	350
6	1 set	Reverse Sensor	✓ DM	\$	350.00	\$	350.00	200
7	1	Rear No. Plate Wirth Casing	✗ NN	\$	50.00	\$	50.00	✗
8	4	Tail Lamp Clip	✗ NN	\$	5.00	\$	20.00	✗
9	1	End Panel Sealant	✗ NN	\$	80.00	\$	80.00	✗
10	1	Boot Spoiler	✗ NN	\$	950.00	\$	950.00	✗

Total for SP \$ 2,500.00 610
Sub-Total for Parts : \$ 2,500.00

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as- mention repair parts, inclusive of replacement parts.	\$	1,500.00 600
2		To putty and spray paint on all accident damage parts and other accident affected areas	\$	1,600.00 800
3		Apply rust proofing on the adjacent panels	\$	50.00 40
4		To supply under coating / putty on parts replaced	\$	50.00 }
5		To perform water seepage test after repair	\$	80.00 ✗ NN
6		To remove and refit bumper reverse sensor	\$	80.00 40
7		To check wiring and lighting system	\$	50.00 30
8		To remove and refit rear end panel lining and garnish to facilitate repair	\$	80.00 60
9		Remove and replace exhaust pipe/system to facilitate repair	\$	80.00 ✗ NN
10		To remove and refir rear windscreen	\$	150.00 ✗ NN

TOTAL AMOUNT : \$ 3,720.00 1570

OVERALL COST: \$ ~~6,220.00~~

14,420.64 ~~13,807.00~~

4909.24

-20%: 3900

5 Days.

Impsum repair ~~10~~

After repair photos.

Gmo Qianf - 8288082

12/8/2020