

Special Nett							
1	10	Rear Bumper Clip	/ <i>mc</i>	\$	5.00	\$	50.00
2	10	End Panel Top Garnish Clip	X	\$	5.00	\$	50.00
3	10	RHS Rear Fender Inner Trim Board Clip	X	\$	5.00	\$	50.00
4	10	LHS Rear Fender Inner Trim Board Clip	/ <i>mc</i>	\$	5.00	\$	50.00
5	1	Rear Bumper Diffuser	/ <i>CRH</i>	\$	850.00	\$	850.00
6	1 set	Reverse Sensor	/ <i>DM</i>	\$	350.00	\$	350.00
7	1	Rear No. Plate Wirh Casing	X	\$	50.00	\$	50.00
8	4	Tail Lamp Clip	X	\$	5.00	\$	20.00
9	1	End Panel Sealant	X	\$	80.00	\$	80.00
10	1	Boot Spoiler	X	\$	950.00	\$	950.00

Total for SP \$ 2,500.00
Sub-Total for Parts : \$ 2,500.00

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as- mention repair parts, inclusive of replacement parts.	\$	1,500.00 <i>600</i>
2		To putty and spray paint on all accident damage parts and other accident affected areas	\$	1,600.00 <i>800</i>
3		Apply rust proofing on the adjacent panels	\$	50.00 <i>40</i>
4		To supply under coating / putty on parts replaced	\$	50.00
5		To perform water seepage test after repair	\$	80.00 <i>X MC</i>
6		To remove and refit bumper reverse sensor	\$	80.00 <i>40</i>
7		To check wiring and lighting system	\$	50.00 <i>30</i>
8		To remove and refit rear end panel lining and garnish to facilitate repair	\$	80.00 <i>60</i>
9		Remove and replace exhaust pipe/system to facilitate repair	\$	80.00 <i>X</i>
10		To remove and refir rear windscreen	\$	150.00 <i>X GMA</i>

TOTAL AMOUNT : \$ 3,720.00
OVERALL COST: \$ 6,220.00

5 Days .

unpsm repair

After repair photos.

GMO Qianf - 8288082

12/8/2020