



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2100854

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 08/02/2021
Reference CC6/CTI20008324/Uea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLH 4602C
Insured Veh. SJK 6370R
Claim No. SNM20D202849
Policy No. DMPCSN3073801901
Accident Date 11/08/2020
Inspection Date 12/08/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI20008324/Uea3q2	
			Date: 08/02/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJK 6370R	Veh. Inspected	SLH 4602C	
Policy No.	DMPCSN3073801901	Coverage (\$)	0.00	
Claim No.	SNM20D202849	Excess (\$)	0.00	
Assign From		Assign Date	12/08/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MR053REH104555340	Colour	GREY	
Odometer	51160 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	MICHELIN	6 mm	
L/H Front Tyre	215/45 R17	MICHELIN	6 mm	
R/H Rear Tyre	215/45 R17	MICHELIN	6 mm	
L/H Rear Tyre	215/45 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/08/2020	Inspection Date	12/08/2020	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 4602C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOTLID	TO REPAIR SEE LABOUR	1,252.10	-
1	BOOTLID REAR LOGO	NECESSARY	68.50	68.50
1	BOOTLID 'COROLLA' EMBLEM	NECESSARY	62.20	62.20
1	BOOTLID 'ALTIS' EMBLEM	NECESSARY	62.50	62.50
2	BOOTLID REFLECTORS @\$328.10	NOT NECESSARY	656.20	-
1	BOOTLID CENTRE GARNISH	NOT NECESSARY	299.80	-
1	BOOTLID INNER LOCK	NOT NECESSARY	391.10	-
1	BOOTLID WEATHERSTRIP	TWISTED	299.80	299.80
1	BOOTLID INNER TRIM	NOT NECESSARY	315.10	-
1	SET BOOTLID INNER TRIM CLIPS	NOT NECESSARY	50.00	-
1	REAR BUMPER	DENTED / DEFORMED	699.50	685.10
2	REAR BUMPER SIDE HOLDERS @\$105.00	BENT	210.00	210.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR BUMPER REINFORCEMENT	DENTED	580.60	472.21
2	REAR BUMPER REFLECTORS @\$95.50	NOT NECESSARY	191.00	-
2	REAR BUMPER PDC SENSORS @\$383.00	SHORTED	766.00	215.00
1	REAR END PANEL	DENTED	988.10	815.10
1	REAR END PANEL TOP GARNISH	TWISTED	435.50	366.50
2	REAR TAILLAMPS @\$688.10	CRACKED	1,376.20	970.20
2	REAR TAILLAMP HOUSING PANELS @\$450.00	TO REPAIR SEE LABOUR	900.00	-
1	REAR FLOOR PANEL	NOT NECESSARY	1,450.10	-
1	REAR FLOOR PANEL TOP BOARD	TORN	899.50	466.10
1	REAR EXHAUST	NOT NECESSARY	899.10	-
2	REAR EXHAUST MOUNTINGS @\$65.00	NOT NECESSARY	130.00	-
1	REAR EXHAUST HEAT SHIELD	NOT NECESSARY	215.10	-
2	REAR FENDERS @\$1455.10	TO REPAIR SEE LABOUR	2,910.20	-
2	REAR FENDER INNER TRIMS @\$488.10	NOT NECESSARY	976.20	-
1	SET REAR FENDER INNER TRIM CLIPS	NOT NECESSARY	50.00	-

Report Ref No. CC6/CTI20008324/Uea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	121.10	-
	LESS 25% DISCOUNT		-	-1,185.80
			17,305.50	3,557.41
	<u>SPECIAL NETT ITEMS</u>			
1	REAR END PANEL SEALANT (SN)	NECESSARY	80.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	50.00	-
1	SET REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	220.00	-
1	REAR LICENCE PLATE W/HOLDER (SN)	NOT NECESSARY	50.00	-
1	REAR REVERSE CAMERA (SN)	NOT NECESSARY	480.00	-
			880.00	50.00
	<u>LABOUR</u>			
	TO CHECK WIRING .		50.00	20.00
	TO DISMANTLE & REPLACING PDC SENSOR .		80.00	50.00
	TO TRANSFER BOOTLID MECHANISM .	NOT NECESSARY	80.00	-
	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY .		150.00	80.00
	TO DISMANTLE & REFIX REAR EXHAUST .	NOT NECESSARY	120.00	-
	TO DISMANTLE & REFIX FUEL TANK .	NOT NECESSARY	100.00	-
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	TO SPRAY RUST PROOFING .		150.00	30.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF BOOTLID ,REAR TAILLAMP HOUSING PANELS AND REAR FENDERS .		1,800.00	600.00
	TO PUTTY & SPRAY PAINTING.		1,680.00	900.00
			4,590.00	1,680.00
GRAND TOTAL			22,775.50	5,287.41
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,200.00

Report Ref No. CC6/CTI20008324/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLH 4602C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLH 4602C

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLH 4602C

RE-INSPECTION

