

(08/11/13) Wef

ASS. REC. BY: Marcus

REF:

CC6/CT120008324/4ea3**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TR / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

1/9/20 1/5 @ 4200 confirmed with Alan.

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) \$ + RS, SI

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

)

FASTECH AUTO PTE LTD  
BLK1 KAKI BUKIT AVE 6  
#01-46,48,50 AUTOBAY  
SINGAPORE 417883

Uchi Ashur

Not Authorized

Uchi  
2/5 @ 4200  
12/8/20

4 days

VEHICLE NO: SLH 4602C

QTY	PARTICULAR		
1 PCS	BOOTLID		\$1,252.10 X
1 PCS	BOOTLID REAR LOGO	R	\$68.50 X
1 PCS	BOOTLID 'COROLLA' EMBLEM	12C	\$62.20 X
1 PCS	BOOTLID 'ALTIS' EMBLEM	12C	\$62.50 X
2 PCS	BOOTLID REFLECTORS @\$328.10	11	\$656.20 X
1 PCS	BOOTLID CENTRE GARNISH	11	\$299.80 X
1 PCS	BOOTLID INNER LOCK	11	\$391.10 X
1 PCS	BOOTLID WEATHERSTRIP	1W1	\$299.80 X
1 PCS	BOOTLID INNER TRIM	11	\$315.10 X
1 SET	BOOTLID INNER TRIM CLIPS	11	\$50.00 X
1 PCS	REAR BUMPER	DD/DE	\$699.50 X
2 PCS	REAR BUMPER SIDE HOLDERS @\$105.00	11	\$210.00 X
1 SET	REAR BUMPER CLIPS	11	\$50.00 X
1 PCS	REAR BUMPER REINFORCEMENT	DD	\$580.60 X
2 PCS	REAR BUMPER REFLECTORS @\$95.50	11	\$191.00 X
2 PCS	REAR BUMPER PDC SENSORS @\$383.00	11	\$766.00 X
1 PCS	REAR END PANEL	DD	\$988.10 X
1 PCS	REAR END PANEL TOP GARNISH	1W1	\$435.50 X
2 PCS	REAR TAILLAMPS @\$688.10	11	\$1,376.20 X
2 PCS	REAR TAILLAMP HOUSING PANELS @\$450.00	11	\$900.00 X
1 PCS	REAR FLOOR PANEL	11	\$1,450.10 X
1 PCS	REAR FLOOR PANEL TOP BOARD	11	\$899.50 X
1 PCS	REAR EXHAUST	11	\$899.10 X
2 PCS	REAR EXHAUST MOUNTINGS @\$65.00	11	\$130.00 X
1 PCS	REAR EXHAUST HEAT SHIELD	11	\$215.10 X
2 PCS	REAR FENDERS @\$1455.10	11	\$2,910.20 X
2 PCS	REAR FENDER INNER TRIMS @\$488.10	11	\$976.20 X
1 SET	REAR FENDER INNER TRIM CLIPS	11	\$50.00 X
1 PCS	REAR WINDSCREEN MOULDING	11	\$121.10 X
			\$17,305.50
	S.NETT		
1 PCS	REAR END PANEL SEALANT	11	\$80.00 X
1 PCS	REAR WINDSCREEN SEALANT	11	\$50.00 X
1 SET	REAR FLOOR PANEL INSULATOR	11	\$220.00 X
1 PCS	REAR LICENCE PLATE W/HOLDER	11	\$50.00 X
1 PCS	REAR REVERSE CAMERA	11	\$480.00 X

LABOUR CHARGES:

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACING PDC SENSOR	\$80.00	50
TO TRANSFER BOOTLID MECHANISM	\$80.00	X
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY	\$150.00	80
TO DISMANTLE & REFIX REAR EXHAUST	\$120.00	X
TO DISMANTLE & REFIX FUEL TANK	\$100.00	X
TO MOUNT VEHICLE ON CAR O-LINER	\$380.00	X

TO SPRAY RUST PROOFING  
LABOUR FOR PANEL BEATING & REPLACING PARTS  
TO PUTTY & SPRAY PAINTING

	\$150.00	30
	\$1,800.00	600
	\$1,680.00	900
TOTAL	\$22,775.50	

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-4743.21  
252  
P-3557.60  
S.V-50.00  
L-1680.00  
5287.4  
201  
4229