

ASS. REG. BY:

Steve

REF:

CC4/111 2000 8327 / E6a3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SMR 3768A

Yr Regn:

31/12/19

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius Plus

c.c

1798

Colour:

Blk

A/C: Insured / Std / NI / NA

Sp. Reading

540/2

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTD2SJE4X 0751997

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Westlake

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

9/8/20

D.O.I.

12/8/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV- 107K

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Rep. Format:

Lump Sum / L.B.:



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date:

10/8/2020

Vehicle:

SMR3768A

Make / Model:

TOYOTA PRIUS

Chassis No:

JTDZS3EU90J038190

No.	Description	Unit	Unit Price	Amount
	Parts Replacement:			
1	FRONT BUMPER / DEF	1	\$ 570.00	\$ 570.00
2	FRONT BUMPER LOGO / NPC	1	\$ 189.00	\$ 189.00
3	FRONT BUMPER FOGLAMP RH / CUT	1	\$ 435.00	\$ 435.00
4	FRONT BUMPER TOP GRILLE / (RH) / CUT	1	\$ 145.00	\$ 145.00
5	FRONT BUMPER GRILLE BASE / CUT	1	\$ 296.00	\$ 296.00
6	FRONT BUMPER TOP RUBBER X	1	\$ 48.00	\$ 48.00
7	FRONT BUMPER TOP BEAM X	1	\$ 415.00	\$ 415.00
8	FRONT BUMPER LOWER ABSORBER X	1	\$ 235.00	\$ 235.00
9	FRONT BUMPER LOWER GRILLE X	1	\$ 186.00	\$ 186.00
10	FRONT BUMPER UNDER GARNISH X	1	\$ 298.00	\$ 298.00
11	FRONT BUMPER SIDE RETAINER / BR	2	\$ 58.00	\$ 118.00
12	FRONT BUMPER REINFORCEMENT X	1	\$ 459.00	\$ 459.00
13	FRONT BUMPER TOWING COVER X	1	\$ 68.00	\$ 68.00
14	FRONT BUMPER SPONGE X	1	\$ 119.00	\$ 119.00
15	FRONT BUMPER LOWER X		\$ 415.00	\$ 415.00
16	FRONT FENDER RH X R	1	\$ 985.00	\$ 985.00
17	FRONT FENDER EMBLEM 'HYBRID' / NPC	1	\$ 65.00	\$ 65.00
18	FRONT FENDER INNER COWLING RH X	1	\$ 135.00	\$ 135.00
19	FRONT FENDER GARNISH RH X	1	\$ 64.00	\$ 64.00
20	HEADLAMP RH / CUT	1	\$ 1,487.00	\$ 1,487.00
21	FRONT SUPPORT PANEL X	1	\$ 468.00	\$ 468.00
22	FRONT SUPPORT LOWER PANEL X	1	\$ 544.00	\$ 544.00
23	FRONT SUPPORT TOP GARNISH X	1	\$ 289.00	\$ 289.00
24	AIR GUARD RH X	1	\$ 71.00	\$ 71.00
25	FRONT KNUCKLE ARM RH X	1	\$ 821.00	\$ 821.00
26	FRONT KNUCKLE ARM BEARING RH X	1	\$ 165.00	\$ 165.00
27	FRONT SHOCK ABSORBER RH X	1	\$ 651.00	\$ 651.00
28	FRONT LOWER ARM RH X	1	\$ 628.00	\$ 628.00
29	STABILIZER LINK RH X	1	\$ 198.00	\$ 198.00
30	STEERING TIE ROD RH X	1	\$ 211.40	\$ 211.40
				\$ 10,778.40
			Less 25%	\$ 2,694.60
			Total	\$ 8,083.80
	S/Nett items:			
1	FRONT GRILLE CLIPS X	1 SET	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP / NPC	1 SET	\$ 80.00	\$ 80.00
3	FRONT SPORTS RIM RH X	1	\$ 800.00	\$ 800.00
4	FRONT TYRE RH X	1	\$ 250.00	\$ 250.00

5	FRONT FENDER SEALANT RH X	1	\$ 150.00	\$ 150.00	
6	MISCELLANEOUS X	1	\$ 200.00	\$ 200.00	
				\$ 1,530.00	
	Labour to:				
1	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00	409
2	PANEL BEATING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00	250
3	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00	30
4	REMOVE AND REFIX FRONT UNDERCARRIAGE	1	\$ 450.00	\$ 450.00	X
5	REALIGN HEADLAMP	1	\$ 120.00	\$ 120.00	30
6	CHECK AND TEST FOR WATER LEAKAGE	1	\$ 50.00	\$ 50.00	X
7	CHECK AND RESET FAULT CODE LIGHT ON	1	\$ 250.00	\$ 250.00	X
8	CONDUCT WHEEL ALIGNMENT	1	\$ 120.00	\$ 120.00	X
9	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 120.00	\$ 120.00	X
				\$ 2,790.00	
			Parts Replacement Amount	\$ 9,613.80	
			Total Amount for Labour	\$ 2,790.00	
			Total Amount	\$ 12,403.80	

Steve (LKK) ML ML
 12/8/20, 2.00pm
 3 dy
 Ry AL Ry
 L/S

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: