

A.S. REC. BY:

Steve

REF:

CC4/111 2000 8327 / E6a3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Toyota Prius PLUS

C.C.

1798

Colour

Blk

A/C: Insured / Std / NI / NA

Sp. Reading

540/2

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

JTD2SJEU X 07951997

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

R: _____

205/60R16

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

R/Bal. _____

5

mm

L/Bal. _____

5

mm

D.O.A. _____

9/8/20

Survey held at

My car

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV- 107K

17/8/20 Final \$2450 - 3 days (Hai Qia)

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Rep. Format: _____

Lump Sum / I.B.I. / C

☐ : Preli. Report☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date:

10/8/2020

Vehicle:

SMR3768A

Make / Model:

TOYOTA PRIUS

Chassis No:

JTDZS3EU90J038190

No.	Description	Unit	Unit Price	Amount
	Parts Replacement:			
1	FRONT BUMPER / DEF	1	\$ 570.00	\$ 570.00
2	FRONT BUMPER LOGO / NPC	1	\$ 189.00	\$ 189.00
3	FRONT BUMPER FOGLAMP RH / CUT	1	\$ 435.00	\$ 435.00
4	FRONT BUMPER TOP GRILLE / CRH / CUT	1	\$ 145.00	\$ 145.00
5	FRONT BUMPER GRILLE BASE / CUT	1	\$ 296.00	\$ 296.00
6	FRONT BUMPER TOP RUBBER X NM	1	\$ 48.00	\$ 48.00
7	FRONT BUMPER TOP BEAM X NM	1	\$ 415.00	\$ 415.00
8	FRONT BUMPER LOWER ABSORBER X NM	1	\$ 235.00	\$ 235.00
9	FRONT BUMPER LOWER GRILLE X NM	1	\$ 186.00	\$ 186.00
10	FRONT BUMPER UNDER GARNISH X NM	1	\$ 298.00	\$ 298.00
11	FRONT BUMPER SIDE RETAINER / BR	2	\$ 58.00	\$ 118.00
12	FRONT BUMPER REINFORCEMENT X NM	1	\$ 459.00	\$ 459.00
13	FRONT BUMPER TOWING COVER X NM	1	\$ 68.00	\$ 68.00
14	FRONT BUMPER SPONGE X NM	1	\$ 119.00	\$ 119.00
15	FRONT BUMPER LOWER X NM	1	\$ 415.00	\$ 415.00
16	FRONT FENDER RH X R	1	\$ 985.00	\$ 985.00
17	FRONT FENDER EMBLEM 'HYBRID' X NPC	1	\$ 65.00	\$ 65.00
18	FRONT FENDER INNER COWLING RH X NM	1	\$ 135.00	\$ 135.00
19	FRONT FENDER GARNISH RH X NM	1	\$ 64.00	\$ 64.00
20	HEADLAMP RH / CUT	1	\$ 1,487.00	\$ 1,487.00
21	FRONT SUPPORT PANEL X NM	1	\$ 468.00	\$ 468.00
22	FRONT SUPPORT LOWER PANEL X NM	1	\$ 544.00	\$ 544.00
23	FRONT SUPPORT TOP GARNISH X NM	1	\$ 289.00	\$ 289.00
24	AIR GUARD RH X NM	1	\$ 71.00	\$ 71.00
25	FRONT KNUCKLE ARM RH X NM	1	\$ 821.00	\$ 821.00
26	FRONT KNUCKLE ARM BEARING RH X NM	1	\$ 165.00	\$ 165.00
27	FRONT SHOCK ABSORBER RH X NM	1	\$ 651.00	\$ 651.00
28	FRONT LOWER ARM RH X NM	1	\$ 628.00	\$ 628.00
29	STABILIZER LINK RH X NM	1	\$ 198.00	\$ 198.00
30	STEERING TIE ROD RH X NM	1	\$ 211.40	\$ 211.40
				\$ 10,778.40
			Less 25%	\$ 2,694.60
			Total	\$ 8,083.80
	S/Nett items:			
1	FRONT GRILLE CLIPS X NM	1 SET	\$ 50.00	\$ 50.00
2	FRONT REAR BUMPER CLIP / NPC	1 SET	\$ 80.00	\$ 80.00
3	FRONT SPORTS RIM RH X NM	1	\$ 800.00	\$ 800.00
4	FRONT TYRE RH X NM	1	\$ 250.00	\$ 250.00

72-10 /
62 /

3195-10
-25%
2328-82 /

30

5	FRONT FENDER SEALANT RH <i>X</i> <i>NNI</i>	1	\$ 150.00	\$ 150.00
6	MISCELLANEOUS <i>X</i> <i>NNI</i>	1	\$ 200.00	\$ 200.00
				\$ 1,530.00
	Labour to:			
1	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
2	PANEL BEATING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
3	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
4	REMOVE AND REFIX FRONT UNDERCARRIAGE	1	\$ 450.00	\$ 450.00
5	REALIGN HEADLAMP	1	\$ 120.00	\$ 120.00
6	CHECK AND TEST FOR WATER LEAKAGE	1	\$ 50.00	\$ 50.00
7	CHECK AND RESET FAULT CODE LIGHT ON	1	\$ 250.00	\$ 250.00
8	CONDUCT WHEEL ALIGNMENT	1	\$ 120.00	\$ 120.00
9	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 120.00	\$ 120.00
				\$ 2,790.00
			Parts Replacement Amount	\$ 9,613.80
			Total Amount for Labour	\$ 2,790.00
			Total Amount	\$ 12,403.80

Steve (LKK) ML ML
12/8/20, 2:00pm
3 dy
Ry AL Ry
L/S

P-2328-82
N-30
L-710
3068-82

L/S - 2455.05
= 2450

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: