

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd
Date: 12/08/2020
Attn: MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLB4299B
CHASSIS NO : NSP1707012916
MAKE / MODEL : Toyota Sienta 1.5G CVT
DATE OF ACCIDENT : 29/06/2020
YOUR INSURED VEHICLE NUMBER : SKP48185
MILEAGE : 293853 km

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PARTS DESCRIPTION		QTY	UNIT PRICE	LIST PRICE
1	Rear tailgate / DD	1PC	\$ 1,879.00	\$ 1,879.00 / 120
2	Rear tailgate weatherstrip XSV	1PC	\$ 432.00	\$ 432.00 X
3	Rear tailgate Toyota logo / Nec	1PC	\$ 60.00	\$ 60.00
4	Rear bumper center pad / S.C.R. \$240	1PC	\$ 64.80	\$ 64.80 255
LIST TOTAL S\$:				\$ 2,435.80 1,435
25.00% DISCOUNT S\$:				\$ 608.95 256
				\$ 1,826.85 1,076.25
SPECIAL NETT				
1	Bumper clips XSV	1 SET	\$	80.00
2	Reverse sensor XSV	1 SET	\$	260.00
3	Windscreen sealant / Nec	1PC	\$	100.00 30
Special Nett Total S\$:				\$ 440.00 30
LABOUR CHARGES				
1	To labour charge for removing rear tailgate and rear bumper out to facilitate replacement of parts		\$ 600.00	250 400
2	To respray rear bumper, tailgate and end panel		\$ 800.00	400
3	To remove and install rear tailgate glass		\$ 120.00	✓
3	Transfer tailgate mechanism		\$ 100.00	60
LABOUR TOTAL S\$:				\$ 1,620.00 980
TOTAL S\$:				\$ 3,886.85
7% GST				\$ 272.08
GRAND TOTAL S\$:				\$ 4,158.93

Repair day - 3 days

L/S

After paint photo

Sun Pin (L/R)

12/08/2020

TP without prejudice.

215
\$1,650
3 days

P = 1,076.25

N = 30

L = 980

2,086.25

- 20%

1,669