

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Steve (LKK) Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

13/8/20, 11.30 am

ESTIMATE OF REPAIR

Veh# : SMD3160B

WHL PL

Model:

NISSAN NOTE

Accident Date : 12/8/2020

P/P, Ry Bel SM, 14 days

(14/8/2018)

Location : DAIRY FARM SLIP ROAD/ EXIT BKE

3P:



SME3732S(AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear bumper / DD	-	-	681.40
2	10pcs	Rear bumper clips / MC	-	60.00	31
3	1pc	Rear bumper sponge ? / BR	-	-	210.00
4	2pcs	Rear bumper screw clips / MC	-	20.00	18
5	2pcs	Rear bumper o/s & n/s reflector ? / BR	-	-	244.20
6	2pcs	Rear bumper o/s & n/s retainer (Inner) ? / BR	-	-	190.60
7	2pcs	Rear bumper o/s & n/s retainer (Outer) ? (Back) / BT	-	-	210.20
8	1pc	Rear buzzer ? / BR	-	-	265.40
9	1pc	Rear reverse sensor / BR	-	280.00	299
10	1pc	Rear end panel / DD	-	-	681.90
11	1pc	Rear end panel inner trim ? / CRH	-	-	183.50
12	4pcs	Rear end panel inner trim clips ? / MC	-	16.00	10
13	2pcs	Rear o/s & n/s tail-lamp ? / BR	-	-	1,178.20
14	2pcs	Rear o/s & n/s tail-lamp panel ? / DD	-	-	663.80
15	1pc	Rear Regn. No. Plate lamp X	-	-	167.50
16	1pc	Rear boot cover / DD	-	-	1,474.40
17	1pc	Rear boot cover weatherstrip ? / CRH	-	-	240.50
18	1pc	Rear boot cover emblem / MC	-	-	81.60
19	1pc	Rear boot cover 'NOTE' emblem / MC	-	-	71.70
20	1pc	Rear boot cover inner trim ? / BR	-	-	356.60
21	11pcs	Rear boot cover inner trim clips ? / MC	-	44.00	15
22	2pcs	Rear boot cover o/s & n/s hinges X	-	-	160.00
23	1pc	Rear boot cover moulding ? X	-	-	287.10
24	4pcs	Rear boot cover moulding clips ? X	-	16.00	-
25	1pc	Rear boot cover lock (Upper) ? / BT	-	-	291.60
26	1pc	Rear boot cover lock (Lower) X	-	-	43.10
27	1pc	Rear boot floor panel ? / DD	-	-	1,318.75
28	1pc	Rear boot floor panel insulator ? / MC	-	-	374.40
29	12 pcs	Rear boot floor o/s & n/s corner panel ? (LH) / BT	-	-	463.80
30	1pc	Rear n/s chassis frame ? / DD	-	-	355.20
31	1pc	Rear n/s fender X R	-	-	-
32	1pc	Rear n/s fender wheel guard ? / TN	-	-	163.80
33	6 pcs	Rear n/s fender wheel guard clips ? / MC	-	24.00	15
34	1pc	Rear n/s fender inner trim ? / DEF	-	-	423.20

35	8 pcs	Rear n/s fender inner trim clips	/ APC	32.00	15	-
36	1pc	Rear n/s fender air vent	? / BR	-	-	165.60
37	1 pc	Rear windscreen sealant	/ M	80.00	-	-
38	1 pc	Rear windscreen inner seal	/ APC	160.00	-	-
39	1 pc	Rear regn. no. plate	/ (H)	45.00	49	-
40	1 pc	Rear regn. no. plate bracket	X	29.00	-	-
41	1 pc	Front bumper	/ BR	-	-	796.70
42	10 pcs	Front bumper clips	/ APC	30.00	-	-
43	1 pc	Front bumper enforcement	? X	-	-	596.70
44	1 pc	Front bumper n/s retainer	/ BR	-	-	86.70
45	1 pc	Front bumper top garnish	? / BR	-	-	213.20
46	1 pc	Front grille base	? / BR	-	-	321.20
47	1 pc	Front grille emblem	/ APC	-	-	91.70
48	6 pcs	Front grille clips	/ APC	24.00	12	-
49	1 pc	Front grill chrome	/ BR	-	-	362.60
50	1 pc	Front n/s head-lamp	/ BR	-	-	896.80
Sub-Total:				0.00	860.00	14,313.65
				30%	0%	10%
After Less %:				0.00	860.00	12882.29
Labour						
1		To dismantle, straighten, welding & replace rear damage parts.		1,600.00	1400	
2		To spray painting.		1,400.00	/	
3		To re-align rear n/s chassis		200.00	100	
4		To remove & refit rear seat, roof lining.		160.00	80	
5		To remove & replace rear windscreen.		160.00	120	
6		To check wiring.		100.00	30	
7		To re-set electrical system.		480.00	30	
8		To re-seal anti-rust.		200.00	50	
Sub-Total:				4,300.00		
Total:				18,042.29		

Chan

Chan San Choon
Director
DipEng. AAE MIMI,MSAE(Aust)



bizSAFE
S T R

AL 8778 1999
24 hr accident call

Mobil 1



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SMD3160B ESTIMATEPg2