

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Steve (LKK)

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

13/8/20, 11.30 am

ESTIMATE OF REPAIR

Veh# : SMD3160B

WHL PL

Model:

NISSAN NOTE

(14/8/2018)

Accident Date : 12/8/2020

P/P, Ry Bel smy, 14 days

Location : DAIRY FARM SLIP ROAD/ EXIT BKE

3P:

SME3732S(AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear bumper / DD	-	-	681.40
2	10pcs	Rear bumper clips - MC	-	60.00	30
3	1pc	Rear bumper sponge ? - BR	-	-	210.00
4	2pcs	Rear bumper screw clips - MC	-	20.00	10
5	2pcs	Rear bumper o/s & n/s reflector ? / BR 1pc - 76	-	-	244.20
6	2pcs	Rear bumper o/s & n/s retainer (Inner) ? / BR 1pc - 69	-	-	190.60
7	2pcs	Rear bumper o/s & n/s retainer (Outer) ? (Back) - BT	-	-	210.20
8	1pc	Rear buzzel ? / BR	-	-	265.40
9	1pc	Rear reverse sensor - BR	-	280.00	200
10	1pc	Rear end panel / DD	-	-	681.90
11	1pc	Rear end panel inner trim ? / CRU	-	-	183.50
12	4pcs	Rear end panel inner trim clips ? / MC	-	16.00	10
13	2pcs	Rear o/s & n/s tail-lamp ? / BR 1pc - 435	-	-	1,178.20
14	2pcs	Rear o/s & n/s tail-lamp panel ? / DD 1pc - 185	-	-	663.80
15	1pc	Rear Regn. No. Plate lamp X A/N	-	-	167.50
16	1pc	Rear boot cover / DD	-	-	1,474.40
17	1pc	Rear boot cover weatherstrip ? / CRU	-	-	240.50
18	1pc	Rear boot cover emblem - MC	-	-	81.60
19	1pc	Rear boot cover 'NOTE' emblem - MC	-	-	71.70
20	1pc	Rear boot cover inner trim ? / BR	-	-	356.60
21	11pcs	Rear boot cover inner trim clips ? / MC	-	44.00	15
22	2pcs	Rear boot cover o/s & n/s hinges X A/N	-	-	160.00
23	1pc	Rear boot cover moulding ? X A/N	-	-	287.10
24	4pcs	Rear boot cover moulding clips ? X A/N	-	16.00	-
25	1pc	Rear boot cover lock (Upper) ? / BT	-	-	291.60
26	1pc	Rear boot cover lock (Lower) X A/N	-	-	43.10
27	1pc	Rear boot floor panel ? / DD	-	-	1,318.75
28	1pc	Rear boot floor panel insulator ? / MC	-	-	374.40
29	12 pcs	Rear boot floor o/s & n/s corner panel ? (LH) - BT X R	-	-	463.80
30	1pc	Rear n/s chassis frame ? / DD	-	-	355.20
31	1pc	Rear n/s fender X R	-	-	-
32	1pc	Rear n/s fender wheel guard ? / TN	-	-	163.80
33	6 pcs	Rear n/s fender wheel guard clips ? / MC	-	24.00	15
34	1pc	Rear n/s fender inner trim ? / DEF	-	-	423.20

35	8 pcs	Rear n/s fender inner trim clips	/ MPC	-	32.00	15	-	(NPT)
36	1pc	Rear n/s fender air vent	? / BR	-	-	165.60	-	55 (list)
37	1 pc	Rear windscreen sealant	/ MPC	-	80.00	60	-	(NPT)
38	1 pc	Rear windscreen inner seal	/ MPC	-	160.00	-	-	80 (list)
39	1 pc	Rear regn. no. plate	/ CUT	-	45.00	40	-	(NPT)
40	1 pc	Rear regn. no. plate bracket	X NN	-	29.00	-	-	X
41	1 pc	Front bumper	/ BR	-	-	796.70	-	394 (list)
42	10 pcs	Front bumper clips	/ MPC	-	30.00	-	-	(NPT)
43	1 pc	Front bumper enforcement	? X NN	-	-	596.70	-	X
44	1 pc	Front bumper n/s retainer	/ BR	-	-	86.70	-	/ (list)
45	1 pc	Front bumper top garnish	? / BR	-	-	213.20	-	194 (list)
46	1 pc	Front grille base	? / BR	-	-	321.20	-	/ (list)
47	1 pc	Front grille emblem	/ MPC	-	-	91.70	-	70 (list)
48	6 pcs	Front grille clips	/ MPC	-	24.00	12	-	(NPT)
49	1 pc	Front grill chrome	/ BR C/w grille assy	-	-	362.60	-	X
50	1 pc	Front n/s head-lamp	/ BR	-	-	896.80	-	796 (list)
Sub-Total:				0.00	860.00	14,313.65	-	
				30%	0%	10%	-	
After Less %:				0.00	860.00	12882.29	-	
Labour								
1		To dismantle, straighten, welding & replace rear damage parts.			1,600.00	1400	-	
2		To spray painting.			1,400.00	/	-	
3		To re-align rear n/s chassis			200.00	100	-	
4		To remove & refit rear seat, roof lining.			160.00	80	-	
5		To remove & replace rear windscreen.			160.00	120	-	
6		To check wiring.			100.00	30	-	
7		To re-set electrical system.			480.00	30	-	
8		To re-seal anti-rust.			200.00	50	-	
Sub-Total:					4,300.00		-	
Total:					18,042.29		-	

List - 9073
- 10%
8165-70

Nett - 635

Labour - 3219

Chan San Choon
Director
DipEng, AAE MIMI, MSAE (Aust)

12,010.70

= 12,010.70



AL 8778 1999
24 hr accident call



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Supplementary - 1410.43

= 13,421.13

13,421.13 P/P

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# : SMD3160B

Model:

NISSAN NOTE

Accident Date : 12/8/2020

(14/8/2018)

Location : DAIRY FARM SLIP ROAD/ EXIT BKE

3P:

SME3732S(AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Front n/s support panel garnish / DEF	-	-	86.50
2	1pc	Front n/s chassis (outer portion) / DD	-	-	210.20
3	1pc	Front n/s chassis (outer portion) bracket / DD	-	-	265.00
4	1pc	Rear o/s fender inner trim / DEF	-	-	423.20
5	1pc	Rear boot floor panel DD Repeated Item 27	-	-	880.60
6	1pc	Rear spare tyre sponge / BR	-	-	285.60
7	1pc	Rear boot cover handle / BR	-	-	96.50
Sub-Total:			0.00	0.00	2,247.60
			30%	0%	10%
After Less %:			0.00	0.00	2022.84
Labour					
1		To dismantle, straighten, welding & replace front damage parts.		400.00	200
2		To spray paint front damage parts.		400.00	200
Sub-Total:				800.00	
Total:				2,822.84	

68 (114)
/ (114)
180 (114)
398 (114)
X
170 (114)
/ (114)

Chan San Choon

Director
DipEng, AAE MIMI,MSAE(Aust)

Steve 18/8/20

List - 1122-79
- 1970
1,010-43

labour - 400
= 1,410-43



8778 1999
24 hr accident call

Mobil 1

