

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 81A**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

12 AUG 2020

**SHD 81A**

VF1ABL15AUC283395

RENAULT

LATITUDE

10.8.2020

**TOKIO MARINE**

24/07/2017

	<b>PART</b>
1	BUMPER COVER REAR
1	BUMPER LOWER REAR
1	BUMPER BRACKET CTR REAR
1	BUMPER BRACKET SIDE RH REAR
1	BUMPER RETAINER RH REAR
1	BUMPER REFLECTOR REAR
1	BUMPER BRACKET SIDE LH REAR
1	BUMPER RETAINER LH REAR
1	BUMPER BEAM REAR
1	BUMPER BEAM BRACKET LH REAR
1	BUMPER BEAM BRACKET RH REAR
1	OUTER PANEL REAR (End Panel)
1	OUTER PANEL REAR (End Panel) TRIM
1	TAIL-LAMP
1	BOOT REAR
1	BOOT WEATHERSTRIP
1	BOOT REFLECTOR LAMP
1	BOOT BADGE 'RENAULT'
1	BOOT BADGE
1	EXHAUST CAP REAR

	<b>LIST</b>	
\$	CM	561.70 ✓
\$	nd/hn	411.90 ✓
\$	Sh	98.10
\$	Sh	82.10
\$	Sh	59.80
\$	Sh	16.60
\$	Sh	80.80
\$	Sh	54.20
\$	R	547.80
\$	R	114.50
\$	R	114.50
\$	R	745.80
\$	Sh	404.56
\$	Sh	401.40
\$	R	1,677.20
\$	Sh	178.20
\$	Sh	277.70
\$	nn	82.40
\$	nn	95.80
\$	Sh	125.40

<b>TOTAL</b>	\$	<b>6,130.46</b>
<b>10%</b>	\$	<b>613.05</b>
	\$	<b>5,517.41</b>

**Special Nett**

1SET PARKING AID

1SET REAR BUMPER CLIP

1SET BUMPER BRACKET CTR CLIP

\$	Sh	700.00 X
\$	nn	75.00
\$	nn	55.00 X

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 81A****AAD2008-040**

1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn	60.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	nn	65.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	nn	60.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	nn	65.00	X
1SET BUMPER LOWER REAR RIVET	\$	nn	69.00	X
1SET BUMPER LOWER REAR CLIP	\$	nn	75.00	X
1 BOOT STICKER "Trans-cab"	\$	nn	80.00	X
1 BOOT STICKER "6555-3333"	\$	nn	80.00	X
1 TAILLAMP CLIP	\$	nn	45.00	X
1 Rear Bumper Protector	\$	nn	170.00	3000
1 REAR LICENCE PLATE WITH HOLDER	\$	nn	120.00	X
1 REAR END PANEL TRIM CLIP	\$	nn	55.00	X
<b>TOTAL</b>	<b>\$</b>		<b>1,774.00</b>	

**TOTAL PARTS \$ 7,291.41****LABOUR**

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	100
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn	250.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn	380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		2,000.00	2000
Putty and spray painting of the affected portion.	\$		2,000.00	2200

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 81A****AAD2008-040**

To transfer of rear bumper fittings, attachment and perform water seepage test.

\$ *nn* 170.00 *X*

To reinstall rear bumper parking sensor.

\$ 170.00 *601*

To repair and realign rear exhaust pipe.

\$ *nn* 170.00 *X***TOTAL** \$ **5,860.00****Over All Total** \$ **13,151.41****LUMP SUM ( REPAIR DAY)**~~20 DAYS~~*2 days***For Official Use**Prepared By : \_\_\_\_\_  
(Accident Dept)Verify By : \_\_\_\_\_  
(Accident Workshop)Checked By : \_\_\_\_\_  
(Finance Dept)LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: