

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO : AXA

DATE : 11/08/2020

ATTENTION : MOTOR CLAIMS DEPT

JOB TYPE : T/P CLAIM

ESTIMATE REPORT :

VEHICLE DETAILS

VEHICLE NO : SFD89C

MODEL : HONDA STREAM 1.8A

CHASSIS NO

ACCIDENT DETAILS

DATE : 9-Jul-20

TIME : 18:00HRS

THIRD PARTY REQUESTOR / CONTACT : JACK LI

X 140 Tony

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR RH <i>Dented</i>	1	\$ 1,130.50	\$ 1,130.50
2	REAR DOOR RH <i>Repair</i>	1	\$ 1,035.20	\$ 1,035.20

1130.50

984.40

TOTAL PRICE

LESS 20%

SUB TOTAL PRICE

\$ 2,165.70

\$ 433.14

\$ 1,732.56

CLAIM DETAILS: LABOUR AND SPRAY PAINTING ( FRONT)

1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,000.00	400
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	600
3	TUFF COAT	\$ 250.00	40
4	WIRING AND BULB CHECKING	\$ 80.00	X
5	REMOVE AND REFIX FRONT & REAR DOOR MECHANISM	\$ 240.00	80

TOTAL

\$ 2,570.00

TOTAL

\$2,570.00

1120

## ESTIMATE REPORT

TOTAL PARTS COST : \$ 1,732.56  
TOTAL LABOUR COST : \$ 5,140.00  
TOTAL REPAIR COST : \$ 6,872.56

### APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian Lj

L/S 12/08/20

03 Days.

total: 2024.40

L/S 1.6K. ✓

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: