

(08/11/13) Wef

ASS. REC. BY: Marcus

REF:

CC4 / FC120008355/4K53

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SFX 99964

at Workshop m/s

Rico 60

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value:

45k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

att 18647

COR 15-12-2028 27A 26353

2/9/20 2/5 7200 confirmed with John

Veh No:

SFX 99964

Yr Regn:

1208

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CM

Make:

Honda civic

c.c

1799

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp.Reading

159817

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMF153095200076

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

7/8/20

D.O.I.

13/8/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS. SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



Rico 60 Auto Services Pte Ltd. Blk 8, Kaki Bukit Avenue 4, #02-24  
Premier @ Kaki Bukit Singapore 415875, Email: claims@rico60.com  
Tel: 6286 6060, FAX: 6286 7060

VEHICLE NUM:  
MAKE & MODEL:  
MILEAGE:  
TYRE:  
CHASSIS NUM:

SFX 9996 U  
HONDA CIVIC

Not Authorized  
13/8/20  
2/s \$7200

Like: Khneaduna

1/s \$7200

12 days

| ATTN | NO. | DESCRIPTION - PARTS                | QTY | PRICE     |
|------|-----|------------------------------------|-----|-----------|
|      | 1   | REAR WINDSCREEN MOULDING           | 1   | \$312.00  |
|      | 2   | BOOTLID                            | 1   | \$1269.00 |
|      | 3   | BOOTLID LOGO (HONDA)               | 1   | \$95.00   |
|      | 4   | BOOTLID EMBLEM (CIVIC)             | 1   | \$91.00   |
|      | 5   | BOOTLID EMBLEM (1.8)               | 1   | \$87.00   |
|      | 6   | BOOTLID EMBLEM (1.7VTEC)           | 1   | \$89.00   |
|      | 7   | BOOTLID LAMP (L+R)                 | 2   | \$1150.00 |
|      | 8   | BOOTLID HANDLE                     | 1   | \$311.00  |
|      | 9   | BOOTLID LOCK CYLINDER              | 1   | \$298.00  |
|      | 10  | BOOTLID CARPLATE LAMP (L+R)        | 2   | \$180.00  |
|      | 11  | BOOTLID INNER TRIM                 | 1   | \$345.00  |
|      | 12  | BOOTLID LOCK                       | 1   | \$372.00  |
|      | 13  | BOOTLID LOCK CATCH                 | 1   | \$97.00   |
|      | 14  | BOOTLID HINGE (L+R)                | 2   | \$345.00  |
|      | 15  | BOOTLID HINGE COVER (L+R)          | 2   | NIL       |
|      | 16  | BOOTLID STOPPER (L+R)              | 2   | \$40.00   |
|      | 17  | BOOTLID WEATHERSTRIP               | 1   | \$325.00  |
|      | 18  | TAIL LAMP (L+R)                    | 2   | \$1452.00 |
|      | 19  | TAIL LAMP BRACKET (L+R)            | 2   | \$362.00  |
|      | 20  | TAIL LAMP PANEL (L+R)              | 2   | \$798.00  |
|      | 21  | REAR BUMPER                        | 1   | \$1072.00 |
|      | 22  | REAR BUMPER RETAINER (L+R)         | 2   | \$294.00  |
|      | 23  | REAR BUMPER REINFORCEMENT BAR      | 1   | NIL       |
|      | 24  | REAR BUMPER BRACKET (L+R)          | 2   | NIL       |
|      | 25  | REAR BUMPER BEAM                   | 1   | NIL       |
|      | 26  | REAR BUMPER SPONGE                 | 1   | NIL       |
|      | 27  | REAR BUMPER REVERSE SENSOR SET     | 4   | \$1896.00 |
|      | 28  | REAR BUMPER UNDERCOVER             | 1   | \$521.00  |
|      | 29  | REAR FENDER (L+R)                  | 2   | \$5446.00 |
|      | 30  | REAR FENDER INNER TRIM (L+R)       | 2   | \$1786.00 |
|      | 31  | REAR FENDER COWLING (L+R)          | 2   | \$457.00  |
|      | 32  | REAR FENDER AIR VENT (L+R)         | 2   | \$330.00  |
|      | 33  | END PANEL                          | 1   | \$1020.00 |
|      | 34  | END PANEL TOP GARNISH              | 1   | \$471.00  |
|      | 35  | REAR SMART LOCK ANTENNA            | 1   | NIL       |
|      | 36  | SPAREWHEEL PANEL                   | 1   | \$1353.00 |
|      | 37  | SPAREWHEEL PANEL TOP BOARD         | 1   | \$651.00  |
|      | 38  | SPAREWHEEL PANEL TOP BOARD TOP MAT | 1   | NIL       |
|      | 39  | SPAREWHEEL PANEL TOOLBOX (L+R)     | 2   | NIL       |



|                                                                       |                                                                |             |       |             |
|-----------------------------------------------------------------------|----------------------------------------------------------------|-------------|-------|-------------|
|                                                                       |                                                                | SUBTOTAL    | \$    | -           |
| P: \$13,378.00                                                        |                                                                | LESS 20%    | \$    | -           |
| 20% = \$10,702.40                                                     |                                                                | PARTS TOTAL | \$    | -           |
| SPECIAL NETT                                                          |                                                                |             | QTY   | PRICE       |
| 1                                                                     | REAR WINDSCREEN SEALANT 11X                                    | 1           | \$    | 200.00 X    |
| 2                                                                     | BOOTLID INNER TRIM CLIPS nu 30                                 | 10          | \$    | 100.00 30   |
| 3                                                                     | REAR CARPLATE                                                  | 1           | \$    | 120.00      |
| 4                                                                     | REAR CARPLATE FRAME > Bent 40                                  | 1           | \$    | 120.00 >40  |
| 5                                                                     | TAIL LAMP CLIPS 11X                                            | 8           | \$    | 80.00 X     |
| 6                                                                     | TAIL LAMP SEALANT 11X                                          | 2           | \$    | 300.00 X    |
| 7                                                                     | REAR BUMPER CLIPS nu 30                                        | 10          | \$    | 100.00 30   |
| 8                                                                     | REAR FENDER SEALANT 11X                                        | 2           | \$    | 500.00 X    |
| 9                                                                     | REAR FENDER INNER TRIM CLIPS 11X                               | 20          | \$    | 200.00 X    |
| 10                                                                    | REAR FENDER COWLING CLIPS 11X                                  | 20          | \$    | 200.00 X    |
| 11                                                                    | REAR FENDER MUDFLAP CLIPS 11X                                  | 4           | \$    | 80.00 X     |
| 12                                                                    | END PANEL SEALANT nu 50                                        | 1           | \$    | 200.00 50   |
| 13                                                                    | END PANEL TOP GARNISH CLIPS 11X                                | 10          | \$    | 100.00 X    |
| 14                                                                    | SPAREWHEEL PANEL SEALANT 11X                                   | 1           | \$    | 300.00 X    |
| 15                                                                    | EXHAUST PIPE RX                                                | 1           | \$    | 6,000.00 X  |
| 16                                                                    | EXHAUST GASKET nu X QN: 1880                                   | 1           | \$    | 250.00 X    |
| 17                                                                    | EXHAUST BRACKET (L+R) 11X                                      | 2           | \$    | 400.00 X    |
| 18                                                                    | EXHAUST HEAT SHIELD Bent 120                                   | 1           | \$    | 450.00 120  |
| 19                                                                    | EXHAUST CHROME TIP SET PD 80.5. ~                              | 2           | \$    | 4,000.00 80 |
| Rear bumper Reverse Sensor Set (Refer to parts no. 27) \$2000 Repetix |                                                                |             |       |             |
| SPECIAL NETT TOTAL                                                    |                                                                |             | \$    | 13,700.00   |
| LABOUR                                                                |                                                                | QTY         | PRICE |             |
| 1                                                                     | TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN 1800     | 1           | \$    | 3,600.00    |
| 2                                                                     | TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA 1100               | 1           | \$    | 3,000.00    |
| 3                                                                     | TO RUST PROOF ACCIDENT AFFECTED AREA 100                       | 1           | \$    | 600.00      |
| 4                                                                     | TO RNR REAR WINDSCREEN 11X                                     | 1           | \$    | 400.00 X    |
| 5                                                                     | TO RNR REAR BOOT MECHANISM 60                                  | 1           | \$    | 400.00      |
| 6                                                                     | TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS 80             | 1           | \$    | 600.00      |
| 7                                                                     | TO RNR REVERSE SENSOR & CHECK FUNCTION. 50 400                 | 1           | \$    | 150.00      |
| 8                                                                     | TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS 60                  | 1           | \$    | 350.00      |
| 9                                                                     | TO CHECK WIRING LAYOUT AND BOOTLID LAMP FUNCTION 11X           | 1           | \$    | 150.00 X    |
| 10                                                                    | TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION 20               | 1           | \$    | 150.00      |
| 11                                                                    | TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE. 11X | 1           | \$    | 800.00 X    |
| 12                                                                    | TO DO WATER LEAK TEST. 11X                                     | 1           | \$    | 100.00 X    |
| 13                                                                    | TO RNR FUEL TANK TO ASSIST WORK LOAD 60                        | 1           | \$    | 350.00      |
| TOTAL                                                                 |                                                                |             | \$    | 10,650.00   |
| GRAND TOTAL COST                                                      |                                                                |             | \$    | 24,350.00   |
| 3080                                                                  |                                                                |             |       |             |

P- 5089.92

S.N- 600

L- 3330

9019.92

20  
72/5



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24  
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com  
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:  
MAKE & MODEL:  
MILEAGE:  
TYRE:  
CHASSIS NUM:

|             |
|-------------|
| SFX 9996 U  |
| HONDA CIVIC |
|             |
|             |
|             |

ATTN: [ ]

68.20  
280.00  
285.00

| NO.                | DESCRIPTION - PARTS                                       | QTY      | PRICE     |
|--------------------|-----------------------------------------------------------|----------|-----------|
| 1                  | REAR FENDER SIDE AIR VENT (L+R) <i>msene 1pc</i>          | 2        | \$330.00  |
| 1                  | SPAREWHEEL PANEL SIDE PANEL (L+R) <i>ms sel 1pc</i>       | 1        | \$1504.00 |
| 2                  | SPAREWHEEL PANEL SIDE INNER PANEL (L+R) <i>ms sel 1pc</i> | 1        | \$1278.00 |
| 3                  | REAR AXLE <i>17X</i>                                      | 1        | \$2410.00 |
| 4                  | REAR CHASSIS (LH) <i>2X</i>                               | 1        | REPAIR    |
| P: \$1556          |                                                           | SUBTOTAL | \$ -      |
| -20% = \$1244.80   |                                                           | LESS 20% | \$ -      |
| PARTS TOTAL        |                                                           |          | \$ -      |
| SPECIAL NETT       |                                                           | QTY      | PRICE     |
| 1                  | SPAREWHEEL PANEL SIDE PANEL SEALANT <i>ms 50</i>          | 2        | \$ 400.00 |
| 2                  | SPAREWHEEL PANEL SIDE INNER PANEL SEALANT <i>17X</i>      | 2        | \$ 400.00 |
| 2/2: \$50          |                                                           |          |           |
| SPECIAL NETT TOTAL |                                                           |          | \$ 800.00 |
| LABOUR             |                                                           | QTY      | PRICE     |
| 1                  | TO RNR UNDERCARRIAGE SYSTEM <i>17X</i>                    | 1        | \$ 250.00 |
| 2                  | TO CHECK WHEEL ALIGNMENT <i>17X</i>                       | 1        | \$ 250.00 |
| TOTAL              |                                                           |          |           |
| GRAND TOTAL COST   |                                                           |          |           |

1pc  
1pc  
1pc  
X  
X

P: \$11,947.20  
SN: \$930  
L: \$0930  
Total: \$15,807.20  
-20% = \$12,650

P-6362-4  
508992

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: