



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SFX 9996 U
HONDA CIVIC

Not Authorized
13/8/20
The photo of the repair
2/5

12 days.

ATTN:			
NO.	DESCRIPTION - PARTS	QTY	PRICE
1	REAR WINDSCREEN MOULDING 14 X	1	
2	BOOTLID 3u1 ✓	1	
3	BOOTLID LOGO (HONDA) ne ✓	1	
4	BOOTLID EMBLEM (CIVIC) ne ✓	1	
5	BOOTLID EMBLEM (1.8) ne ✓	1	
6	BOOTLID EMBLEM (i.VTEC) ne ✓	1	
7	BOOTLID LAMP (L+R) en ✓	2	
8	BOOTLID HANDLE 17 X	1	
9	BOOTLID LOCK CYLINDER ?	1	
10	BOOTLID CARPLATE LAMP (L+R) 17 X	2	
11	BOOTLID INNER TRIM ?	1	
12	BOOTLID LOCK Tw ✓	1	
13	BOOTLID LOCK CATCH 17 X	1	
14	BOOTLID HINGE (L+R) 17 X	2	
15	BOOTLID HINGE COVER (L+R) 17 X	2	
16	BOOTLID STOPPER (L+R) 17 X	2	
17	BOOTLID WEATHERSTRIP Tw ✓	1	
18	TAIL LAMP (L+R) en ✓	2	
19	TAIL LAMP BRACKET (L+R) ?	2	
20	TAIL LAMP PANEL (L+R) ?	2	
21	REAR BUMPER 17.5 ✓	1	
22	REAR BUMPER RETAINER (L+R) 31 ✓	2	
23	REAR BUMPER REINFORCEMENT BAR NSX	1	
24	REAR BUMPER BRACKET (L+R) NSX	2	
25	REAR BUMPER BEAM NSX	1	
26	REAR BUMPER SPONGE NSX	1	
27	REAR BUMPER REVERSE SENSOR SET Sheld 200 S-N	4	
28	REAR BUMPER UNDERCOVER NSX	1	
29	REAR FENDER (L+R) 12 X	2	
30	REAR FENDER INNER TRIM (L+R) ?	2	
31	REAR FENDER COWLING (L+R) 17 X	2	
32	REAR FENDER AIR VENT (L+R) 17 X	2	
33	END PANEL 3.5500 ✓	1	
34	END PANEL TOP GARNISH 721 ✓	1	
35	REAR SMART LOCK ANTENNA NSX	1	
36	SPAREWHEEL PANEL crumpled/warped ✓	1	
37	SPAREWHEEL PANEL TOP BOARD Tw ✓	1	
38	SPAREWHEEL PANEL TOP BOARD TOP MAT NSX	1	
39	SPAREWHEEL PANEL TOOLBOX (L+R) NSX	2	

		SUBTOTAL	\$	-
		LESS 20%	\$	-
		PARTS TOTAL	\$	-
	SPECIAL NETT	QTY	PRICE	
1	REAR WINDSCREEN SEALANT 11X	1	\$	200.00
2	BOOTLID INNER TRIM CLIPS nu 30	10	\$	100.00
3	REAR CARPLATE 3 Serf 40	1	\$	120.00
4	REAR CARPLATE FRAME	1	\$	120.00
5	TAIL LAMP CLIPS 11X	8	\$	80.00
6	TAIL LAMP SEALANT 11X	2	\$	300.00
7	REAR BUMPER CLIPS nu 30	10	\$	100.00
8	REAR FENDER SEALANT 11X	2	\$	500.00
9	REAR FENDER INNER TRIM CLIPS 11X	20	\$	200.00
10	REAR FENDER COWLING CLIPS 11X	20	\$	200.00
11	REAR FENDER MUDFLAP CLIPS 11X	4	\$	80.00
12	END PANEL SEALANT nu 50	1	\$	200.00
13	END PANEL TOP GARNISH CLIPS 11X	10	\$	100.00
14	SPAREWHEEL PANEL SEALANT 11X	1	\$	300.00
15	EXHAUST PIPE ?	1	\$	6,000.00
16	EXHAUST GASKET ?	1	\$	250.00
17	EXHAUST BRACKET (L+R) 11X	2	\$	400.00
18	EXHAUST HEAT SHIELD ?	1	\$	450.00
19	EXHAUST CHROME TIP SET ?	2	\$	4,000.00
		SPECIAL NETT TOTAL	\$	13,700.00
	LABOUR	QTY	PRICE	
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN 1400	1	\$	3,600.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA 1100	1	\$	3,000.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA 100	1	\$	600.00
4	TO RNR REAR WINDSCREEN 11X	1	\$	400.00
5	TO RNR REAR BOOT MECHANISM 60	1	\$	400.00
6	TO RNR UPHOLSTERY,GARNISH AND ATTACHMENT PARTS 80	1	\$	600.00
7	TO RNR REVERSE SENSOR & CHECK FUNCTION. 50	1	\$	150.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS 60	1	\$	350.00
9	TO CHECK WIRING LAYOUT AND BOOTLID LAMP FUNCTION 11X	1	\$	150.00
10	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION 20	1	\$	150.00
11	TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE. 11X	1	\$	800.00
12	TO DO WATER LEAK TEST . 11X	1	\$	100.00
13	TO RNR FUEL TANK TO ASSIST WORK LOAD 60	1	\$	350.00
		TOTAL	\$	10,650.00
		GRAND TOTAL COST	\$	24,350.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: