

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sundari Nagarajan

Date: 14 Aug 2020

Preliminary Advice

Vehicle No	: GBH153B	Accident Date	: 08/08/2020
Make	: NISSAN CABSTAR	Policy No.	: D19MFL0005549
Assignment Date	: 13/08/2020	Excess	: S\$0.00
Date of Inspection	: 13/08/2020	Est. Duration of Repair	: 18 Days
Inspection At	: Efficient Motor & Engineering Works Pte Ltd (HQ) 56 Loyang Way #06-07, Loyang Enterprise Building Singapore 508775		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the front o/s & o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,166.90
Revised Amount	:S\$	15,582.40
Check Items (Estimated)	:S\$	9,839.50
Total	:S\$	25,421.90

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	51,000.00
COE / PARF Rebate	:S\$	41,166.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,834.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck. Vehicle recommended total loss.
- () Other comments : We are still pending repair cost from repairer.