

Steve (CLKK) ML PL
14/8/20, 12.00pm
4 days

Bifrost Auto Pte Ltd

NO.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: 65 64524457 / Fax: +65 64524584

CO. Reg. No.: 201929175W

Model : Honda Vezel 1.5X CVT

Registration No : SMP 5476 P

Chassis No: RU11313714

Year of Manufacturing: 2018

S/No	Qty	Items	Unit Price	Amount
1	1	Tailgate / <i>DD</i>	\$ 1,195.30	\$ 1,195.30 <i>1100 ✓</i>
2	1	RHS Tailgate Hinge <i>X N/A</i>	\$ 89.50	\$ 89.50 <i>X</i>
3	1	LHS Tailgate Hinge <i>X N/A</i>	\$ 89.50	\$ 89.50 <i>X</i>
4	1	RHS Tailgate Damper <i>X N/A</i>	\$ 210.20	\$ 210.20 <i>X</i>
5	1	LHS Tailgate Damper <i>X N/A</i>	\$ 210.20	\$ 210.20 <i>X</i>
6	1	Tailgate Lock / <i>DT</i>	\$ 257.50	\$ 257.50 <i>204.10 ✓</i>
7	1	Tailgate lock Switch <i>X N/A</i>	\$ 187.50	\$ 187.50 <i>X</i>
8	1	Tailgate Weather Strip <i>X N/A</i>	\$ 185.20	\$ 185.20 <i>X</i>
9	1	Tailgate Inner Trim Board <i>? / BR</i>	\$ 296.30	\$ 296.30 <i>/</i>
10	1	Tailgate Logo <i>X N/A</i>	\$ 82.50	\$ 82.50 <i>X</i>
11	1	Tailgate Emblem "Vezel" / <i>MP</i>	\$ 75.20	\$ 75.20 <i>/</i>
12	1	RHS Tailgate Reflector <i>X ? / BR</i>	\$ 318.40	\$ 318.40 <i>/</i>
13	1	LHS Tailgate Reflector <i>X N/A</i>	\$ 318.40	\$ 318.40 <i>X</i>
14	1	Rear Windscreen Moulding / <i>MP</i>	\$ 198.70	\$ 198.70 <i>/</i>
15	1	Rear Bumper / <i>DD</i>	\$ 995.40	\$ 995.40 <i>762 ✓</i>
16	1	RHS Rear Bumper <i>? / CRV</i>	\$ 385.60	\$ 385.60 <i>282 ✓</i>
17	1	LHS Rear Bumper <i>X N/A</i>	\$ 385.60	\$ 385.60 <i>X</i>
18	1	RHS Rear Bumper Reflector <i>? / BR</i>	\$ 196.60	\$ 196.60 <i>151 ✓</i>
19	1	LHS Rear Bumper Reflector <i>X N/A</i>	\$ 196.60	\$ 196.60 <i>X</i>
20	1	RHS Rear Bumper Bracket / <i>BR</i>	\$ 45.10	\$ 45.10 <i>/</i>
21	1	LHS Rear Bumper Bracket / <i>BR</i>	\$ 45.10	\$ 45.10 <i>/</i>
22	1	Rear Bumper Under Cover <i>? / BR</i>	\$ 282.70	\$ 282.70 <i>/</i>
23	1	Smart Buzzer <i>? / BR</i>	\$ 115.40	\$ 115.40 <i>/</i>
24	1	License Garnish Chrome <i>X N/A</i>	\$ 89.70	\$ 89.70 <i>X</i>
25	1	End Panel <i>X R</i>	\$ 699.80	\$ 699.80 <i>X</i>
26	1	End Panel Top Garnish <i>X N/A</i>	\$ 149.90	\$ 149.90 <i>X</i>
27	1	Spare Tyre Compartment <i>X N/A</i>	\$ 789.40	\$ 789.40 <i>X</i>
28	1	Spare Tyre Panel Board <i>X N/A</i>	\$ 257.80	\$ 257.80 <i>X</i>
29	1	Sponge Tool Box <i>X N/A</i>	\$ 325.60	\$ 325.60 <i>X</i>
30	1	RHS Tail Lamp <i>X N/A</i>	\$ 378.40	\$ 378.40 <i>X</i>
31	1	LHS Tail Lamp <i>X N/A</i>	\$ 378.40	\$ 378.40 <i>X</i>
32	1	Exhaust Pipe <i>X N/A</i>	\$ 979.10	\$ 979.10 <i>X</i>
33	2	Exhaust Mounting <i>X N/A</i>	\$ 49.80	\$ 99.60 <i>X</i>
34	1	Exhaust Pipe Gasket <i>X N/A</i>	\$ 68.90	\$ 68.90 <i>X</i>
35	1	RHS Rear Fender Inner Trim Board <i>X N/A</i>	\$ 358.70	\$ 358.70 <i>X</i>
36	1	LHS Rear Fender Inner Trim Board <i>X N/A</i>	\$ 358.70	\$ 358.70 <i>X</i>
			\$	11,296.50
			-20%	\$ 2,259.30
			Total for spare parts	\$ 9,037.20

3876
-20%
3100.80

Special Nett

1	1	Rear Bumper Diffuser X / BR	\$	680.00	\$	680.00	600
2	1	Rear Bumper Sticker / MC	\$	87.00	\$	87.00	50
3	1 set	Rear Bumper Reverse Sensor / BR	\$	380.00	\$	380.00	200
4	10	Rear Bumper Clip / MC	\$	5.00	\$	50.00	30
5	10	RHS Rear Fender Inner Trim Board Clip X NAI	\$	5.00	\$	50.00	X
6	10	LHS Rear Fender Inner Trim Board Clip X NAI	\$	5.00	\$	50.00	X
7	10	End Panel Top Garnish Clip X NAI	\$	5.00	\$	50.00	X
8	10	Tailgate Inner Trim Board Clip X / MC	\$	5.00	\$	50.00	15
9	1 set	Tail Lamp Clip X NAI	\$	30.00	\$	30.00	X
10	1	Rear Windscreen Tinted X NAI	\$	280.00	\$	280.00	X
11	1	End Panel Scalant X NAI	\$	80.00	\$	80.00	X
12	1	Rear Windscreen Sealant X NAI	\$	80.00	\$	80.00	X
13	1	Rear No. Plate With Casing X NAI	\$	50.00	\$	50.00	X
Total for SP				\$	1,917.00		
Sub-Total for Parts :				\$	10,954.20		895

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as- mention repair parts, inclusive of replacement parts.	\$	1,200.00 600
2		To putty and spray paint on all accident damage parts and other accident affected areas	\$	1,100.00 500
3		Apply rust proofing on the adjacent panels	\$	50.00 30
4		To supply under coating / putty on parts replaced	\$	50.00 X
5		To perform water seepage test after repair	\$	80.00 30
6		To remove and refit bumper reverse sensor	\$	80.00 30
7		To check wiring and lighting system	\$	50.00 30
8		To remove and refit rear windscreen	\$	150.00 120
9		To remove and refit rear luggage compartment	\$	80.00 30
10		Remove rear view camera re-align camera	\$	80.00 30
11		To remove and refit rear end panel lining and garnish to facilitate repair	\$	80.00 30
12		Remove and refit exhaust pipr/system to facilitate repair	\$	80.00 X

P-3199-80
 NI-895
 L-1430
 5425-80
 L/S-4349-64
 = 4350

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL AMOUNT : \$ 3,080.00
 OVERALL COST : \$ 14,034.20

1430