

ASS. REC. BY:

REF:

C72/20008369/Kg

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

14 days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 Got BE

14/08/20@9.50am revised to Irene Tay via Merimen.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: China Taiping Insurance (S) Pte Ltd

Accident Date : 07.08.2020

Not Authorised
Resurvey B4 paint
18 days

Policy No: _____
Third Party
Date: 11.08.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Honda Civic" Reg. No. SCY332A Claiming Against Your Insured Veh. No. SMJ199D		
1pc	Boot		531.20
1pc	Boot Outer Garnish		110.90
1pc	Boot Emblem		138.00
1pc	Boot Badge Civic		21.50
1pc	Boot Badge iVTEC		20.60
1pc	Boot Weatherstrip		70.40
1pc	Boot Trim Board Clips	3.50	52.50
15pcs	Boot Lock		81.20
1pc	Boot Stopper LH		9.50
1pc	Rear Bumper	3.50	617.50
10pcs	Rear Bumper Clips		35.00
1pc	Rear Bumper Bracket LH		12.40
1pc	Rear Bumper Top Retainer LH		25.40
1pc	Rear Bumper Center Diffuser Cover		260.30
1pc	Rear Bumper Tow Point Cover		18.70
1pc	Rear Bumper Reflector LH		17.20
1pc	Rear Bumper Reflector Cover		25.40
1pc	Rear Bumper Reverse Sensors	133.90	267.80
2pcs	Rear Bumper Reverse Sensor Holder	57.20	228.80
4pcs	Rear Bumper Reverse Sensor Wiring Harness		135.00
1pc	Rear Bumper Inner Boot Sensor		58.10
1pc	Rear Bumper Inner Boot Sensor Buzzer		80.20
1pc	Rear Bumper Corner Retainer		25.40
1pc	Rear Bumper Reinforcement		160.40
1pc	Taillamp LH		285.40
1pc	Taillamp Gasket		25.00
1pc	Taillamp Panel		58.90
1pc	End Panel		265.40
1pc	End Panel Garnish		50.30
1pc	Rear Fender Trim Board LH		182.40
1pc	Rear Fender Splash Shield LH		63.20
1pc	Spare Tyre Top Board		295.40
1pc	Spare Tyre Panel		895.00
1pc	Bonnet		654.10
2pcs	Bonnet Hinge	42.80	85.60
1pc	Bonnet Lock		85.40
4pcs	Bonnet Insulator Clips	3.50	14.00
1pc	Bonnet Lower Air Scoop		80.20
		C/F	6,043.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

To: China Taiping Insurance (S) Pte Ltd

Policy No: _____ Third Party

Date: _____ 11.08.2020

Accident Date : 07.08.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Honda Civic" Reg. No. SCY332A Claiming Against Your Insured Veh. No. SMJ199D			
		B/F	6,043.70
1pc	Front Bumper	3.80	CM 632.00 ✓
1pc	Front Bumper Clips	26.70	RM 38.00 ✓
2pcs	Front Bumper Brackets		53.40 ✓
1pc	Front Bumper Reinforcement		369.00 ✓
1pc	Front Bumper Top Beam	21.00	DIT 246.00 ✓
2pcs	Front Bumper Top Retainers		CM 42.00 ✓
1pc	Front Bumper Side Cover RH		CM 42.00 ✓
1pc	Front Bumper Center Air Grille		DI 47.00 ✓
1pc	Front Bumper Corner Retainer RH		DI 21.00 ✓
1pc	Front Bumper Inner Ambience Sensor		106.00 ✓
1pc	Front Bumper Top Rubber Seal		RM 28.00 ✓
1pc	Front Bumper Core		395.00 ✓
2pcs	Horn	614.00	SM 62.00 X
1pc	Headlamps	101.00	1,228.00 ✓
2pcs	Headlamp Top Chrome Mouldings	47.00	202.00 ✓
1pc	Headlamp Top Chrome Moulding Retainers		94.00 ✓
1pc	Support Panel		AT 602.00 ✓
8pcs	Support Panel Top Garnish	3.50	CM 29.00 ✓
1pc	Support Panel Top Garnish Clips		RM 28.00 ✓
1pc	Support Panel Sticker		RM 42.00 ✓
1pc	Air Con Condenser		RM 739.00 ✓
1pc	Air Con Condenser Side Air Guide RH		62.00 ✓
1pc	Air Con Condenser Liquid Pipe		72.00 ✓
1pc	Air Con Condenser Discharge Hose		83.00 ✓
1pc	Radiator		1,155.00 ✓
1pc	Radiator Lower Carrier		194.00 ✓
1pc	Radiator Fan Assy		SM 1,004.00 X
1pc	Front Fender RH		RM 472.00 ✓
1pc	Front Fender Signal Lamp		MSM 54.80 ✓
1pc	Front Grille		CM 133.00 ✓
1pc	Front Grille Top Rubber Seal		RM 38.50 ✓
1pc	Front Grille Garnish		CM 28.70 ✓
1pc	Front Grille Emblem		RM 27.00 ✓
Less 20%			14,413.10
			2,882.62
			11,530.48
		C/F	11,530.48

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: China Taiping Insurance (S) Pte Ltd

Accident Date : 07.08.2020

Third Party

Policy No: _____

11.08.2020

Date: _____

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Honda Civic" Reg. No. SCY332A Claiming Against Your Insured Veh. No. SMJ199D		11,530.48
	To Dismantle / Transfer Boot Fittings / Ancillary Accessories	B/F	80.00 501
	To Conduct Rear Electrical Check, Replace Back Up Sensor, Reprogram System		180.00 601
	To Dismantle / Refit Trunk Compartment Boards & Trims		m 80.00 X
	To Supply Rear Body Panel Joint Sealant		100.00 301
	To Conduct Water Test Leak		30.00 201
	To Conduct Front Electrical Check, Focus Headlamp		30.00 201
	To Remove / Refit Air Con Condenser & Refill Air Con Gas		120.00 1001
	To Remove / Refit, Radiator System, Bleed, Refill Coolant		120.00 501
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		200.00 1201
	Labour Charge - Panel Beating, Repairing Of Rear Chassis Member Inner Panel, Boot Hinge, Floor Panel, Rear N/S Fender, Front Chassis Member, Front Inner Panel etc. Cnt, Weld Support, End Panel, Spare Tyre Panel And Part Replacement		2,500.00 15001
	To Respray Affected Areas		1,900.00 16001
	Total :		16,870.48



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 07/08/2020 13:59
Date Of Accident 07/08/2020 07:40
Exact Location Of Accident KRANJI EXPRESSWAY
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SCY332A
Insured/Policyholder
Name Of Registered Owner MRS ANG GAKE MOY NEE LEOW GAKE MOY @WEE GAKE MOY
NRIC No SXXXX196F
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-96229380
Alternative Phone No OTHERS-96229380

Vehicle Particulars

Manufacturer HONDA
Model CIVIC 1.6 VTI CVT
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5114597488
Cover Note Number

Driver

Name of Driver ANG CHUI LING, AILEEN(HONG CUILING, AILLEN)
NRIC No SXXXX372A
Date Of Birth 11/07/1978
Occupation INDOOR
Date Of Driving Pass 27/03/1998
Driving Experience 22 YEARS AND 4 MONTHS
Gender FEMALE
Mobile Number (LOCAL) +65-96229380
Fax Number
Contact Number
EMail Address AILEEN.AA@GMAIL.COM

Address APT BLK 264 WATERLOO STREET
 #11-207
 Postcode 180264
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured CHILDREN
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 4
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name 10 UBI AVENUE 3
 Police Station Address ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT NO.T/20200807/7009

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number 6MJ199D
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SKG4473A

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

FV272U

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

MOTORCYCLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

ANG SHUI LING, AILEEN(HONG CUILING, AILEEN)

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SCY332A

Were seat belts worn?


Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report no. T/20200807/7009

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____

10/22/2016 6:26:47 PM

Driver's signature
(If driver is not the policyholder)
Date & Time:

Data & Times:

Reporting Centre Personnel's Signature
Name:
NRIC/EIN No.:

NRIC/JIN No. 3