



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2008144
INV Date 07/12/2020
Reference CC6/LPC20008371/Upa3q2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SLN 279Y
Insured Veh. XD 7622D
Claim No. 19/20/20/VC05/023532
Policy No. Z19VC05003405
Accident Date 11/08/2020
Inspection Date 13/08/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC6/LPC20008371/Upa3q2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 07-12-2020	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 7622D	Veh. Inspected	SLN 279Y	
Policy No.	Z19VC05003405	Coverage (\$)	0.00	
Claim No.	19/20/20/VC05/023532	Excess (\$)	0.00	
Assign From		Assign Date	13/08/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA SIENTA (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	MHFZ28H3900028253	Colour	BROWN	
Odometer	107885	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/50 R16	FALKEN	6 mm	
L/H Front Tyre	195/50 R16	FALKEN	6 mm	
R/H Rear Tyre	195/50 R16	FALKEN	6 mm	
L/H Rear Tyre	195/50 R16	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/08/2020	Inspection Date	13/08/2020	
Survey held at	TAN LIM MOTOR PTE LTD NO.1 DEFU LANE 6 SINGAPORE 539365			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 279Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE LID	BADLY DENTED / TWISTED	1,100.00	1,100.00
1	TAILGATE LID REFLECTOR O/S	NOT NECESSARY	242.00	-
1	TAILGATE LID OUTER CHROME MOULDING	NOT NECESSARY	245.00	-
1	TAILGATE LID SIENTA EMBLEM BADGE	NECESSARY	55.00	55.00
1	TAILGATE LID V EMBLEM BADGE	SERVICEABLE	52.70	-
1	TAILGATE LID TOYOTA LOGO	NECESSARY	72.20	72.20
2	TAILGATE LID HINGES @\$65.00	TWISTED	130.00	130.00
2	TAILGATE LID DAMPER @\$235.00	NOT NECESSARY	470.00	-
1	TAILGATE LID BRACKET	NOT NECESSARY	39.80	-
1	TAILGATE LID STOPPER RUBBER O/S	NOT NECESSARY	12.60	-
1	TAILGATE LID STOPPER	NOT NECESSARY	18.60	-
1	TAILGATE LID INNER TRIMBOARD	NOT NECESSARY	445.00	-
13	TAILGATE LID INNER TRIMBOARD CLIPS @\$4.30	NOT NECESSARY	55.90	-
1	REAR BUMPER (DENTED)	NOT CONSISTENT WITH THE IMPACT	577.80	-
	LESS 25% DISCOUNT		-879.15	-339.30
			2,637.45	1,017.90
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR WINDSCREEN PRIMER (SN)	NECESSARY	40.00	20.00
			120.00	60.00
<u>LABOUR</u>				
	TO TRANSFER OF TAILGATE FITTINGS, FIXTURE AND PERFORM WATERSEEPAGE TEST.		120.00	60.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		100.00	20.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		120.00	30.00
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	NOT NECESSARY	80.00	-
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.		1,200.00	300.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,200.00	400.00
	TO DISMANTLE AND REFIT REAR SEAT,BACKREST,TRIMMING,GARNISH,ROOF-LINING,SPEAKER SHELFBOARD,CARPETING AND OTHER TO ENABLE BODY WORK REPAIR.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMMINGS,GARNISH AND OTHER,TO ENABLE REPAIR.		120.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		120.00	120.00
			3,210.00	990.00
GRAND TOTAL			5,967.45	2,067.90

RECOMMENDED COST OF REPAIRS				2,067.90
-----------------------------	--	--	--	----------

Report Ref No. CC6/LPC20008371/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLN 279Y

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLN 279Y

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLN 279Y

RE-INSPECTION

