

Lonpac Insured's Veh No : XD7622D
Date of Accident : 11 August 2020

not Authorized
Hh
4/5
4 days
13/8/20
take photo before repair.



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Mr Ja'amat Bin Hj Ab Karim @ Mohammad Jamil Bin Hj Ab Ka

Date : 18 August 2020

p/p 2067-90

Estimate To Repair SLN279Y - Toyota SIENTA 1.5G CVT ABS D/AIRBAG
Chassis No : MHFZ28H3900028253

S/No	Quantity	Description	Amount	
		<u>LIST ITEMS</u>		
01	1 pc	tailgate lid <i>bodywork</i>	\$ 1,100.00	✓
02	1 pc	tailgate lid reflector o/s <i>11</i>	\$ 242.00	X
03	1 pc	tailgate lid outer chrome moulding <i>11</i>	\$ 245.00	X
04	1 pc	tailgate lid Sienta emblem badge <i>new</i>	\$ 55.00	✓
05	1 pc	tailgate lid V emblem badge <i>SVL</i>	\$ 52.70	X
06	1 pc	tailgate lid Toyota logo <i>new</i>	\$ 72.20	✓
07	2 ps	tailgate lid hinges @ \$65.00 <i>7m</i>	\$ 130.00	✓
08	2 ps	tailgate lid damper @ \$235.00 <i>11</i>	\$ 470.00	X
09	1 pc	tailgate lid bracket <i>11</i>	\$ 39.80	X
10	1 pc	tailgate lid stopper rubber o/s <i>11</i>	\$ 12.60	X
11	1 pc	tailgate lid stopper <i>11</i>	\$ 18.60	X
12	1 pc	tailgate lid inner trimboard <i>11</i>	\$ 445.00	X
13	13 ps	tailgate lid inner trimboard clips @ \$4.30 <i>11</i>	\$ 55.90	X
14	1 pc	rear bumper <i>DO 1/c</i>	\$ 577.80	X
			\$ 3,516.60	
		Less 25 %	\$ 879.15	
			\$ 2,637.45	
		<u>SPECIAL NETT ITEMS</u>		
15	1 pc	rear windscreen sealant <i>new</i>	\$ 80.00	40
16	1 pc	rear windscreen primer <i>new</i>	\$ 40.00	20
			\$ 120.00	
		<u>LABOUR & MISC. CHARGES</u>		
01		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 120.00	60
02		To check electrical lighting concerned.	\$ 100.00	20
03		To rust-proofing of the affected areas.	\$ 120.00	30
04		To reinstall of rear bumper parking sensor.	\$ 80.00	X
05		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,200.00	300
06		Putty and spray painting of the affected portion.	\$ 1,200.00	400
07		To dismantle and refit rear seat, backrest, trimming, garnish, roof-lining, speaker shelfboard, carpeting and other to enable body work repair.	\$ 150.00	X
08		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 120.00	60



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Lonpac Insured's Veh No : XD7622D
Date of Accident : 11 August 2020

Mr Ja'amat Bin Hj Ab Karim @ Mohammad Jamil Bin Hj Ab Ka

Date : 18 August 2020

Estimate To Repair SLN279Y - Toyota SIENTA 1.5G CVT ABS D/AIRBAG
Chassis No : MHFZ28H3900028253

S/No	Quantity	Description	Amount
09		<u>LABOUR & MISC. CHARGES</u> To remove and refit rear windscreen glass.	\$ 120.00 ✓
			\$ 3,210.00
		Total	\$ 5,967.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P - 1357.20
252
1017.90
P -
S.V - 60.00
L - 990.00
2067.90