

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 13-Aug-20

INSURANCE: Tokio

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHC2959K

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR TRUNK LID COVER <i>1st Dent</i>	1	\$1,126.60	\$1,126.60
REAR TRUNK LID LOCK <i>Dent</i>	1	\$457.90	\$457.90
REAR TRUNK LID COVER TRIM BOARD <i>broken</i>	1	\$216.50	\$216.50
Boot Lid Trimboard, Centre <i>NH</i>	1	\$159.60	\$ 159.60
Boot Lid Trimboard SIDE (LH) <i>NH</i>	1	\$92.50	\$ 92.50
Boot Lid Trimboard REAR <i>NH</i>	1	\$124.80	\$ 124.80
REAR TRUNK LID RUBBER <i>defunct</i>	1	\$365.20	\$365.20
REAR TRUNK LID GLASS (BLACK COLOR) <i>shatterd</i>	1	\$969.70	\$969.70
BOARD ASSY, BACK DOOR TRIM <i>NH</i>	1	\$354.40	\$354.40
REAR TRUNK LID LOGO (PRIUS) <i>NH</i>	1	\$60.80	\$60.80
REAR TRUNK LID LOGO (HYBRID) <i>NH</i>	1	\$52.40	\$52.40
REAR TRUNK LID LOGO (TOYOTA STAR) <i>NH</i>	1	\$52.90	\$52.90
THIRD BRAKE LIGHT <i>NH</i>	1	\$394.70	\$394.70
REAR TRUNK LID HINGE (LH) <i>NH</i>	1	\$189.50	\$189.50
REAR TRUNK LID ABSORBER (LH) <i>NH</i>	1	\$287.50	\$287.50
REAR TRUNK LID ABSORBER BRACKET (LH) <i>NH</i>	1	\$127.90	\$127.90
REAR TRUNK LID STOPPER (LH) <i>NH</i>	1	\$84.80	\$84.80
REAR BUMPER <i>form</i>	1	\$458.60	\$458.60
REAR BUMPER RE-INFORCEMENT <i>1st</i>	1	\$318.80	\$318.80
REAR BUMPER LOWER COVER <i>form</i>	1	\$552.60	\$552.60
REAR BUMPER SIDE RETAINER <i>svc</i>	1	\$112.70	\$112.70
REAR BUMPER TOWING COVER <i>cracked</i>	1	\$82.70	\$82.70
REAR BUMPER CLIPS <i>NH</i>	1	\$22.00	\$22.00
REAR BUMPER UPPER STOPPER (LH) <i>NH</i>	1	\$76.40	\$76.40
SEAL, REAR BUMPER SIDE, LH <i>mounty above</i>	1	\$148.40	\$148.40
REAR BUMPER UNDER SIDE COVER (LH) <i>NH</i>	1	\$232.00	\$232.00
ARM SUB-ASSY, REAR BUMPER, LH <i>NH</i>	1	\$139.60	\$139.60
TAIL LAMP ASSY (UPPER) <i>crack</i>	<i>42</i>	\$557.90	<i>1115.80</i>
TAIL LAMP ASSY (LOWER) <i>crack</i>	<i>42</i>	\$548.40	<i>1096.80</i>
TAIL LAMP QUARTER PANEL <i>form</i>	1	\$216.00	\$216.00
TAIL LAMP SIDE COVER <i>NH</i>	1	\$256.00	\$256.00
REAR TAIL LAMP GUIDE - WHITE <i>NH</i>	2	\$95.30	\$190.60
REAR END PANEL <i>Dent</i>	1	\$602.10	\$602.10
REAR END PANEL GARNISH <i>mounty defunct</i>	1	\$161.80	\$161.80
REAR WIRING ASSY <i>NH</i>	1	\$582.40	\$582.40
REAR SPARE TYRE PANEL <i>NH</i>	1	\$667.70	\$667.70
REAR FIBER TOOL BOX TRIM (LH) <i>NH</i>	1	\$598.00	\$598.00
REAR FIBER TOOL BOX CENTER <i>NH</i>	1	\$186.20	\$186.20
SPARE TYRE LOCK NUT <i>NH</i>	1	\$88.40	\$88.40
SPARE TYRE LOCK NUT BRACKET <i>NH</i>	1	\$113.50	\$113.50
SPARE TYRE SIDE PANEL (LH) <i>NH</i>	1	\$196.50	\$196.50

REAR FENDER, LH HH	1	\$836.70	\$836.70	X
REAR FENDER SHIELD (LH) HH	1	\$174.20	\$174.20	X
REAR FENDER AIR DUCT HH	1	\$165.10	\$165.10	X
REAR FLOOR PANEL SIDE (LH) HH	1	\$717.60	\$717.60	X
REAR FLOOR UNDER COVER (LH) HH	1	\$846.80	\$846.80	X
REAR CROSSMEMBER UNDER COVER HH	1	\$891.10	\$891.10	X
SUB TOTAL			\$15,858.50	
LESS 20% 25%			\$3,171.70	
DISCOUNTED TOTAL			\$12,686.80	
REVERSE CAMERA ASSY HH	1	\$380.00	\$380.00	X
REAR TRUNK LOWER W/S MOULDING HH	1	\$180.00	\$180.00	X
REAR LOWER W/S SEALANT HH	1	\$46.00	\$46.00	X
REAR WINDSCREEN MOULDING HH	1	\$160.00	\$160.00	X
REAR WINDSCREEN SEALANT New	1	\$46.00	\$46.00	✓
REAR BUMPER REVERSE SENSOR Demo	1	\$135.70	\$135.70	✓
SUB TOTAL			\$947.70	
Labour Charge				
Panel Beating	1	\$1,200.00	\$1,200.00 800/-	
Spray Painting Charge	1	\$1,000.00	\$1,000.00 700/-	
Wiring Charge	1	\$140.00	\$140.00 30/-	
Tuff Kote	1	\$140.00	\$140.00 40/-	
Towing Charge	1	\$80.00	\$80.00 40/-	
Remove/Refix Cushion & Upholstery Rear	1	\$150.00	\$150.00 80/-	
Remove/Refix Rear Windscreen Glass	1	\$120.00	\$120.00 80/-	
Remove/Refix Reverse Sensor	1	\$120.00	\$120.00 40/-	
Re-set Rear ABS System	1	\$400.00	\$400.00 40/-	
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00 40/-	
TOTAL LABOUR			\$3,900.00	
ESTIMATE TOTAL			\$17,534.50	

18,419.54

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

13/08/2020 @ 17:00 PM P/P 7847-90

Not Authory

15 days.

Yan

Part 1/2A-

Photo after repair with damaged parts.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: