

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

N/S	O/S

Veh No: G8B6896H Yr Regn: 12 09
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

On 10-12-2024 LTA #10825
B1 involved.

26/9/20 L/S \$8000 contribute with William (Road #8535.04, 52%)

Date/Time, File Pass to?

☐

: Preli. Report

1) 28/9 2024

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / L.B.I. (\$

MER-TP

8000

William Lee Car Air Con Engrg

No. 61 Ubi Ave 2, Ubi Auto Megamart, #08-04A, Singapore 408898

submit to insurance

To AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#08-16
Singapore 079120

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Authorized
16/8/20
2/5 = 80000
9 days

Vehicle No : GBB 6896H
Date of accident : 30/07/2020
Vehicle made / model : Nissan Cabstar 3.0

Estimate

<u>PARTS REPLACEMENT – NETT ITEMS</u>		Cost Price (\$\$)	
1pc	Front panel <i>Bodywork</i>	1580.90	1,583.60
1pc	Front panel emblem 'Cabstar' <i>ner</i>	36.10	71.20
1pc	Front wiper garnish <i>11</i>		494.60
1pc	Front grille <i>C12</i>	461.90	578.60
1pc	Front grille logo emblem <i>ner</i>		55.10
2pc	Headlamp L/R @ \$682.00 <i>C12</i>		1364.00
1pc	Headlamp apron garnish R/L @ \$75.40 <i>11</i>		150.80
1pc	Front bumper <i>215</i>	903.60	993.40
1pc	Front bumper reinforcement <i>Self</i>	481.00	702.60
1pc	Front mirror bracket LH <i>11</i>		191.10
1pc	Front mirror bracket cap cover LH <i>11</i>		22.90
1pc	Front mirror bracket garnish LH <i>11</i>		111.30
1pc	Front round mirror LH <i>11</i>		105.30
2pcs	Front wiper arm @ \$103.10 <i>11</i>		206.20
1pc	Front mirror bracket RH <i>11</i>		191.90
1pc	Front mirror bracket cap cover RH <i>11</i>		22.90
1pc	Front mirror bracket garnish RH <i>11</i>		111.30
1pc	Front mirror bracket inner cover RH <i>11</i>		22.90
1pc	Front windscreen lower moulding <i>ner</i>		24.70
2pcs	Front windscreen side moulding L/R @ \$67.20 <i>ner</i>		134.40
1pc	Front windscreen upper moulding <i>ner</i>		93.50
1pc	Tailgate lower member <i>Self</i>		645.50
2pcs	Tailgate stopper bracket @ \$105.00 <i>1/5 tm</i>		210.00
1pc	Rear number plate lamp <i>11</i>		71.30

William Lee Car Air Con Engrg

No. 61 Ubi Ave 2, Ubi Auto Megamart, #08-04A, Singapore 408898

<u>PARTS REPLACEMENT – NETT ITEMS</u> (CONT'D)		Cost Price (S\$)	
1pc	Rear number plate bracket	Sent	112.00 ✓
2pc	Taillamp panel R/L @ \$168.40	NN	336.80 X
2pc	Taillamp R/L @ \$219.80	mscne	439.60 1pc
1pc	Rear number plate lamp	Repair	71.30 X
4pcs	Tailgate rubber stopper L/R @ \$51.20	mscne	204.80 2pcs
			9,323.60
	Less 10%		(932.36)
	Sub total		8,391.24
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>			
2pc	Tailgate R/L @ \$1,200.00	mscne/sent	2,400.00 900
2pc	Tailgate lock R/L @ \$250.00	NN	500.00 X
2pc	Tailgate lock catch upper R/L @ \$75.00	NN	150.00 X
2pc	Tailgate lock catch lower R/L @ \$75.00	NN	150.00 X
1pc	Tailgate lower member stainless steel panel	sent	350.00 300
1set	Reverse sensor	one	250.00 200
1pc	Rear safety beam	sent	650.00 300
1pc	Front number plate	sent	50.00 40
1pc	Rear number plate	sent	50.00 40
1pc	Front panel sealant	NN	80.00 X
1pc	Front windscreen sealant	NN	120.00 40
1set	Front grille clip	NN	24.00 X
	Sub total		13,165.24 1820
<u>LABOUR & MISC. CHARGES</u>			
	To respray painting on affected area		1,500.00 1100
	To provide labour to repair & replace damaged parts		1,500.00 1200
	To apply anti-rust chemical on affected area		100.00 30
	To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focusing		50.00 30
	To remove, renew reverse sensor		80.00 50
	To remove, refix front windscreen glass		140.00 100
	Grand total		16,535.24
		P-568791 1001791 71319.90 S.N. 1820 2036 10% L-2.5m 2.5m 5687.91	