

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

DATE: 12/08/20

3P INSURANCE: NTUC

MODEL: HYUNDAI I 40

SURVEYOR: LKK

VEH NO.: SHD3229Y

MVA: OLIVIA

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Rear Bumper	1		\$1,106.00
	Rear Bumper Under Cover	1		\$228.00
	Rear Bumper Reflector Lamp(RH)	1		\$31.90
	Rear Bumper Reinforcement Bracket (RH)	1		\$80.30
	Rear Bumper Reinforcement	1		\$428.40
	Rear Bumper Clip (10 pcs)	10	\$2.20	\$22.00
	Rear Bumper Side Bracket (RH)	1		\$35.60
	Rear Bumper Sponge	1		\$119.50
SPARE PARTS SUB TOTAL			1128	\$2,051.70
LESS 20%				\$410.34
DISCOUNTED SPARE PARTS TOTAL			902.40	\$1,641.36
	Rear Bumper Rubber Mat	1		\$50.00
	Rear Bumper Reverse Sensor	1	50	\$135.70
NETT TOTAL				\$185.70
SPARE PARTS & NETT TOTAL				\$1,827.06
	Panel Beating		510	\$900.00
	Spray Painting			\$600.00
	Remove/Refix Reverse Sensor			\$120.00
LABOUR TOTAL			1462.40	\$1,620.00
ESTIMATE TOTAL			2151.150	\$3,447.06

Panel Beating

Spray Painting

Remove/Refix Reverse Sensor

Taufik 97495749 - WP

12/8/20 @ 2pm - 2 days

Lumpsum

Reasoning after repair

taufik@lkkmotor.com. Hanh.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.