

AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

FWD / AIG

M/S: LUM SHUET LYN JACQUELINE
80 CASUARINA ROAD
579468

Estimate No: MCS1900318
Date: 12 Aug 2020
Policy No: PNPV2019-00012872
Veh Reg No: SLB6284E
Make/Model: TOYOTA SIENTA 1.5

ATTN:

Your Ref No: SLB6284E
Claim Type: Third Party
Accident Date: 10/08/2020
TP Veh Reg No: SMA7915E

Not Authored
Return B4 paint
LKK - Kenneth
Kong

4 days 14/08/20
@ 10.05am

Estimate Repair Cost to Vehicle No: SLB6284E

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 TAILGATE	1 PC	1,131.90	✓
2 TAILGATE CENTRE LOGO	1 PC	72.20	✓
3 NUMBER PLATE LAMP GARNISH	1 PC	207.90	✓
4 REAR WINDSCREEN MOULDING 1 SET	2 PC	105.80	✓
5 REAR BUMPER CENTRE GARNISH	1 PC	190.00	✓
		1,707.80	
	Less 25%	426.95	1,280.85
Special Nett			
6 WINDSCREEN SEALANT	2 PC	30.00	✓
		30.00	30.00
LABOUR			
7 TO REMOVE & REFIT REAR WINDSCREEN	1 EA	120.00	✓
8 TO DISMANTLE AND INSTALL TAILGATE AND TRANSFER WIRING HARNESS, LAMP AND INNER LOCK	1 PC	90.00	601
9 TO DISMANTLE AND INSTALL DAMAGE PARTS, TO KNOCK, ALIGN AND REPAIR REAR AFFECTED AREA AND TO REFIT LISTED PARTS BACK SAME	1 PC	500.00	3501
10 TO SPRAY TAILGATE AND REAR BUMPER	1 PC	500.00	4001
		1,210.00	1,210.00
Total			SS 2,520.85
Add GST @ 7%			176.46
Total Amount Payable			SS 2,697.31

TOTAL: SINGAPORE DOLLAR TWO THOUSAND SIX HUNDRED NINETY SEVEN AND CENTS THIRTY ONE ONLY

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE