

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 45346

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0566/2020/NS
Date : 13-Aug-20

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Veh No : GBB 1216 D

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street
#19-00 The Octagon
Singapore 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name : Mr Sim Khia Liang, Melvin(Shen Jialiang , Melvin)
Address : 7 Sembawang Crescent
#14-14
Singapore 757096
Telephone : HP +65 93398595
Type of Claim : Third Party Claim
Policy No. : 10933949
Vehicle No : **SMM 3355 J**
Model Code : Audi A3 Sportsback 1.0 TF
Model / Year : Sep-18
Engine No : CHZ C22329
Chassis No : WAUZZZ8V9JA153812
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 12-Aug-20
Place of Accident : Slip Road Of Sle Towards BKE Exit 9

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMM 3355 J

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00 /	
2	To dismantle and renew rear bumper. To inspect rear end panelling. Re-organise crash management components. Reinstall all parts removed.	\$ 1,050.00 700	
3	To respray rear bumper and rear lid.	\$ 2,000.00 1400	
4	To carry out diagnostic check.	S/N \$ 192.00 /	
TOTAL LABOUR CHARGES		: \$ 3,522.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMM 3355 J

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER <i>de</i> ✓	\$	1,847.00
2	REAR BUMPER FIXING PARTS ?	\$	191.00
3	REAR BUMPER LOCKING MECHANISM - LH / RH ?	2 \$	28.00
4	REAR BUMPER SPOILER ?	\$	234.00
5	REAR LIGHT REFLECTOR - LH / RH X	2 \$	60.00
6	REAR PARKING AID SENSOR - INNER / OUTER ?	2	TBC
7	REAR PARKING AID SEAL RING <i>re</i> ✓	4 \$	14.00
8	REAR BUMPER WIRING SET ?	\$	510.00
9	REAR BUMPER SIDE REINFORCEMENT BEAM ?	\$	565.00
10	REAR BUMPER BRACKET - LH ?	\$	27.00
11	REAR BUMPER BRACKET - RH ?	\$	28.00
12	PACKING ADHESIVE <i>re</i> ✓	\$	18.00
13	AUDI EMBLEM <i>re</i> ✓	\$	122.00
14	A3 INSCRIPTION <i>re</i> ✓	\$	95.00
15	TFSI INSCRIPTION <i>re</i> ✓	\$	95.00
16	SUNDRIES ?	\$	200.00
TOTAL SPARE PARTS CHARGES		: \$	4,034.00
TOTAL LABOUR CHARGES		: \$	3,522.00
GRAND TOTAL		: \$	7,556.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Rasul - Hp 90010068
: 14/08/2020 @ 1145
: 5 days
: Resy before paint

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant