

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20008391/R1SF3Q2

**Date:** 04/11/2020

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00018152000
<b>Claimant Vehicle No :</b>	SMM3355J	<b>Insured Vehicle No :</b>	GBB1216D
Date of Loss:	12/08/2020	Nature of Claim:	TP
		Claim No:	SNM20D202843/C02/LEWLC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMM3355J</b>		
Make & Model:	AUDI A3 SPORTBACK, 999cc TFSI S TRONIC (LED) (A)	Engine No:	CHZC22329
Reg. Date:	21/09/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8V9JA153812
Colour:	Yellow	Odometer:	39938 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,034.00	2,175.40	1,858.60	46.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,522.00	2,572.00	950.00	26.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,556.00</b>	<b>4,747.40</b>	<b>2,808.60</b>	<b>37.17</b>
<b>+ GST 7.00/7.00% (S\$)</b>	528.92	332.32	196.60	37.17
<b>Nett Amount (S\$)</b>	<b>8,084.92</b>	<b>5,079.72</b>	<b>3,005.20</b>	<b>37.17</b>

### INSPECTION

Date of Assignment:	13/08/2020	
Date Inspected:	14/08/2020 Inspected At:	281 ALEXANDRA RD Repairer: Premium Automobiles Pte Ltd (UBI)
Estimated Period of Repair:	5.0 days	

**Adjuster:** MOHD RASUL

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 04 Nov 2020)
<b>Parts:</b>	144	AUDI A3 SPORTBACK 999cc TFSI S TRONIC (LED) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMM3355J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Deformed	1,847.00 FS	*1,847.00 FS
2	1	*REAR BUMPER FIXING PARTS	Not Necessary	191.00 FS	*- FS
3	2	*REAR BUMPER LOCKING MECHANISM-LH/RH	Not Necessary	28.00 FS	*- FS
4	1	*REAR BUMPER SPOILER	Not Necessary	234.00 FS	*- FS
5	2	*REAR LIGHT REFLECTOR-LH/RH	Not Necessary	60.00 FS	*- FS
6	2	*REAR PARKING AID SENSOR-INNER/OUTER (NPA)	Not Necessary	0.00 FS	*- FS
7	4	*REAR PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
8	1	*REAR BUMPER WIRING SET	Not Necessary	510.00 FS	*- FS
9	1	*REAR BUMPER SIDE REINFORCEMENT BEAM	Not Necessary	565.00 FS	*- FS
10	1	*REAR BUMPER BRACKET-LH	Not Necessary	27.00 FS	*- FS
11	1	*REAR BUMPER BRACKET-RH	Not Necessary	28.00 FS	*- FS
12	1	*PACKING ADHESIVE	Necessary	18.00 FS	*18.00 FS
13	1	*AUDI EMBLEM	Necessary	122.00 FS	*122.00 FS
14	1	*A3 INSCRIPTION	Necessary	95.00 FS	*94.20 FS
15	1	*TFSI INSCRIPTION	Necessary	95.00 FS	*94.20 FS
16	1	*SUNDRIES	Not Necessary	200.00 FS	*- FS
<b>Total Parts (\$\$)</b>				<b>4,034.00</b>	<b>2,175.40</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER.TO INSPECT REAR END PANELLING.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,050.00	700.00
3	TO RESPRAY REAR BUMPER AND REAR LID	New	2,000.00	1,400.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,522.00</b>	<b>2,572.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**