

Our Ref : TP/082020/4472
Accident date : 11/8/2020
Your Ref : SMR3913Y

Invoice No.:

Date : 12/8/2020

MOTOR CLAIM DEPARTMENT
AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building
78 Shenton Way #07-16
Singapore 079120

ESTIMATE COST OF REPAIRS TO

Vehicle No. : GOH EE MEI
Model : TOYOTA SIENTA ELEGANCE (AUTO)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

1	pc	Rear LH taillamp	✓ CAA	\$	347.00	✓
1	pc	Rear LH taillamp lower bracket	✓ 20	\$	92.33	✓
1	pc	Rear bumper	✓ 20	\$	278.00	✓
1	pc	Rear bumper LH pad	✓ Cat	\$	122.80	✓
1	pc	Rear bumper centre pad	✓ 20	\$	180.70	✓
1	pc	Rear bumper LH reflector	X NW	\$	56.90	X
1	pc	Rear bumper LH retainer	✓ M.S.	\$	89.90	✓
1	pc	Rear LH fender mud flap	X NW	\$	73.90	X
				\$	1,241.53	1110.73
Less 25%				\$	(310.38)	
				\$	931.15	833.05

1	set	Rear bumper sensor	✓ NW	\$	280.00	N 250.
To repair rear damages				\$	480.00	350
To spray painting				\$	580.00	480
				\$	2,271.15	830

VIN'S MOTOR PTE LTD

part by part.
before paint photos.
Gina Qian - 8288082
13/8/2020
4 days.

1913.05