

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Cecilia Low

Date: 20 Aug 2020

Preliminary Advice

| | | | |
|--------------------|---|-------------------------|--------------|
| Insured Vehicle No | : GBG6806S | Accident Date | : 12/08/2020 |
| TP Vehicle No | : S3760CD | Assignment Date | : 13/08/2020 |
| Make | : HONDA ODYSSEY | Est. Duration of Repair | : 5 |
| Date of Inspection | : 14/08/2020 | | |
| Inspection At | : SPARK CAR CARE @ BRADDELL (HQ) 205 BRADDELL RD SINGAPORE 579701 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front rear portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 20,550.76 |
| Revised Amount | :S\$ | 6,746.28 |
| Check Items (Estimated) | :S\$ | 380.00 |
| Total | :S\$ | 7,126.28 |

| | |
|-----------------|------|
| Lump Sum Repair | :S\$ |
|-----------------|------|

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Survey on WP