

**Spark Car Care**  
**ComfortDelgro Engineering Pte Ltd**  
 205 Braddell Road S (579701)  
 Tel: 63837168 / 63837466 Fax:62815767

Finalization Form

**Bill To** : CHINA TAIPING      **Vehicle Number** : S3760CD  
**Attn to** : GUO XIANG      **Type Of Claim** : TP

<b>A. Spare parts</b> \$ <u>4,144.80</u>  <b>B. Supplementary</b> \$ <u>25.80</u>  <b>C. Nett Price</b> \$ <u>-</u>  <b>D. Supp Nett Price</b> \$ <u>-</u>  <b>E. S/Nett</b> \$ <u>893.00</u>	<b>F. Total Parts</b> \$ <u>4,229.48</u> 4184.48  <b>G. Total Labour</b> \$ <u>2,370.00</u> ✓  <b>H. Total Repair</b> \$ <u>6,599.48</u> 6554.48  <b>I. Excess</b> _____ <b>P/P Total</b> <u>6,599.48</u>
---	--

Total Spare Parts Price	\$ 4,170.60
Cost plus / List Down      20%	834.12
Total	3,336.48

Total Nett Price	\$ -
Nett Price Less      _____	\$ -
Total	-

Lump Sum Less      \_\_\_\_\_      \$ -

Lump Sum Rounding      \_\_\_\_\_

**Total Finalized**      \$ 6,599.48

*N.B. If we DO NOT receive your reply within 2 weeks, we shall treat the above finalized amount as confirmed & correct.*

Remarks : Please confirm and revert by Fax or Email

Date In : _____	Total Repair Day : _____
Date Survey : _____	LOU/ Day : _____
Date Out : _____	Total LOU : _____
Sat/Sun/Ph. : _____	Rental/Day : _____
Authorized Repair Day <u>5+2 =7</u>	Total Rental : _____

Submitted By / Date :  
 WILLIAM WANG  
31.08.2020

Confirmed By / Date :  
 \_\_\_\_\_

# Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

## Spare Parts

Vehicle No : **S3760CD** Case Owner : **0**

Make & Model : **HONDA ODYSSEY 2.4 EXV** Year Manufacture : **2015**

Chassis No : **JHMRC1890FC203253** Engine No : **K24W71011642**

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : **TP**

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear number plate with casing	1				\$ 45.00	×
2	Rear bumper	1		\$ 598.30	✓		
3	Rear bumper spoiler LH	1					
4	Rear bumper spoiler RH	1					
5	Rear bumper reflector LH	1					
6	Rear bumper reflector RH	1					
7	Rear bumper retainer LH	1					
8	Rear bumper retainer RH	1					
9	Rear bumper clips	10		\$ 39.00	✓		
10	Reverse sensor set	1					
11	Smart buzzer assy	1					
12	Rear antenna assy	1					
13	Rear end panel	1					
14	Rear end panel inner garnish	1					
15	Taillamp LH	1					
16	Taillamp RH	1					
17	Tailgate	1		\$ 1,193.70	✓		
18	Tailgate outer garnish	1		\$ 246.70	✓		
19	Tailgate outer chrome moulding	1		\$ 190.60	✓		
20	Tailgate lamp assy LH	1					
21	Tailgate lamp assy RH	1		\$ 378.60	✓		
22	Tailgate lock assy	1					
23	Tailgate opener switch assy	1					
24	Tailgate weatherstrip	1		\$ 120.90	✓		
25	Tailgate inner lower garnish	1					
26	Tailgate inner upper garnish	1					
27	Tailgate inner side garnish LH	1					
28	Tailgate inner side garnish RH	1					
29	Rear windscreen glass	1		\$ 1,153.90	✓		
30	Rear windscreen glass side moulding	2		\$ 62.60	✓		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

# Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

## Spare Parts

Vehicle No : S3760CD Case Owner : 0

Make & Model : HONDA ODYSSEY 2.4 EXV Year Manufacture : 2015

Chassis No : JHMRC1890FC203253 Engine No : K24W71011642

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
31	Rear windscreen glass upper dam	1		\$ 31.20	✓		
32	Rear windscreen glass lower dam	1		\$ 31.20	✓		
33	Rear windscreen glass dam rubber A	1					
34	Rear windscreen glass pivot cap	1					
35	Rear windscreen sealant	1				\$ 40.00	✓
36	Rear windscreen solar film	1				\$ 280.00	✓
37	Rear wiper arm assy	1		\$ 50.10	✓		
38	Rear wiper blade	1		\$ 48.00	✓		
39	Rear wiper motor assy	1					
40	BlackVue camera set	1				\$ 528.00	✓
41	0	0					
42	0	0					
43	0	0					
44	0	0					
45	0	0					
46	0	0					
47	0	0					
48	0	0					
49	0	0					
50	0	0					
51	0	0					
52	0	0					
53	0	0					
54	0	0					
55	0	0					
56	0	0					
57	0	0					
58	0	0					
59	0	0					
60	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

# Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

## Supplementary 1

Vehicle No : S3760CD Case Owner : 0

Make & Model : HONDA ODYSSEY 2.4 EXV-5 Year Manufacture : 2015

Chassis No : JHMRC1890FC203253 Engine No : K24W71011642

Sales Order : 0 Supplier : 0

Order By : \_\_\_\_\_ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Item	S/N	Disposition By Surveyor
1	Tailgate badge logo ✓ NEC	1		\$ 25.80			
2		1					
3		1					
4		1					
5		1					
6		1					
7		1					
8		1					
9		1					
10		1					
11		1					
12		1					
13		1					
14		1					
15		1					
16		1					
17		1					
18		1					
19		1					
20		1					
21		1					
22		1					
23		1					
24		1					
25		1					
26		1					
27		1					
28		1					
29		1					
30		1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

# Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

## Labour

Vehicle No. : **S3760CD** Case Owner : **0**  
 Make & Model : **ONDA ODYSSEY 2.4 EXV-S** Year of Manufacture : **2015**

S/No	Labour Description	Estimated Price	Adjusted Price	
1	To remove/refit boot compartment trims and garnish to facilitate repairs.	\$280.00	\$ 180.00	✓
2	To remove/replace rear windscreen to facilitate repairs.	\$120.00	\$ 120.00	✓
3	To transfer tailgate parts and fittings to new tailgate.	\$180.00	\$ 80.00	✓
4	Labour charges to repair and panel beat the LH rear fender, RH rear fender, rear floor panel, cutting/welding and replacing damaged parts.	\$1,440.00	\$ 720.00	✓
5	To check wiring functions.	\$40.00	\$ 20.00	✓
6	To remove/replace reverse sensor set.	\$120.00	\$ 80.00	✓
7	To putty, apply primer & spray-paint the rear bumper, tailgate, LH rear fender, RH rear fender, rear end panel, rear floor panel and affected areas.	\$1,500.00	\$ 1,000.00	✓
8	To apply rust-proofing on repaired/replaced panels.	\$150.00	\$ 50.00	✓
	Supplementary			
1	To remove/replace BlackVue camera set.	\$120.00	\$ 120.00	✓

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.